

Index of Photographs

- Photograph D.1.1: Site entrance security gate
- Photograph D.1.2: CCTV camera positions on Main Process Building
- Photograph D.1.3: Site roads and Windsock
- Photograph D.1.4: Interior of Main Process Building
- Photograph D.1.5: Extension to Main Process Building – exterior (Fines Processing Plant)
- Photograph D.1.6: New fines processing line – interior (Main Process building extension)
- Photograph D.1.7: Rotating Drying Unit (Drying Plant building)
- Photograph D.1.8: Weighbridge position and operator's window
- Photograph D.1.9: Screenshot of weighbridge software - sample load weigh-in
- Photograph D.1.10: Garage/vehicle workshop plant and equipment
- Photograph D.1.11: Vehicle wash bay
- Photograph D.1.12: Storage bay
- Photograph D.1.13: Designated parking area
- Photograph D.1.14: Spill pallet in garage building
- Photograph D.1.15: Site offices located at western side of Main Process Building
- Photograph D.2.1: Input material inspection and storage bay
- Photograph D.2.2: Glass loading into Main Process
- Photograph D.2.3: Clean/separated glass cullet output
- Photograph D.2.4: Residual waste storage
- Photograph D.2.5: Can crushing and baling
- Photograph D.2.6: Bulk glass cullet storage
- Photograph D.2.7: Baled cans/metal storage
- Photograph D.2.8: Hopper and picking station at Drying Plant
- Photograph D.2.9: Crushed and graded product from the Drying Plant
- Photograph D.2.10: Output from the Drying Plant for diversion to Main Process
- Photograph D.2.11: Residual waste from the Drying Plant
- Photograph F.1.1: Water gun #1 positioned at Main Process building - extension
- Photograph F.1.2: Water gun #2 positioned at Main Process building
- Photograph F.1.3: Misting system at Drying Plant (1)
- Photograph F.1.4: Misting system at Drying Plant (2)
- Photograph F.1.5: Misting system at Drying Plant (3)
- Photograph F.1.6: Misting system at Drying Plant (4) – spray nozzles
- Photograph F.1.7: Industrial vacuum system in Drying Plant (1)
- Photograph F.1.8: Industrial vacuum system spot cleaning hose in Drying Plant (2)
- Photograph F.1.9: Sealed/contained chutes/silos to storage bags in Drying Plant (2)
- Photograph F.1.10: Product from Drying Plant – bagged and sealed
- Photograph H.3.1: Eddy Current Separator Unit
- Photograph H.3.2: Spectrum Unit showing glass input conveyor
- Photograph H.3.3: Glass cullet quality control (QC) laboratory (1)
- Photograph H.3.4: Glass cullet quality control (QC) laboratory (2)

Photograph D.1.1: Site entrance security gate



Photograph D.1.2: CCTV camera positions on Main Process Building



Photograph D.1.3: Site roads and Windsock



Photograph D.1.4: Interior of Main Process Building



Photograph D.1.5: Extension to Main Process Building – exterior (Fines Processing Plant)



Photograph D.1.6: New fines processing line – interior (Main Process building extension)



Photograph D.1.7: Rotating Drying Unit (Drying Plant building)



Photograph D.1.8: Weighbridge position and operator's window



Photograph D.1.9: Screenshot of weighbridge software - sample load weigh-in

Record Load In

Load Details - General

Glassco Ticket No: 028109 Supplier Ticket No:

Supplier: Rehab Glassco Depot: Demand Glassco Logistics

Haulier Name: P Logistics Limited Vehicle Type:

Vehicle: 88888888 Multiple Materials: No

Material Details

New Material: Sorted Glass EWC Code: 15 01 07

Weight (Kg)	Date	Time	Audit No
Weight I: 37700	<input type="checkbox"/> 17-05-2011	11:22:26	056009
Weight II: 19160	<input type="checkbox"/> 17-05-2011	11:37:59	056011
Net Weight: 18540			

Rejected: No Contaminated: No Upload Images: No Load Images

Comments:

Billing Details

Billed: Billed Date: 27/05/2011 Reference No:

Reprint Save Delete Open Load Close

Photograph D.1.10: Garage/vehicle workshop plant and equipment



Photograph D.1.11: Vehicle wash bay



Photograph D.1.12: Storage bay



Photograph D.1.13: Designated parking area



Photograph D.1.14: Spill pallet in garage building



Photograph D.1.15: Site offices located at western side of Main Process Building



Photograph D.2.1: Input material inspection and storage bay



Photograph D.2.2: Glass loading into Main Process



Photograph D.2.3: Clean/separated glass cullet output



Photograph D.2.4: Residual waste storage



Photograph D.2.5: Can crushing and baling



Photograph D.2.6: Bulk glass cullet storage



Photograph D.2.7: Baled cans/metal storage



Photograph D.2.8: Hopper and picking station at Drying Plant



Photograph D.2.9: Crushed and graded product from the Drying Plant



Photograph D.2.10: Output from the Drying Plant for diversion to Main Process




Photograph D.2.11: Residual waste from the Drying Plant



Photograph F.1.1: Water gun #1 positioned at Main Process building - extension



Photograph F.1.2: Water gun #2 positioned at Main Process building



Photograph F.1.3: Misting system at Drying Plant (1)



Photograph F.1.4: Misting system at Drying Plant (2)



Photograph F.1.5: Misting system at Drying Plant (3)



Photograph F.1.6: Misting system at Drying Plant (4) – spray nozzles



Photograph F.1.7: Industrial vacuum system in Drying Plant (1)



Photograph F.1.8: Industrial vacuum system spot cleaning hose in Drying Plant (2)



Photograph F.1.9: Sealed/contained chutes/silos to storage bags in Drying Plant (2)



Photograph F.1.10: Product from Drying Plant – bagged and sealed



Photograph H.3.1: Eddy Current Separator Unit



Photograph H.3.2: Spectrum Unit showing glass input conveyor



Photograph H.3.3: Glass cullet quality control (QC) laboratory (1)



Photograph H.3.4: Glass cullet quality control (QC) laboratory (2)

