



Project-information

Project name:
Panda Yard Tanks

Contract number:
001

Contact:
Terry Radcliffe

Date:
29.01.2015

Client **Panda Waste Services**
 Contact:
 Position:
 Road **Navan,**
 Town **Beauparc Business Park,**
 County **Co. Meath.**
 Telephone:
 Fax:
 Mobile:
 E-Mail:

Site **Panda Waste**
 Contact:
 Position:
 Road **Navan,**
 Town **Beauparc Business Park,**
 County **Co. Meath.**
 Telephone:
 Fax:
 Mobile:
 E-Mail:

Consent of copyright owner required for any other use.

Contractor **Panda Waste**
 Contact: **Terry Radcliffe**
 Position:
 Road **Navan,**
 Town **Beauparc Business Park,**
 County **Co. Meath.**
 Telephone: **01 8298944**
 Fax: **046 9024189**
 Mobile:
 E-Mail: **tcurran@panda.ie**



Defect Grade Description

Project name:
Panda Yard Tanks

Contract number:
001

Contact:
Terry Radcliffe

Date:
29.01.2015

1:

Occurrences without damage: for example, laterals, joints etc.

NO DEFECTS WERE DETECTED.

2:

Constructional deficiencies or occurrences with insignificant influence to tightness, hydraulic or static pressure of pipe: f.e. wide joints, badly torched intakes, minor deformation of plastic pipes, minor erosions etc.

REHABILITATION CAN BE SCHEDULED LONG-TERM.

3:

Constructional deficiencies diminishing static, hydraulic and tightness: f.e. open joints, untorched intakes, cracks, minor drainage obstructions such as calcide build ups, protruding laterals, minor damages to pipe wall, individual root penetrations, corroded pipe walls etc.

REHABILITATION IS NECESSARY MEDIUM-TERM WITHIN 3 TO 5 YEARS.

4:

Constructional damages with nonsufficient static safety, hydraulic or tightness: f.e. axial/radial pipebursts, pipe deformations, visually noticeable infiltration/exfiltration, cavities in pipe-wall, severe protruding, laterals severe root penetrations, severe corrosion of pipe wall etc.

REHABILITATION PROCEDURE IS URGENT AND HAS TO BE COMPLETED WITHIN 1 TO 2 YEARS. NECESSITY FOR EMERGENCY OPERATIONS HAS TO BE EXAMINED.

5:

Pipe is already or will shortly be impermeable: f.e. collapsed pipe, deeply rooted pipe or other drainage obstructions. Pipe loses water or danger of backwater in basements etc.

REHABILITATION IS URGENT AND SHORT-TERM. IN ORDER TO PREVENT FURTHER DAMAGE, NECESSARY TEMPORARY SPOT REPAIR HAS TO BE CONDUCTED ON EMERGENCY LEVEL.



Panda Waste
 Beauparc Business Park,
 Co. Meath.
 Tel: 01 8298944, Fax: 046 9024189

Inspection report


Date: 29.01.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 1	PLR:
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: Surface T1
Place: Beauparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use:	Material: Concrete Pipe length:
Catchment: Surface water	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
	0.00	ST	Start of Survey	00:00:00		0
	0.00	FH	Finish Survey	00:01:28		0



For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report


Date: 29.01.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 2	PLR:
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: Surface T2
Place: Beuparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use:	Material: Concrete Pipe length:
Catchment: Surface water	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
	0.00	ST	Start of Survey	00:00:00		0
	0.00	FH	Finish Survey	00:03:27		0



For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report

Date: 29.01.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 3	PLR: Tank 3
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: Surface T3
Place: Beuparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use: Foul	Material: Concrete Pipe length:
Catchment:	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
		ST	Start of Survey	00:00:00		0
		FH	Finish Survey	00:01:02		0

For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report

Date: 29.01.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 4	PLR: Tank 4
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: Truck Wash
Place: Beuparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use: Foul	Material: Concrete Pipe length:
Catchment:	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
	0.00	ST	Start of Survey	00:00:00		0
	0.00	FH	Finish Survey	00:01:20		0

For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report

Date: 29.01.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 5	PLR: Tank 5
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: T5 Sweeper
Place: Beauparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use: Foul	Material: Concrete Pipe length:
Catchment:	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
		0.00	ST Start of Survey	00:00:00		0
		0.00	FH Finish Survey	00:02:24		0

For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report

Date: 29.01.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 6	PLR: Tank 6
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: T6 Leachate
Place: Beuparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use: Foul	Material: Concrete Pipe length:
Catchment:	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
		0.00	ST Start of Survey	00:00:00		0
		0.00	FH Finish Survey	00:02:10		0

For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report

Date: 19.02.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 7	PLR: Tank 8
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: Leachate 2
Place: Beauparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use: Foul	Material: Concrete Pipe length:
Catchment:	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
	0.00	ST	Start of Survey	00:00:00		0
	0.00	FH	Finish Survey	00:01:11		0

For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report

Date: 19.02.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 8	PLR: Tank 7
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: Shed 2
Place: Beuparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use: Foul	Material: Concrete Pipe length:
Catchment:	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
	0.00	ST	Start of Survey	00:00:00		0
	0.00	FH	Finish Survey	00:05:18		0

For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report

Date: 19.02.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 9	PLR: Tank 9
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: Shed 3
Place: Beuparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use: Foul	Material: Concrete Pipe length:
Catchment:	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
	0.00	ST	Start of Survey	00:00:00		0
	0.00	FH	Finish Survey	00:01:14		0

For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection report

Date: 19.02.2015	Job N°: 001	Weather: Dry	Operator: John	section number: 10	PLR: No 10 Biocycle
Video Volume No.:	Vehicle: Van 1	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:

Road: Panda Yard	Map No.1:	start MH: No 10 Biocyc
Place: Beuparc Business Park,	Map No.2:	end MH:
Location: Main road - urban	Tape No.:	Total length: 0 m

Purpose: Assess condition	Size/Shape:
Section use: Foul	Material: Concrete Pipe length:
Catchment:	Lining: Concrete

Comment:

1:25	position	code	observation	counter	photo	grade
		ST	Start of Survey	00:00:00		0
		FH	Finish Survey	00:03:52		0

For inspection purposes only.
 Consent of copyright owner required for any other use.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

This document was created with Win2PDF available at <http://www.win2pdf.com>.
The unregistered version of Win2PDF is for evaluation or non-commercial use only.
This page will not be added after purchasing Win2PDF.

For information purposes only.
Consent of copyright holder required for any other use.