




# TIER 2/3 ENVIRONMENTAL RISK ASSESSMENT

LIMERICK CITY COUNCIL SITE  
ST. MARY'S PARK  
LIMERICK

## APPENDIX 5

### PHOTOS

For inspection purposes only.  
Consent of copyright owner required for any other use.



VERDE REF	20476
-----------	-------





Photo 1 - Access road between rear of houses and the landfill



Photo 2 - Type of waste visible on surface of the landfill



Photo 3 - Manure and other mixed wastes becoming overgrown on the landfill



Photo 4- Trial pit excavations showing buried mixed waste beneath