

Appendix 2

Photographs of the Site

For inspection purposes only.
Consent of copyright owner required for any other use.



PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:
Longford Co. Co.

Site Location: Ballymulvey Landfill

Project Number: P1444

Photo No. 1
Date: 26-06-18

Description:
Main site entrance gates
from L1121 road.



Photo No. 2
Date: 26-06-18

Description:
View from the top of Bund
No.1 over to Bund No. 2.



PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:
Longford Co. Co.

Site Location: Ballymulvey Landfill

Project Number: P1444

Photo No.
3

Date:
26-06-18

Description:

Old groundwater monitoring borehole BH2 flush with ground and no well head or concrete plinth.



Photo No.
4

Date:
26-06-18

Description:

View showing lagoon to the south of the landfill with overgrown vegetation.



PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:

Longford Co. Co.

Site Location: Ballymulvey Landfill

Project Number: P1444

Photo No.

5

Date:

26-06-18

Description:

View showing evidence of perimeter drainage installed along the cap



Photo No.

6

Date:

26-06-18

Description:

View showing leachate monitoring well BH6 installed within Bund No. 1.



PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:

Longford Co. Co.

Site Location: Ballymulvey Landfill

Project Number: P1444

Photo No.

7

Date:

26-06-18

Description:

View showing one of
the gas vents.



Photo No.

8

Date:

26-06-18

Description:

View showing perimeter
cut-off drain along
western side of Bund No.
2.



PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:

Longford Co. Co.

Site Location: Ballymulvey Landfill

Project Number: P1444

Photo No.

9

Date:

26-06-18

Description:

View showing slope down from Bund No. 2 towards lagoon.



Photo No.

10

Date:

26-06-18

Description:

View showing location of surface water monitoring point SW-C to the south-west of the site. Woodland in background divides landfill from agricultural fields.



PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:
Longford Co. Co.

Site Location: Ballymulvey Landfill

Project Number: P1444

Photo No.
11

Date:
26-06-18

Description:
View showing old
groundwater monitoring
borehole BH1 near the
L1121 roadway.



Photo No.
12

Date:
26-06-18

Description:
View showing location of
surface water monitoring
point SW-G, the tributary
stream of the River Inny.

