




**FEHILY  
TIMONEY**

**CONSULTANTS IN ENGINEERING,  
ENVIRONMENTAL SCIENCE & PLANNING**

# **APPENDIX 5**

**Site Walkover Checklist and  
Photographic Log**

*For inspection purposes only.  
Consent of copyright owner required for any other use.*



### Walkover Survey Checklist

#### Historic Kerry Landfills - Ardferf

Walkover Survey Checklist		
Information	Checked	Comment (include distances from Site Boundary)
1. What is the current land use?	✓	Unused grassland
2. What are the neighbouring land uses?	✓	Cathedral (directly south), agricultural field (directly north, east and west – beyond a roadway), residential dwellings
3. What is the size of the site?	✓	Circa 1.01 ha
4. What is the topography?	✓	Slightly sloped (uphill is a north – south direction)
5. Are there potential receptors (if yes, give details)?	✓	Nearby residences, groundwater, surface water (River Tyshe)
<b>Houses</b>		
Surface water features (if yes, distance and direction of flow)?	✓	Yes, River Tyshe located less than 50m north of site boundary
Any wetland or protected areas?	✓	No
Public water supplies?	✓	Not identified
Private wells?	✓	Possible local usage
Services?		None
Other buildings?	✓	None with site boundary – cathedral directly south of site boundary and residential dwelling located approx. 25m north-west of site
Other?		No
6. Are there any potential sources of contamination (if yes, give details)?	✓	Buried waste
Surface waste (if yes, what type)?	✓	None noted
Surface ponding of leachate	✓	None present
Leachate seepage	✓	None noted
Landfill gas odours	✓	None noted
7. Are there any outfalls to surface water? (If yes, are there discharges and what is the nature of the discharge?)	✓	No evidence
8. Are there any signs of impact on the environment? (if yes, take photographic evidence)	✓	None noted.
Vegetation die off, bare ground	✓	None noted
Leachate seepages	✓	None noted
Odours	✓	None Noted
Litter	✓	None
Gas bubbling through water	✓	None noted

**Walkover Survey Checklist**

**Historic Kerry Landfills - Ardfert**

Signs of settlement	✓	No
Subsidence, water logged areas	✓	No evidence

Walkover Survey Checklist		
Information	Checked	Comment (include distances from Site Boundary)
Drainage or hydraulic issues	✓	None noted
Downstream water quality appears poorer than upstream water quality	✓	No
9. Are there any indications of remedial measures? (Provide details)	✓	No
Capping	✓	No evidence of waste
Landfill gas collection	✓	No
Leachate collection	✓	No
10. Describe fences and security features (if any)	✓	Ditches surrounding north, east and western boundaries, stone wall along southern boundary
Any other relevant information?		

For inspection purposes only.  
Consent of copyright owner required for any other use.

# Appendix

## Site Walkover Photographs

*For inspection purposes only.  
Consent of copyright owner required for any other use.*



# PHOTOGRAPHIC LOG



**Client Name:** Kerry County Council

**Site Location:** Ardfert

**Project Number:** P1766

**Photo No.**

**Date:**

23/10/19

**Description:**

Residential entrance west of site, BH01 located just outside



**Photo No.**

**Date:**

23/10/19

**Description:**

BH01





# PHOTOGRAPHIC LOG



**Client Name:** Kerry County Council

**Site Location:** Ardfert

**Project Number:** P1766

**Photo No.**

**Date:**

23/10/19

**Description:**

BH02 within field just north of old cathedral



**Photo No.**

**Date:**

23/10/19

**Description:**

Looking north from BH02 to river flowing in an east to west direction where surface water samples were collected.

