




CONSULTANTS IN ENGINEERING,
ENVIRONMENTAL SCIENCE & PLANNING

APPENDIX 2

Site Walkover Assessment and Photo Logs

For inspection purposes only.
Consent of copyright owner required for any other use.



Appendix

Site Walkover Photographs

For inspection purposes only.
Consent of copyright owner required for any other use.



PHOTOGRAPHIC LOG



Client Name: Kerry
County Council

Site Location: Dingle

Project Number: P1788

Photo No.

Date:

1

23/10/19

Description:

River flowing along
the south-western
boundary of site,
where surface water
samples were
collected



Photo No.

Date:

2

23/10/19

Description:

BH02 within agricultural
field



PHOTOGRAPHIC LOG



Client Name: Kerry
County Council

Site Location: Dingle

Project Number: P1788

Photo No.

Date:
23/10/19

3

Description:

Looking at old landfill
from BH01 (facing
south-west)



Photo No.

Date:
23/10/19

4

Description:

BH01 location, just in
front of a farm lane
(facing north-east)



Walkover Survey Checklist

Historic Kerry Landfills - Dingle

Walkover Survey Checklist		
Information	Checked	Comment (include distances from Site Boundary)
1. What is the current land use?	✓	Agricultural land
2. What are the neighbouring land uses?	✓	Agricultural land (south, east and west of the site), residential dwelling (50m north of site), roadway (running along north-eastern boundary)
3. What is the size of the site?	✓	Circa 2.35 ha
4. What is the topography?	✓	Site is dome shaped
5. Are there potential receptors (if yes, give details)?	✓	Nearby residences, groundwater, surface water (Kilfountain River)
Houses		
Surface water features (if yes, distance and direction of flow)?	✓	Yes, Kilfountain River running along the south-western boundary flowing in a north-west south-eastern direction
Any wetland or protected areas?	✓	No
Public water supplies?	✓	Not identified
Private wells?	✓	Possible local usage
Services?	✓	None
Other buildings?	✓	Unused empty small single-story building by access gate
Other?		No
6. Are there any potential sources of contamination (if yes, give details)?	✓	Buried waste
Surface waste (if yes, what type)?	✓	None noted
Surface ponding of leachate	✓	None present
Leachate seepage	✓	None noted
Landfill gas odours	✓	None noted
7. Are there any outfalls to surface water? (If yes, are there discharges and what is the nature of the discharge?)	✓	No evidence
8. Are there any signs of impact on the environment? (if yes, take photographic evidence)	✓	None noted.
Vegetation die off, bare ground	✓	None noted
Leachate seepages	✓	None noted
Odours	✓	None Noted
Litter	✓	None
Gas bubbling through water	✓	None noted

Walkover Survey Checklist

Historic Kerry Landfills - Dingle

Signs of settlement	✓	No
Subsidence, water logged areas	✓	No evidence

Walkover Survey Checklist		
Information	Checked	Comment (include distances from Site Boundary)
Drainage or hydraulic issues	✓	None noted
Downstream water quality appears poorer than upstream water quality	✓	No
9. Are there any indications of remedial measures? (Provide details)	✓	No
Capping	✓	No waste evident
Landfill gas collection	✓	No
Leachate collection	✓	No
10. Describe fences and security features (if any)	✓	Site is fenced with sheep wire fencing and ditches. Access is through a metal gate.
Any other relevant information?		

For inspection purposes only.
Consent of copyright owner required for any other use.