




**FEHILY
TIMONEY**

**CONSULTANTS IN ENGINEERING,
ENVIRONMENTAL SCIENCE & PLANNING**

APPENDIX 5

**Site Walkover Checklist and
Photographic Log**

*For inspection purposes only.
Consent of copyright owner required for any other use.*



Walkover Survey Checklist

Historic Kerry Landfills - Ardferf

Walkover Survey Checklist		
Information	Checked	Comment (include distances from Site Boundary)
1. What is the current land use?	✓	Unused grassland
2. What are the neighbouring land uses?	✓	Cathedral (directly south), agricultural field (directly north, east and west – beyond a roadway), residential dwellings
3. What is the size of the site?	✓	Circa 1.01 ha
4. What is the topography?	✓	Slightly sloped (uphill is a north – south direction)
5. Are there potential receptors (if yes, give details)?	✓	Nearby residences, groundwater, surface water (River Tyshe)
Houses		
Surface water features (if yes, distance and direction of flow)?	✓	Yes, River Tyshe located less than 50m north of site boundary
Any wetland or protected areas?	✓	No
Public water supplies?	✓	Not identified
Private wells?	✓	Possible local usage
Services?		None
Other buildings?	✓	None with site boundary – cathedral directly south of site boundary and residential dwelling located approx. 25m north-west of site
Other?		No
6. Are there any potential sources of contamination (if yes, give details)?	✓	Buried waste
Surface waste (if yes, what type)?	✓	None noted
Surface ponding of leachate	✓	None present
Leachate seepage	✓	None noted
Landfill gas odours	✓	None noted
7. Are there any outfalls to surface water? (If yes, are there discharges and what is the nature of the discharge?)	✓	No evidence
8. Are there any signs of impact on the environment? (if yes, take photographic evidence)	✓	None noted.
Vegetation die off, bare ground	✓	None noted
Leachate seepages	✓	None noted
Odours	✓	None Noted
Litter	✓	None
Gas bubbling through water	✓	None noted

Walkover Survey Checklist

Historic Kerry Landfills - Ardfert

Signs of settlement	✓	No
Subsidence, water logged areas	✓	No evidence

Walkover Survey Checklist		
Information	Checked	Comment (include distances from Site Boundary)
Drainage or hydraulic issues	✓	None noted
Downstream water quality appears poorer than upstream water quality	✓	No
9. Are there any indications of remedial measures? (Provide details)	✓	No
Capping	✓	No evidence of waste
Landfill gas collection	✓	No
Leachate collection	✓	No
10. Describe fences and security features (if any)	✓	Ditches surrounding north, east and western boundaries, stone wall along southern boundary
Any other relevant information?		

For inspection purposes only.
Consent of copyright owner required for any other use.

Appendix

Site Walkover Photographs

*For inspection purposes only.
Consent of copyright owner required for any other use.*



PHOTOGRAPHIC LOG



Client Name: Kerry County Council

Site Location: Ardfert

Project Number: P1766

Photo No.

Date:

23/10/19

Description:

Residential entrance west of site, BH01 located just outside



Photo No.

Date:

23/10/19

Description:

BH01



PHOTOGRAPHIC LOG



Client Name: Kerry County Council

Site Location: Ardfert

Project Number: P1766

Photo No.

Date:

23/10/19

Description:

BH02 within field just north of old cathedral



Photo No.

Date:

23/10/19

Description:

Looking north from BH02 to river flowing in an east to west direction where surface water samples were collected.

