


30/5/18

EPA

Please find enclosed Letter we had to forward again to Kerry Ingredients in relation to their Treatment Plant.

As you are aware this is ongoing for the last number of years & now with the hot weather & these new tanks built nearer to us & uncovered we are back to the same situation & millions of litres of filthy water whirling around which is actually physically sickening! We are taking no more excuses now at this stage only action. We have tried to be fair with them but they are creating us like shit!



Yours
Carol O'Connor

Mutual OC

Kerry Ingredients

Dear Teresa,

Unfortunately this smell is around again, which we hadn't for last 12 months.

As you are aware I told you we weren't going to object to anything when ye were looking for phawing because it would improve the situation.

It is very disappointing to see these new tanks nearer to us instead of they being built further away, when ye knew that it was an ongoing problem. Ye covered one of the old tanks going back 2 years ago and it made a big improvement. Now we have these newer tanks, nearer to us and uncovered! So windows closed again back to square one!!

Yours
Carol O'Connor
Michael O'Connor



Kerry Ingredients

Kilmallock Road
Charleville
Co. Cork
Ireland
Telephone: 063 35000
Fax: 063 35001

Mr. and Mrs. Michael O' Connor,
Ballincolly,
Charleville,
Co. Cork.

15/6/15

Re: Odours from Effluent Treatment Plant

Dear Mr. and Mrs. O' Connor,

Following our meeting in January, we consulted with an effluent treatment plant expert to advise us on potential sources of smells from our effluent treatment plant. Following this season's milk start-up he assessed the plant and identified the effluent receipt balance Tank as the most likely cause of issues, and advised the following works to be carried out:

1. To change the current surface mounted aerator with a mixer located on the tank floor. This would eliminate the spray of effluent into the air and would mix the tank better thus reducing the risk of solids settling out and going off at the bottom of the tank.
2. To enclose the tank fully.
3. To fit an odour scrubbing unit to treat the air coming off the tank.

Quotations have been got for this work and budget approval has been received. Work is commencing this week on installing the different type of mixers outlined in point 1 above. The structure to enclose the tank and the odour scrubber unit have also been ordered. There is a longer lead time on these items. Our plan is to complete their installation in October.

We are confident that the planned works will deal with this recent issue and previous problems.

Hopefully, this will assure ye that we are taking this issue seriously.

Yours sincerely,

Teresa Fitzgerald

Environment Manager.