



# Meeting Record

<p>Title</p> <p>Meeting Date &amp; Time</p> <p>Venue</p>	<p>Tipperary County Council and EPA</p> <p>Meeting to discuss changes in management arrangements and operational issues at Ballaghveny Landfill, Donohill Landfill and Wallerslot Transfer Station.</p> <p>08/12/14 14:40</p> <p>Ballaghveny Landfill</p>
<p>Name, Address and Reg. No. of the Licensee</p>	<p>Ballaghveny Landfill W0078-03, Donohill Landfill W0078-03 and Recycling Centre and Waste Transfer Station W0200-01</p>
<p>Name of Facility</p>	<p>Ballaghveny Landfill, Donohill Landfill and Wallerslot Transfer Station</p>
<p>Present at meeting</p>	<p>Office of Environmental Enforcement – Mary Frances Rochford (MFR) Tipperary County Council (Licensee)- Louise Ryan (LR), Ann Peters (AP)</p>
<p>Issues and action items</p>	<p>Ballaghveny:</p> <ul style="list-style-type: none"> <li>• Groundwater Report: Due for completion by 25<sup>th</sup> January 2015. Meeting between EPA and Tipperary CoCo to discuss the findings on Tuesday 3<sup>rd</sup> February 2015.</li> <li>• Louise Ryan will schedule an appointment to view the Licence application files at EPA offices on a date in early January. To arrange an appointment please contact Andrew Cox on 053-9160600 or <a href="mailto:a.cox@epa.ie">a.cox@epa.ie</a>.</li> <li>• The Licensee advised that it was considering putting a proposal forward to request amendments to the monitoring requirements of the licence in light of the closed status of the landfill. MFR advised that the Licensee should submit a proposal to the Agency including justification for each amendment.</li> <li>• Request for postponement of monitoring of Noise and Dust 2014. The Licensee was advised to submit this request in writing prior to the end of 2014.</li> <li>• The Licensee advised that improvements had been made in the telemetry system at the landfill and it was now possible to view and control the flare and leachate pumps remotely. Surface water monitoring is not currently on SCADA as the Licensee has been in discussions with its insurance company to ensure that repair and installation of replacement sampler meets the insurance company requirements. External sampling and analysis has been used to monitor the quality of discharges from the site.</li> <li>• Site security: The site was broken into earlier in 2014 and significant damage was carried out. In weeks prior to the meeting over 22 stray horses had been removed from the site.</li> <li>• The Licensee enquired as to the Agency’s thoughts on the treatment of</li> </ul>

leachate in a local integrated constructed wetland. The Licensee was advised that appropriate authorisation would be essential prior to further consideration. MFR advised that she would consult colleagues on the matter of alternative treatment for leachate.

- Changes to licence boundary. The Licensee was advised that any requests for alterations should be submitted to the Agency via EDEN.

#### Donohill

The Licensee advised that it would be reviewing leachate and gas infrastructure at the landfill and the procurement was underway.

MFR advised of the need to expedite in installation of temporary capping and associated infrastructure and that the Agency was extremely concerned at the lengthy timeframe for the commencement of these works.

#### Wallerslot

The Licensee queried why IED amendments were not included in the licence review. MFR advised that she would seek clarification on this matter and that the Licensee should also seek feedback on its previous conversation with the EPA licensing unit.

#### Incident Reporting:

MFR advised that all incidents should be notified in accordance with the licence conditions via EDEN and that where an incident relates to more than one monitoring point each monitoring point should be subject to a separate notification and where an incident covers more than one day of monitoring each day should be a separate notification.

The EPA will be considering this matter further in early 2015.

Signed: *Mary Frances Rochford*

Date: 22/12/14