

Environmental Health Service
HSE Dublin/North East
Cavan and Monaghan
The Arcade
Main Street
Cavan
Co Cavan

Tel No: +353 (0) 49 4373418 Fax No: +353 (0) 49 4373427

Ref/ IMcC/BMcK/CMcE

24 November 2011

Ms Josephine Kennedy
Office of Climate, Licencing & Resource Use
Environmental Protection Agency
Headquarters
PO Box 3000
Johnstown Castle Estate
County Wexford

ENVIRONMENTAL PROTECTION AGENCY
28 NOV 2011

Re: Review License Registration Number P0800-02

Lakelands Dairies Co-operative Society Limited, Killeshandra, Co.Cavan

Dear Ms Kennedy,

Please find enclosed the HSE consultation report in relation to the above application.

If you have any queries regarding the report, the initial contact is Brian McKeever Principal Environmental Health Officer.

The Environmental Health service response to the application is in the attached consultation report.

- The assessment is based on an assessment of documentation submitted to this office.
- No additional investigations / measurements were undertaken.

Yours sincerely,

Brian McKeever

Principal Environmental Health Officer

## HSE IPPC LICENSE REVIEW SUBMISSION REPORT

## **Environmental Health Service Consultation Report**

Report to: Josephine Kennedy

Office of Climate, Licensing & Resource use

**Environmental Protection Agency** 

Headquarters

PO Box 3000

Johnstown Castle Estate

Co. Wexford

Type of consultation: License Review

Reference Number: P0800-02

Applicant: Lakeland Dairies Co-Operative Society Limited,

Killeshandra, Co Cavan

## Section B

In the application, it states that Tables B1(i) and B.1(ii) have been completed for the 4 emission points;

SW1 – Storm waters, Cooling waters and RO water

SW2 – Storm waters, Cooling waters and RO water

SW3 – Storm waters, Cooling waters and RO water

SW4 - Treated effluent from the Waste Water

**Treatment Plant** 

however, the attachment only contains completed tables for SW4. In Table B.1(ii) the parameters Ammonia and Total Nitrogen as N exceed the license limits. Results have not been provided for all the parameters listed in this table.

Section B2 states that SW1, SW2 and SW3 are sampled and monitored at locations immediately prior to the waters leaving the dairy site. The three surface waters then combine in one pipe and are diverted to the Town Lough together. The emission point to the lake is located at 630770, 807701. However, these same reference points are given for SW1 in Table B2, which seems to contradict what has been stated. This requires clarification.

Consent of copyright owner required for any other use.