



APPENDIX 5


For inspection purposes only.
Consent of copyright owner required for any other use.



Rialtas Áiríúil
Local Government

9th August 2010

Martina Nolan,
Office of Environmental Enforcement,
Regional Inspectorate,
Seville Lodge,
Callan Road,
Kilkenny.



Comhairle Chontae
Wexford

Wexford County Council
County Hall
Wexford

Tel 053 9176500
Fax 053 9143406
Email postmaster@wexfordcoco.ie

**Re: PAE2010/160 – Carcur Closed Landfill -
Illegal Dumping**

A Chara,

I refer to your letter dated 7th July 2010 in connection with the above.

The issues raised in your correspondence are addressed as per your standard attachment 1, activity details plus our backup information and photographs.

Should you have any further queries, please do not hesitate to contact me.

Yours Sincerely

Rory O'Mahony
Senior Executive Engineer
Environment Section
Tel. 053 9176334
Email: { HYPERLINK "mailto:rory.omahony@wexfordcoco.ie" }

11. Describe the types of waste/material handled	THE MATERIAL IS BROWN CLAY, DENSE WITH A LOW PERMEABILITY OF 1×10^{-9} M/S. THE MATERIAL IS IDEAL FOR CAPPING COVER TO LANDFILL.
12. Quantities of waste/material handled (tpa)	12,411 tonnes
13. Tonnage on-site	12,411 tonnes
14. Describe, how and for what period the waste/material is stored	THE MATERIAL WAS DEPOSITED ON SITE OVER A PERIOD FROM 16 JAN '09 TO 5 FEB '09
15. Origins of such waste/material	FROM THE SITE OF THE NEW COCA COLA FACILITY AT DRINAGH, WEXFORD.
16. Describe how the waste/material is processed	THE MATERIAL WAS TESTED AT ITS ORIGINAL SITE COCA COLA DRINAGH AND FOUND TO HAVE LOW PERMEABILITY, THEREFORE CONSIDERED ENGINEER GRADE MATERIAL (NOT WASTE). THE MATERIAL WAS TRANSFERRED TO CARCUR IN TEMP. SPOIL HEAP, ADJA

17. Type of waste activity (tick all that apply)				
Disposal activity		Recovery activity	<input checked="" type="checkbox"/>	Both
Hazardous waste		Non-hazardous		Inert
Existing		Past/ceased		Proposed development

TO THE LANDFILL

18. What best describes this activity (landfill, transfer station, land reclamation etc.)	RESTORATION WORK TO COVER/CAP OFF HISTORIC LANDFILL SITE AT CARCUR
19. Describe the ultimate destination(s) of the waste/material handled	FINAL DESTINATION WILL BE CAPPING COVER TO HISTORIC LANDFILL AT CARCUR

Attachment 1 Activity Details

1. Location address -as specific as possible	CARCUR CLOSED LANDFILL CARCUR WEXFORD
2. County	WEXFORD
3. Site Area Involved	9 HECTARES
4. Operator name	WEXFORD BOROUGH COUNCIL
5. Contact address	CRESCENT QUAY WEXFORD
6. Owner name (if different from above)	SAME
7. Owner address (if different from above)	SAME
8. When did the Local Authority become aware of this activity?	WCC ENVIRONMENT COMPLAINTS DESK RECEIVED A COMPLAINT BY PHONE FROM JOSEPHINE SOMERS ON 9/2/9
9. Details of enforcement actions taken/to be taken	SEE ATTACHED LIST
10. Details of planning status/planning issues	CARCUR LANDFILL CLOSED IN 1985 WBC ARE PREPARING AN APPLICATION FOR AUTHORISATION TO OCLR FOR THE RESTORATION & AFTER CARE FOR THE SITE.


Consent of copyright owner required for any other use.

REF. NO. 4724

A PRELIMINARY MEETING WAS HELD WITH THE OCLR IN 2009. WBC NOW APPOINTING CONSULTANTS TO COMPLETE THE PROCESS WITH OCLR (EPA) TO GET AGREEMENT OF RESTORATION WORK. AFTER THAT STAGE WBC COULD GO FOR PLANNING PERMISSION IN FEB 2009 WBC COUNCILLORS APPROVED THE PLAN TO RESTORE CARCUR LANDFILL TO A PUBLIC PARK

APPENDIX 1

(Map of Carcur Landfill Site)





Map Width: 763.2 m

© Ordnance Survey Ireland. All rights reserved. Licence number 2009/34/CCMA/Wexford Local Authority

Produced By: 10.68.1.13

3 Nov







For information purposes only.
Concept of copyright is not required for any other uses.

