

NOTES

- Denotes Sewer Monitoring Point
- Denotes Surfacewater Monitoring
- Denotes noise monitoring point
- ⊗ Denotes dust monitoring point

I.D.	EASTING	NORTHING
NSL1	298403	143634
NSL2	298382	143394
N1	298282	143574
N2	298302	143479
SE-1	298360	143420
SE-2	298251	143491
SW-1	298258	143487
D1	298283	143575
D2	298368	143478
D3	298368	143530

REV	DATE	DESCRIPTION	DRN	CHNO	APP
B	08/07/08	FI	MW	JOC	**
A	09/11/07	ISSUE	MW	JOC	**

O'Callaghan Moran & Associates,
 Genery House, Rutland Street,
 Cork, Ireland.
 Tel. (021) 4321521 Fax. (021) 4321522
 email : ocm@oandac.ie

CLIENT
GREENSTAR LTD

TITLE
**MONITORING LOCATIONS
 ENNISCORTHY**

SCALE	DRAWING No.	REV.
1:1000	F1	B

