

CONTENTS

CONTENTS	I
TABLE OF FIGURES	I
TABLES	II
SECTION 1: INTRODUCTION	1
SECTION 2: THE PROPOSED DEVELOPMENT	6
2.1 ALTERNATIVES	6
2.2 LAYOUT, INFRASTRUCTURE, AND OPERATIONS	10
2.3 CONSTRUCTION AND DECOMMISSIONING	26
SECTION 3: ENVIRONMENTAL ASSESSMENT	28
3.1 HUMAN BEINGS	29
3.2 FLORA AND FAUNA	41
3.3 SOILS, GEOLOGY AND WATER	52
3.4 AIR	53
3.5 CLIMATE	57
3.6 THE LANDSCAPE	62
3.7 MATERIAL ASSETS	67
3.8 NOISE	73
3.9 INTER-RELATIONSHIPS	75
SECTION 4: ATTACHMENTS	79
ATTACHMENT A: ARCHAEOLOGY REPORT	I
ATTACHMENT B: SOILS, GEOLOGY AND WATER SECTION	II
ATTACHMENT C: AIR QUALITY REPORT	III
ATTACHMENT D: ENVIRONMENTAL NOISE SURVEY	IV
ATTACHMENT E: NOISE IMPACT ASSESSMENT	V
ATTACHMENT F: ODOUR AND BIOAEROSOLS RISK ASSESSEMENT	VI
ATTACHMENT G: DECOMMISSIONING AND SITE RESTORATION PLAN	VII
ATTACHMENT H: MAPS AND DRAWINGS	VIII

TABLE OF FIGURES

Figure AR2-01: EU Waste Management Hierarchy	8
Figure AR2-02: Projected BMW production Vs. Landfill Directive targets	9
Figure AR2-03: Process Flow Diagram	19
Figure AR2-04: Biofilter configuration	23
Figure AR3-01: Map of road network	29
Figure AR3-02: Travellers encampment located near the site	30
Figure AR3-03: Dwellings in the vicinity of the site	31
Figure AR3-04: Bord Na Mona Briquette Factory	32
Figure AR3-05: Main Dublin-Cork Road passing through Littleton	33
Figure AR3-06: Road serving proposed development	33

Figure AR3-07: Road Traffic Results 35

Figure AR3-08: Vehicles estimated to service facility 39

Figure AR3-09: Overall Predicted Traffic 8am-6pm during operations..... 39

Figure AR3-10: Ecology map of the site and surrounding land 42

Figure AR3-11: Locations of the 5 Quadrats..... 44

Figure AR3-12: Results of Flora Species 46

Figure AR3-13: Tree Species Composition..... 47

Figure AR3-14: Monitoring and Emission Point Location Map 57

Figure AR3-15: Example of base unit for monitoring station 61

Figure AR3-16: Example of wind anemometer for measuring wind speed and direction 61

Figure AR3-17: View towards site from entrance..... 63

Figure AR3-18: Mature hedgerow east of site..... 63

Figure AR3-19: Existing willow plantation (May 2007) 64

Figure AR3-20: Landscaping Plan..... 65

Figure AR3-21: Map showing the towns linked up by the Turnpike Routeway 67

Figure AR3-22: Past and present populated areas in the village of Littleton..... 68

Figure AR3-23: Saint Mary’s Church in the village of Littleton. 69

Figure AR3-24: Ballybeg Tower House..... 70

Figure AR3-25: Map Of Recorded Sites in the Vicinity of the site..... 71

TABLES

Table AR2-01: Bio-filter monitoring schedule.....25

Table AR3-01: Traffic Survey Data 34

Table AR3-02: Predicted increase in traffic movements.....37

Table AR3-03: Materials transportation.....38

Table AR3-04: Ground Flora Results45

Table AR3-05: Trees Species on Site46

Table AR3-06: Bird Species Present on Site48

Table AR3-07: Mammals Present on Site49

Table AR3-08: Insects, Water Dwellers and Reptiles present on site.....49

Table AR3-09: Air Quality Monitoring Schedule56

Table AR3-10: The Monthly and Annual Mean and Extreme Values Over The Past 30 Years57

Table AR3-11:The Average Relative Humidity Over 30 Years Taken at 0900UTC.....57

Table AR3-13: The Average Wind Figures For a 30 Year Period58

Table AR3-14: 30 Year Averages of Snow, Hail, Thunder and Fog.....59

Table AR3-15: Proposed Noise Monitoring Schedule74

Table AR3-16: Inter-relationships between environmental categories.75

*For inspection purposes only.
Consent of copyright owner required for any other use.*