

## Appendix 1

### Satellite Image of Oxigen Site Ballymount



## Appendix 2

### Photographs taken at monitoring locations



Photograph taken at D1



Photograph taken at D2



**Photograph taken at D3**

*For inspection purposes only.  
Consent of copyright owner required for any other use.*





Ireland

6 Bridge Court,  
City Gate,  
St. Augustine Street,  
Dublin 8

Tel: 01 633 4725  
Fax: 01 633 4562

**TOBIN CONSULTING  
ENGINEERS  
BALLYMOUNT, DUBLIN  
TRAFFIC SURVEY**

**SURVEY REPORT  
MARCH 2010**

*For inspection purposes only. Consent of copyright owner required for any other use.*

PROJECT NO.	663
CHECKED	P. MURRAY
DATE	11/03/2010
CONTACT	J. FAULDS
REVISION	

## CONTENTS

Introduction

Junction Turning Counts

Diagram 663-01

Appendix A – Vehicle Categories

Appendix B – Survey Results

*For inspection purposes only.  
Consent of copyright owner required for any other use.*

## INTRODUCTION

Nationwide Data Collection (NDC) was instructed by Tobin Consulting Engineers to undertake classified junction turning counts in around the Ballymount Industrial Estate in Dublin.

A general location plan is given in Diagram 663-01.

## JUNCTION TURNING COUNTS

Classified junction turning counts were undertaken at the following sites:

Site No.	Location.	Day / Date
1	Turnpike Rd / Access Rd / Ballymount Rd Upper / Ballymount Road Lower	Wednesday 3 <sup>rd</sup> March 2010
2	Access Rd(N) / Oxigen Facility / Access Rd(S) / Site Entrance(E)	
3	Turnpike Rd(N) / Turnpike Rd(S) / Access Rd	

All sites were surveyed using telescopically mounted video cameras from which the information was subsequently extracted. Details of the arm labelling are given in Diagram 663-01.

The survey was carried out with survey hours of 07:00 to 19:00. All information was collected in 15 minute intervals and has been tabulated with both hourly and period totals.

Vehicles were classified into the following categories:

- Cars and Taxis / Light Goods Vehicles (**LV**),
- Heavy Goods Vehicles / Buses (**HV**).

A detailed description of the vehicles included in each category is provided in Appendix A.

**SITE REPORT**

**Weather** Wednesday 3<sup>rd</sup> March 2010 – Clear and Bright.

**Accidents** None.


**Roadworks** None.

**Queues** Not recorded.


**Pedestrians** Not recorded.

**General Site Notes.** None.

*For inspection purposes only.  
Consent of copyright owner required for any other use.*



Copyright © and (P) 1988–2006 Microsoft Corporation and/or its suppliers. All rights reserved.

	<b>Sites / Location:</b> 1 to 3 / Ballymount, Dublin	<b>Project No:</b> 663	<b>Diagram No:</b> 663-01	<b>Drawn By:</b> JF
	<b>Survey Date:</b> Wednesday 3rd March 2010	<b>Project Name:</b> BALLYMOUNT, DUBLIN		
	<b>Survey Times:</b> 07:00 to 19:00	<b>Diagram Title:</b> General Location Plan		