



The existing operational area is located behind this vegetation/ridgeline

VIEWPOINT E: DISTANT VIEW ALONG LOCAL ROAD SOUTH WEST OF THE APPLICATION SITE

Grid Reference: 298870E, 136138N

Distance from site boundary: 1.2km

Approximate Elevation: 70m AOD

Direction of View: North West

DESCRIPTION: THE APPLICATION SITE IS NOT VISIBLE FROM THIS AREA, DUE TO INTERVENING TOPOGRAPHY AND MATURE VEGETATION.

Visual Impact Assessment of Proposed Development:

SENSITIVITY OF VIEWPOINT: NEGLIGIBLE

MAGNITUDE OF CHANGE TO VIEW: NONE

RESIDUAL VISUAL IMPACT: NONE



The existing operational area is located behind this vegetation/ridgeline

VIEWPOINT F: DISTANT VIEW ALONG LOCAL ROAD SOUTH OF THE APPLICATION SITE

Grid Reference: 297949E, 136064N

Distance from site boundary: 1.2km

Approximate Elevation: 10m AOD

Direction of View: North

DESCRIPTION: THERE ARE A NUMBER OF PROPERTIES IN THE VICINITY OF THIS VIEWPOINT WITH SIMILAR VIEWS. THE APPLICATION SITE IS NOT VISIBLE FROM THIS AREA, DUE TO INTERVENING TOPOGRAPHY AND MATURE VEGETATION.

Visual Impact Assessment of Proposed Development:


Sensitivity of Viewpoint: LOW

Magnitude of Change to View: NONE

Residual Visual Impact: NONE

- NOTES**
1. EXTRACT FROM 1:50,000 O.S DISCOVERY MAP NO. 68 & 69
 2. ORDNANCE SURVEY IRELAND LICENCE N SU 0000711 (C) ORDNANCE SURVEY & GOVERNMENT OF IRELAND

LEGEND



Note: All photos were taken on 8th August 2010 in partly cloudy dry conditions using the digital equivalent of 50mm focal length lens.



SLR
 SLR CONSULTING RB
 7 DUNDUM BUSINESS PARK
 WINDY ASH
 DUBLIN
 T: +353-1-226
 F: +353-1-226
 www.slrconsulting.com

ROADSTONE WOOD LTD.
 ENVIRONMENTAL IMPACT STATEMENT
 WASTE RECOVERY FACILITY,
 BROWNSWOOD, CO. WEXFORD
 VIEWPOINTS E & F

FIGURE 10-4

Scale: NTS Date: JUNE 2011