#### WATER MATTERS





## **RESPONSE GROUP • CORK • CHARLEVILLE • CARLOW • DONEGAL**

Response Group LimitedRailway Road, Charleville, Co. Cork, Ireland (registered office)Tel +353 (0)63 33400 Fax +353 (0)63 33401 Web www.response-group.ie

	IONS MANAGER Johnston	MONTHLY STATUS REPORT FOR KILBRITTAIN WWTP		resp	group
Respo	onse Engineerir	ng Ltd			
Document Title:		Monthly Report			
DOCUMENT No:		AJ-01			
	TH: May 2012 It: Cork County Incil		5 <sup>56</sup> .		
	Kilbrittain	es only any other			
Site: I	-	ition: Edel Brennan	Date:	08/06/201	2
Site: I	Kilbrittain Manager Authorisa	Chipseiton Person		APPROV	ALS
Site: I	Kilbrittain Manager Authorisa Date	Issue Description	Ву	APPROV Check	ALS Approved
Site: I	Kilbrittain Manager Authorisa	MAY MONIFLY OPERATIONS REPORT		APPROV	ALS
Site: I	Kilbrittain Manager Authorisa Date	Issue Description	Ву	APPROV Check	ALS Approved
Site: I	Kilbrittain Manager Authorisa Date	MAY MONIFLY OPERATIONS REPORT	Ву	APPROV Check	ALS Approved
Site: I	Kilbrittain Manager Authorisa Date	MAY MONIFLY OPERATIONS REPORT	Ву	APPROV Check	ALS Approved
Site: I	Kilbrittain Manager Authorisa Date	MAY MONIFLY OPERATIONS REPORT	Ву	APPROV Check	ALS Approved
Site: I	Kilbrittain Manager Authorisa Date	MAY MONIFLY OPERATIONS REPORT	Ву	APPROV Check	ALS Approved
Site: I Project Rev	Kilbrittain Manager Authorisa Date 08/06/2012	MAY MONIFLY OPERATIONS REPORT	By POK	APPROV Check	ALS Approved
Site: I	Kilbrittain Manager Authorisa Date	MAY MONTHER OPERATIONS REPORT	By POK	APPROV Check	ALS Approved
Site: I Project Rev	Kilbrittain Manager Authorisa Manager Authorisa Date 08/06/2012	MAY MONTHERY OPERATIONS REPORT	By POK	APPROV Check	ALS Approved
Site: I Project Rev	Kilbrittain Manager Authorisa Date 08/06/2012	Issue Description         MAY MONTHEY OPERATIONS REPORT         Construction         DOCUMENT IS         In-house Review         Y       Client Approval	By POK	APPROV Check	ALS Approved

**OPERATIONS MANAGER** 

MONTHLY STATUS REPORT FOR



**KILBRITTAIN WWTP** 

response group

#### 1.0 **EXECUTIVE SUMMARY**

2.0 **INTRODUCTION** 

#### 3.0 RESULTS

- 3.1 FLOWS
- 3.2 PE COMPARISON
- 3.3 AERATION TANK
- 3.4 INLET AND FINAL EFFLUENT

#### 4.0 COMMENTS ON ANALYSIS RESULTS

- **PROCESS OPERATIONAL ISSUES** 5.0
- ould any other use. 

   BREAKDOWNS AND NON ROUTINES
   MAINTENANCE

   HEALTH AND SAFETY
   HEALTH AND SAFETY

   COMPLAINTS
   Foot inspection product of the 6.0
- 7.0
- 8.0
- ALARM CALLOUTS & SITE INCIDENTS 9.0

0

- ANALYSIS RESULTS FOR THE EPA 10.0
- 11.0 SLUDGE AND NON SLUDGE REMOVAL
- 12.0 FACILITY MAINTENANCE
- **13.0 FINANCIAL REVIEW**

**OPERATIONS MANAGER** 

#### **MONTHLY STATUS REPORT FOR**



**Ailish Johnston** 

**KILBRITTAIN WWTP** 

#### **APPENDICIES**

Appendix A: Flow Readings Appendix B: Results Summary Appendix C: Graphs Appendix D: Hours Run Schedule Appendix E: Weather Record Appendix F: Facility Maintenance Appendix G: Proposed Additional Works

**OPERATIONS MANAGER** 

MONTHLY STATUS REPORT FOR



**Ailish Johnston** 

**KILBRITTAIN WWTP** 

#### 1. EXECUTIVE SUMMARY

The plant was in full compliance with all parameters.

## 2. INTRODUCTION

This report deals with the month of May 2012, from  $1^{st} - 31^{st}$ .

#### 3. RESULTS

#### Refer to Appendix A & B.

3.1 Flows

The average flow to the plant was 425m<sup>3</sup>/day.

#### **3.2 PE Comparison**

uppose only any other use. lipose only to any other use. lan, The hydraulic PE of the plant was 2127m<sup>3</sup>/day, plant is designed for 800. The PE BOD of the plant was 2127, plant is designed for 800. spector 3.3 Aeration Tank

The average MLSS for the month was 5109mg/l.

## 3.4 Inlet & Final Effluent Results

All effluent results are compliant for the month of May.

## 4. COMMENTS ON ANALYSIS RESULTS

The plant is significantly biologically under loaded in terms of BOD and under loaded in terms of flow.

## 5. PROCESS OPERATIONAL ISSUES

There is nothing to report.

MONTHLY STATUS REPORT FOR **OPERATIONS MANAGER** 



**Ailish Johnston** 

**KILBRITTAIN WWTP** 

## 6. BREAKDOWNS & NON-ROUTINE MAINTENANCE

Inlet Pump No.1 needs a new impellor. RAS/WAS pump no. 2 tripping. It was sent off site for repair on 4/01/2012.

#### 7. HEALTH & SAFETY

There is nothing to report.

#### 8. COMPLAINTS

There is nothing to report.

#### 9. ALARM CALLOUTS & SITE INCIDENTS

## **10. ANALYSIS RESULTS FOR THE EPA**

There is nothing to report.						
9. ALARM CALLOUTS & SITE INCID	ENTS					
There is nothing to report.	ENTS					
10. ANALYSIS RESULTS FOR THE EPA	A set of tot					
The plant discharge parameters were:						
LICENCE REQUIREMENTS	MONTH AVERAGES					
COD 125mg/l	61mg/l					
BOD 25mg/l	18mg/l					
SS 30mg/l	21mg/l					
TP 2mg/l	1.20mg/l					

## **11. SLUDGE REMOVAL**

16<sup>th</sup> May, Sludge removed from site by Countywide Drain Services Ltd.

## **12. FACILITY MAINTENANCE**

No issues to report.

#### **13. FINANCIAL REVIEW**

Monthly Application submitted, in accordance with the contract requirements for May 2012.



# APPENDIX A.



# **APPENDIX B.**



# APPENDIX C.



# APPENDIX D.



# **APPENDIX E.**



# **APPENDIX F.**



## APPENDIX G.