

WATER MATTERS



RESPONSE GROUP • CORK • CHARLEVILLE • CARLOW • DONEGAL

Response Group LimitedRailway Road, Charleville, Co. Cork, Ireland (registered office)Tel +353 (0)63 33400 Fax +353 (0)63 33401 Web www.response-group.ie

MONTHLY STATUS REPORT FOR





Response Engineering Ltd

DOCUMENT No: AJ-01

PROJECT NUMBER:

MONTH: September 2012

Client: Cork County

Council

Site: Kilbrittain

Inspection purposes only any other tree. Project Manager Authorisation: Neil Ronan Date: 10/10/2012

		tingfe om	APPROVALS		
Rev	Date	Issue Description	Ву	Check	Approved
	10/10/2012	SEPTEMBER MONTHLY OPERATIONS REPORT	POK	AJ	NR
		Course			
\boxtimes	Entire Document	DOCUMENT ISSUED FOR:			
	Issued this Revision	In-house Review			
	Revised Pages Only	Client Approval			
	Issued this Revision	Enquiry			

MONTHLY STATUS REPORT FOR

response

Ailish Johnston

KILBRITTAIN WWTP

- 1.0 **EXECUTIVE SUMMARY**
- 2.0 INTRODUCTION
- 3.0 **RESULTS**
 - 3.1 **FLOWS**
 - 3.2 PE COMPARISON
 - 3.3 AERATION TANK
 - INLET AND FINAL EFFLUENT
- 4.0 COMMENTS ON ANALYSIS RESULTS
- PROCESS OPERATIONAL ISSUES 5.0
- BREAKDOWNS AND NON ROUTINES MAINTENANCE
 HEALTH AND SAFETY
 COMPLAINTS

 FOOTBREEFFE TO THE PROPERTY OF THE PROPE 6.0
- **7.0**
- 8.0
- ALARM CALLOUTS & SITE INCIDENTS 9.0
- ANALYSIS RESULTS FOR THE EPA 10.0
- 11.0 SLUDGE AND NON SLUDGE REMOVAL
- 12.0 **FACILITY MAINTENANCE**
- 13.0 FINANCIAL REVIEW

MONTHLY STATUS REPORT FOR

Ailish Johnston

KILBRITTAIN WWTP



APPENDICIES

Appendix A: Flow Readings Appendix B: Results Summary

Appendix C: Graphs

Appendix D: Hours Run Schedule Appendix E: Weather Record Appendix F: Facility Maintenance

Appendix G: Proposed Additional Works

MONTHLY STATUS REPORT FOR

Ailish Johnston

KILBRITTAIN WWTP



1. EXECUTIVE SUMMARY

The plant was in full compliance with all parameters.

2. INTRODUCTION

This report deals with the month of September 2012, from $1^{st} - 30^{th}$.

3. RESULTS

Refer to Appendix A & B.

3.1 Flows

The average flow to the plant was 89m³/day.

3.2 PE Comparison

The hydraulic PE of the plant was 443m³/day plant is designed for 800. The PE BOD of the plant was 321, plant is designed for 800.

3.3 Aeration Tank

The average MLSS for the month was 4851mg/l.

3.4 Inlet & Final Effluent Results

All effluent results are compliant for the month of September.

4. COMMENTS ON ANALYSIS RESULTS

The plant is significantly biologically under loaded in terms of BOD and under loaded in terms of flow.

5. PROCESS OPERATIONAL ISSUES

There are none to report.

MONTHLY STATUS REPORT FOR

Ailish Johnston

KILBRITTAIN WWTP



6. BREAKDOWNS & NON-ROUTINE MAINTENANCE

Inlet Pump No.1 needs a new impellor.

17th September, there was Power cut in plant all panels had to be reset.

7. HEALTH & SAFETY

There is nothing to report.

8. COMPLAINTS

There is nothing to report.

9. ALARM CALLOUTS & SITE INCIDENTS

10. ANALYSIS RESULTS FOR THE EPA

9. ALARM CALLOUTS & SITE INCIDENTS						
9. ALARM CALLOUTS & SITE INCIDENTS There is nothing to report. 10. ANALYSIS RESULTS FOR THE EPA per all the plant discharge parameters were:						
10. ANALYSIS RESULTS FOR THE EPA						
The plant discharge parameters were:						
LICENCE REQUIREMENTS	MONTH AVERAGES					
COD 125mg/l	19mg/l					
BOD 25mg/l	7mg/l					
SS 30mg/l const	15mg/l					
TP 2mg/l	1.5mg/l					

11. SLUDGE REMOVAL

There was no sludge removed from the site this month.

12. FACILITY MAINTENANCE

No issues to report.

13. FINANCIAL REVIEW

Monthly Application submitted, in accordance with the contract requirements for September 2012.

MONTHLY STATUS REPORT FOR

Ailish Johnston





APPENDIX A.

MONTHLY STATUS REPORT FOR

Ailish Johnston

KILBRITTAIN WWTP



APPENDIX B.

MONTHLY STATUS REPORT FOR

Ailish Johnston

KILBRITTAIN WWTP



APPENDIX C.

MONTHLY STATUS REPORT FOR

Ailish Johnston

KILBRITTAIN WWTP



APPENDIX D.

MONTHLY STATUS REPORT FOR

Ailish Johnston KILBRITTAIN WWTP



APPENDIX E.

MONTHLY STATUS REPORT FOR

Ailish Johnston

KILBRITTAIN WWTP



APPENDIX F.

MONTHLY STATUS REPORT FOR

Ailish Johnston

KILBRITTAIN WWTP



APPENDIX G.