

Limerick Gasworks - Site Photographs, July 2009



Photo 1) AGI site



Photo 2) Gasholder 2 and Groverner house

Limerick Gasworks - Site Photographs, July 2009



Photo 3) Bord Gais offices



Photo 4) Back wall of booster house

Limerick Gasworks - Site Photographs, July 2009



Photo 5) Looking west from Gasholder 2



Photo 6) Gasholder 2

Limerick Gasworks - Site Photographs, July 2009



Photo 7) Gasholder 2 and AGI



Photo 8) Groverner house

Limerick Gasworks - Site Photographs, July 2009



Photo 9) Inside manhole



Photo 10) Booster house slab