

Limerick Gasworks - Site Photographs, July 2009



Photo 31) Limestone behind No. 5 stores



Photo 32) South west side of No.5 stores



Limerick Gasworks - Site Photographs, July 2009



Photo 33) Gasholder 3



Photo 34) Exposed wall



Limerick Gasworks - Site Photographs, July 2009



Photo 35) Tank 1 bund



Photo 36) Tank 1 bund



Limerick Gasworks - Site Photographs, July 2009



Photo 37) Site corner from Gasholder 3



Photo 38) Exposed limestone bedrock



Limerick Gasworks - Site Photographs, July 2009



Photo 39) Tank 1 bund exterior



Photo 40) View west across the site