

Map showing location of Photographs



Map 1




Map 2

# Photograph 1 – Aerial View



Current View



Restored View



## Photograph 2 – View from Redhills



Current View



Restored View



### Photograph 3 – View from Redhills



Current View



Restored View

## Photograph 4 – View from Redhills



Current View



Restored View

For inspection purposes only.  
Consent of copyright owner required for any other use.



## Photograph 5 – View from Redhills



Current View



Restored View

For inspection purposes only.  
Consent of copyright owner required for any other use.

## Photograph 6 – View from Existing Entrance



Current View



Restored View



Photograph 7 – View from within site (see map for location)



Current View



Restored View

Photograph 8 – View from within site (see map for location)



Current View



Restored View

For inspection purposes only.  
Consent of copyright owner required for any other use.



Photograph 9 – View from within site (see map for location)



Current View



Restored View

For inspection purposes only.  
Consent of copyright owner required for any other use.

Photograph 10 – View from within site (see map for location)



Current View



Restored View

For inspection purposes only  
Consent of copyright owner required for any other use



Photograph 11 – View from within site (see map for location)



Current View



Restored View

Photograph 12 – View from within site (see map for location)



Current View



Restored View

For inspection purposes only.  
Consent of copyright owner required for any other use.



Photograph 13 – View from within site (see map for location)



Current View



Restored View

For inspection purposes only.  
Consent of copyright owner required for any other use.

Photograph 14 – View from within site (see map for location)



Current View



Restored View



Photograph 15 – View from within site (see map for location)



Current View



Restored View

Photograph 16 – View from within site (see map for location)



Current View



Restored View

For inspection purposes only  
Consent of copyright owner required for any other use



Photograph 17 – View from within site (see map for location)



Current View



Restored View

For inspection purposes only  
Consent of copyright owner required for any other use

Photograph 18 – View from within site (see map for location)



Current View



Restored View



Photograph 19 – View from within site (see map for location)



Current View



Restored View

Photograph 20 – View from within site (see map for location)



Current View



Restored View



Photograph 21 – View from within site (see map for location)



Current View



Restored View

For inspection purposes only.  
Consent of copyright owner required for any other use.

Photograph 22 – View from within site (see map for location)



Current View



Restored View



Photograph 23 – View from within site (see map for location)



Current View



Restored View

Photograph 24 – View from within site (see map for location)



Current View



Restored View