



- NOTES**
1. Verifying Dimensions.  
The contractor shall verify dimensions against such other drawings or site conditions as pertain to this part of the work.
  2. Existing Services.  
Any information concerning the location of existing services indicated on this drawing is intended for general guidance only. It shall be the responsibility of the contractor to determine and verify the exact horizontal and vertical alignment of all cables, pipes, etc. (both underground and overhead) before work commences.
  3. Issue of Drawings.  
Hard copies, dwf and pdf will form a controlled issue of the drawing. All other formats (dwg, dxf etc.) are deemed to be an uncontrolled issue and any work carried out based on these files is at the recipient's own risk. RPS will not accept any responsibility for any errors arising from the use of these files, either by human error by the recipient, listing of un-dimensioned measurements, compatibility issues with the recipient's software, and any errors arising when these files are used to aid the recipient's drawing production, or setting out on site.
  4. Keys:

rev	amendments	drawn	date

**Keys:**

- 50mm Ø MDPE Header (Supply) Pipes
- 80mm Ø MDPE Header (Supply) Pipes [between 90mm HDPE main and LDC1B/2B]
- 150mm Ø nb uPVC pipe [between ICW Break chamber and connected to inlets to ICWs]
- 90mm Ø HDPE PE100 Pumping Main
- 50mm Ø MDPE Pumping Main from leachate tower to 90mm HDPE pumping main with 100mm bed and surround
- 150mm Ø HDPE Outfall Pipe [To Drainage Ditch] with 100mm bedding and surround
- Existing 63mm Ø HDPE Outfall Pipe [To Collection Sump]
- Existing Lined French Drain (Runoff Drainage)
- Existing Leachate Toe Drain - Collecting Leachate from beneath landfill cap and discharging to Collection Sump

**Client**



**Comhairle Contae Dhún na nGall Donegal County Council**

**Project**  
Churchtown License Review

**Title**  
Monitoring Locations

Drawing Status	Sheet Size	Drawing Scale	
Preliminary	A3	1:2000	
Drawing Number		Rev	
IBR1015 /104		-	
Project Leader	Drawn By	Date	Initial Review
DD	AMB	May - 2017	AMcG

UMK - Job:IBR1015 Churchtown License Review\IBR1015 Drawings\IBR1015 104 Churchtown Landfill Site Monitoring Locations.dwg - 22/05/2017 15:36:52