

Si Points at Waterstown Park (Surveyed by Focus Surveys Ltd) 12-05-15

Point Name	Easting	Northing	Ground/Casing Level	Inner Pipe Level
BH4	708611.737	735429.952	35.53	35.51
BH5	708566.952	735438.623	36.32	36.23
BH6	708475.907	735440.656	39.95	39.84
BH7	708352.612	735480.784	40.57	40.48
BH8	708292.398	735564.385	36.50	36.4
BH9	708127.188	735615.758	34.48	34.39
BH10	708351.183	735781.882	17.21	17.12
BH11	708486.755	735620.935	29.15	29.06
BH12	708591.433	735622.898	24.38	24.29
MW7	708102.733	735802.625	16.46	16.39
MW7A	708143.394	735806.790	17.84	N/A
MW9	708397.340	735812.108	16.11	16.08
MW9A	708512.915	735851.549	10.14	N/A
MW10	708640.809	735738.096	14.49	14.46
MW10A	708617.435	735727.395	14.98	N/A
MW11	708733.944	735636.470	16.17	16.15
MW12	708720.681	735480.296	25.63	25.59
TP7	708713.448	735677.390	15.06	N/A
TP8	708726.457	735601.319	19.02	N/A
TP9	708726.019	735508.760	24.87	N/A
TP10	708725.447	735454.935	26.42	N/A
TP11	708165.700	735678.921	23.84	N/A
TP12	708279.620	735636.265	32.20	N/A
TP13	708460.495	735549.701	32.95	N/A
TP14	708533.774	735647.944	25.54	N/A
TP15	708600.439	735458.934	34.54	N/A
TP16	708435.900	735667.238	28.45	N/A
TP17	708725.465	735419.254	28.37	N/A

For inspection purposes only. Consent of copyright owner required for any other use.