



- LEGEND**
- ★ D Approximate Dust Monitoring Locations
  - MW Groundwater Monitoring Locations
  - N Noise Monitoring Locations
  - SW Surface water Monitoring Locations
  - ☾ Surface Water Features Within 500m
  - Site Boundary
  - Lands in Ownership by Applicant
  - Water and Electrical Supply to wheelwash location
  - Breakthrough from the existing quarry
  - - - Extraction and Filling Area
  - 5 metre wide Topsoil Storage Bund

**Notes -**

All locations given are approximate

Contours and levels provided are based on survey levels obtained by Coastway Surveys in 2017 - levels within existing quarry will have altered since date of this survey

Route of Access Road will amend as the quarry is extended and filled

Dust Monitoring locations may be moved by agreement with EPA and Wexford County Council as quarry is extended and filled.

Storage areas, weighbridge, site office and car park locations are approximate only

**enviroguide** consulting  
 3D Core C, Block 71, The Plaza, Park West, Dublin 12 D12F9TN  
 www.enviroguide.ie  
 info@enviroguide.ie  
 +353 (0)1 5654730

**ROB HEALY & ASSOCIATES**  
 LAND SURVEYING & ENGINEERING SERVICES  
 Unit 11 Westpoint Business Park, Clonard, Wexford  
 E-mail: rhealy@enviroguide.ie  
 Tel: (086) 3808706

<b>CLIENT:</b> MSK Silversands LTD.			
<b>LOCATION:</b> Ballinrooaun, Screen, Enniscorthy, Wexford			
<b>DRAWING TITLE:</b> Site Plan			
<b>SCALE:</b> 1:5000@A3	<b>DATE:</b> 08/08/2019	<b>DRN BY:</b> RH	<b>DRG NO:</b> Plan - 1