



- LEGEND**
- ★ D Approximate Dust Monitoring Locations
  - MW Groundwater Monitoring Locations
  - N Noise Monitoring Locations
  - SW Surface water Monitoring Locations
  - ☁ Surface Water Features Within 500m
  - Site Boundary
  - Lands in Ownership by Applicant
  - Water and Electrical Supply to wheelwash location
  - Breakthrough from the existing quarry
  - - - Extraction and Filling Area
  - 5 metre wide Topsoil Storage Bund

**Notes -**

All locations given are approximate

Contours and levels provided are based on survey levels obtained by Coastway Surveys in 2017 - levels within existing quarry will have altered since date of this survey

Route of Access Road will amend as the quarry is extended and filled

Dust Monitoring locations may be moved by agreement with EPA and Wexford County Council as quarry is extended and filled.

Storage areas, weighbridge, site office and car park locations are approximate only

**enviroguide consulting**

3D Core C, Block 71, The Plaza, Park West, Dublin 12 D12F9TN  
 www.enviroguide.ie  
 info@enviroguide.ie  
 +353 (0)1 5654730

**ROB HEALY & ASSOCIATES**  
 LAND SURVEYING & ENGINEERING SERVICES

Unit 11 Westpoint Business Park, Clonard, Wexford  
 E-mail: rhealy@enviroguide.ie  
 Tel: (086) 3808706

**ENGINEERS IRELAND**

<b>CLIENT:</b> MSK Silversands LTD.			
<b>LOCATION:</b> Ballinarooaun, Screen, Enniscorthy, Wexford			
<b>DRAWING TITLE:</b> Site Plan			
<b>SCALE:</b> 1:2500@A3	<b>DATE:</b> 08/08/2019	<b>DRN BY:</b> RH	<b>DRG NO:</b> Plan - 2

230634.1654

209799.0637

208971.8836

229924.6777

300

352

38

23

300

200

(E.D. Co. Wick) le Ellis

Quarantine Area

Weighbridge  
Site Office  
Car Park

D1

D2

D3

D4

MW1

MW2

MW3

MW4

Imported Soil Storage Area 0.100 hectares 3500 cu.m.

Screened Material Area 0.155 hectares 3000 cu.m.

Subsoil Storage Area 0.525 hectares

Storage Area within Existing quarry

Breakthrough from the existing quarry

Extraction and Filling Area

5 metre wide Topsoil Storage Bund