

PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:
Monaghan Co. Council

Site Location: Killycard

Project Number: P1655

Photo No.
9

Date:
12/06/18

Description:

Northern section of site, looking westwards



Photo No.
10

Date:
12/06/18

Description:

Waste material protruding from northern boundary adjacent to surface water ditch



PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:
Monaghan Co. Council

Site Location: Killycard

Project Number: P1655

Photo No.
11

Date:
12/06/18

Description:

Exposed waste material at western boundary of Corrinshigo Lake



Photo No.
12

Date:
12/06/18

Description:

Exposed waste material at western boundary of Corrinshigo lake



PHOTOGRAPHIC LOG

Consultants in Engineering
and Environmental Sciences

www.fehilytimoney.ie



Client Name:
Monaghan Co. Council

Site Location: Killycard

Project Number: P1655

Photo No.
13

Date:
12/06/18

Description:

Waste material protruding from soil surface



Photo No.
14

Date:
12/06/18

Description:

Waste material protruding from soil surface

