SECTION C. SITE DETAILS

SECTION C:	SITE DETAILS	
SECITOI1 CI		

C.1. Site Location

Name:	Galway C.C. Roads Depot
Address*:	Tullyvogheen
	Clifden
	Co. Galway
Tel:	
Fax:	
e-mail:	

^{*} Include any townland

Attachment C.1. should contain appropriately scaled drawings or maps (≤A3) showing the site location in the context of its surroundings and clearly highlighting the site boundary.

C.2. Unauthorised Waste Sites Register (Section 22) – Site Boundary and Site Code

State that the site has been recorded on the online Section 22 Register at www.epa.ie/uwsr and that the boundary drawn of the site represents the full extent of the site.

Following the Tier 2 and Tier 3 site investigations, if the extent of the site is determined to be greater or less than that initially recorded in the Section 22 Register, then the boundary must be amended accordingly.



Provide the unique code assigned to the site in the Section 22 Register

Site Code	S22-02237

Provide a six-digit National Grid Reference for the site location

Grid	67631.14	E	251185.815	N
Reference				

Confirm the following waste details entered on the Section 22 Register:

• State which type of waste activity was carried out at the site (please check):

Disposal	X
Recovery	

State the principal waste type at the site (please check):

C&D	
Industrial	
Municipal	X
Pre 1977	
Unknown	

State any additional waste types at the site (please check):

Agriculture	
C&D	X
Dredged Soil	
ELV/Scrap Metal	
Hazardous	
Industrial	
Mining	
Municipal	
Municipal Sludge	
Other	

State whether or not hazardous waste is present at the site (please check):

Present on site

		. ~
Present on site		2 Pills
Not present on site	X	dorner,
	20	0

Estimate the total quantity of waste at the site (tonnes):

<u> </u>			
Total waste quantity	205,000 TONNES		
at the site:	203,000 TOTALES		

Provide the start date and end date of waste activities at the site:

Start date	1984
End date	1999


C.3. Risk Category


State which Risk Category* the site belongs to (please check):


Class A (High)	X
Class B (Moderate)	
Class C (Low)	


^{*}See Chapter 4, Code of Practice (as required under Section 6(2) of the Regulations)

















C.4. Land Use

Provide details of the current use of the land on which the closed landfill is situate.

Attachment C.4. should detail this information or refer to the specific section of the risk assessment documentation where this information is contained.

See attached Plate C4.1 which shows an aerial photograph taken on 29th September, 2019 of the Former Tullyvogheen Landfill taken at 30m elevation from the northwest of the site facing southwest showing Galway C.C. roads depot area to the west of the site and grassed/capped area to the middle and east of the site. Please note that the site is no longer used for fire drill training by Galway Fire Brigade.

C.5. Types and quantities of waste deposited


Provide details of the types and estimated quantities of waste deposited at the site.

Attachment C.5. should detail this information or refer to the specific section of the risk assessment documentation where this information is contained.

In addition, state whether the types and quantities of waste which have been recorded on the online Section 22 Register at www.epa.ie/uwsr represent the final estimated quantities at the site.

Following the Tier 2 and Tier 3 site investigations, if the type and

recorded in the Section 22 Register, then these quantities must be amended accordingly.



See Section 1.2 of Tier 2 Site Investigation & Tier 3 GQRA Assessment of Tullyvogheen Landfill Report.



Plate C4.1. Aerial photograph taken on 29th September, 2019 of Former Tullyvogheen Landfill taken at 30m elevation from the northwest of the site facing southwest showing Galway C.C. roads depot area to the west of the site and grassed/capped area to the middle and east of thee site