

# Certificate of Authorisation Application Form

Waste Management (Certification of Historic Unlicensed Waste Disposal and Recovery Activity)  
Regulations, 2008

Site: Greenhills, Athy, Co. Kildare

S22-02507

## Attachment C.1

Site Location Maps

A suite of 19no. relevant drawings can be found in the Environment Risk Assessment Report.

*For inspection purposes only.  
Consent of copyright owner required for any other use.*




**Legend**

- Site Boundary
- Groundwater Well Locations
- Leachate Well Locations
- Trial Pit Locations

**ADR**  
MALONE O'REGAN  
ENVIRONMENTAL SERVICES LTD

Ground Floor – Unit 3  
Bracken Business Park  
Bracken Road, Sandyford  
Dublin 18, D18V32Y  
Tel: +353- 1- 567 76 55  
Email: enviro@mores.ie

Client <b>Kildare Co Co</b>			Drawing			
Job <b>Environmental Risk Assessment</b>			<b>Site investigation Locations</b>			
Job No. E1506	Drawing Number 15	Status Draft	Sht. Size A3	Scale 1:5,000	Date June 19	Drawn NM



Base Map courtesy of Bing Map (Microsoft® Bing™ Maps)



**Legend**

- Site Location
- OSI Rivers
- OSI Streams



© OpenStreetMap Contributors 2019

**MDR**  
MALONE O'BEGAN  
ENVIRONMENTAL

Ground Floor - Unit 3,  
Bracken Business Park,  
Bracken Road, Sandystown,  
Dublin 18, D18 V32Y  
Tel: +353 1 907 7855  
Email: env@mdr.ie

Client			Description			
Kildare Co Co			Hydrological Receptors Map			
Job			Environmental Risk Assessment			
Job Number	Drawing Number	Status	Str. Size	Scale	Date	Drawn
E1506	8	DRAFT	A3	1:15,000	May 19	UD