

PHOTOGRAPHIC LOG



Client Name: Mayo County Council

Site Location: Claremorris

Project Number: P2348

Photo No.

Date:
16/01/20

1

Description:

View of Site



Photo No.

Date:

2

16/01/20

Description:

Railway located running along the northern boundary of the site



PHOTOGRAPHIC LOG



Client Name: Mayo County Council

Site Location: Claremorris

Project Number: P2348

Photo No.
3

Date:
16/01/20

Description:
Wetland



Photo No.
4

Date:
16/01/20

Description:
Surface waste



PHOTOGRAPHIC LOG



Client Name: Mayo County Council

Site Location: Claremorris

Project Number: P2348

Photo No.
5

Date:
16/01/20

Description:
Overview of site



Photo No.
6

Date:
16/01/20

Description:
Kilbeg-Malone stream which crosses the site on the North-East corner.



PHOTOGRAPHIC LOG



Client Name: Mayo County Council

Site Location: Claremorris

Project Number: P2348

Photo No.

Date:

7

16/01/20

Description:

Leachate seepage



Photo No.

Date:

8

16/01/20

Description:

Surface waste



PHOTOGRAPHIC LOG



Client Name: Mayo County Council

Site Location: Claremorris

Project Number: P2348

Photo No.

Date:

9

16/01/20

Description:

BH0X located xxxxx.



Photo No.

Date:

10

16/01/20

Description:

Surface waste

