

C.4. Land Use

Provide details of the current use of the land on which the closed landfill is situate.

Attachment C.4. should detail this information or refer to the specific section of the risk assessment documentation where this information is contained.

See attached Plate C4.1 which shows an aerial photograph taken on 29th June, 2020 of the Former Shore Road Landfill taken at 30m elevation from the western end of the site facing eastwards showing the basketball court, public playground and wastewater pumping station in the foreground (i.e. to the west of the site). It is proposed to convert the site to a public park for Clifden Town.

C.5. Types and quantities of waste deposited

Provide details of the types and estimated quantities of waste deposited at the site.

Attachment C.5. should detail this information or refer to the specific section of the risk assessment documentation where this information is contained.

In addition, state whether the types and quantities of waste which have been recorded on the online Section 22 Register at www.epa.ie/uwsr represent the final estimated quantities at the site.

Following the Tier 2 and Tier 3 site investigations, if the type and quantities of waste are determined to be greater or less than that initially recorded in the Section 22 Register, then these quantities must be amended accordingly.

Finalised estimate of waste types and quantities entered in Section 22 Register
--



For inspection purposes only.
Consent of copyright owner required for any other use.

Table C5.1 Breakdown of Old Waste Landfilled at Shore Road Historic Landfill from 1920s to 1960s and Recent Construction and Demoliation Waste Landfilled in 2018

WASTE TYPE	SOURCE	LANDFILL OPERATOR	YEAR(S) DEPOSITED	AREA (m ²)	AVERAGE DEPTH (m)	VOLUME(m ³)	DENSITY (kg/l)	WEIGHT (tonnes)
Old Domestic Waste	Clifden town & environs	Galway C.C.	1920S-1960s	1721	4	6884	1.5	10326
Old Construction & Demolition Waste	Clifden town & environs	Galway C.C.	1920S-1960s	1572	4	6288	1.8	11318
New Construction & Demolition	Demolition of Clifden Community School	Illegal landfilling	2018	1156	1.34	1549	1.8	2788

*For inspection purposes only.
Consent of copyright owner required for any other use.*

For inspection purposes only.
Consent of copyright owner required for any other use.



Plate C4.1. Aerial photograph taken on the 29th June, 2020 of the Former Shore Road Historic Landfill taken at 30m elevation from the western end of the site facing eastwards showing the public basketball court, playground and wastewater pumping station in the foreground.

For inspection purposes only.
Consent of copyright owner required for any other use.