




**FEHILY
TIMONEY**

**CONSULTANTS IN ENGINEERING,
ENVIRONMENTAL SCIENCE & PLANNING**

APPENDIX 4

Site Walkover Checklist and
Photographic Log

*For inspection purposes only.
Consent of copyright owner required for any other use.*



Appendix

Site Walkover Photographs

*For inspection purposes only.
Consent of copyright owner required for any other use.*



PHOTOGRAPHIC LOG



Client Name: Kerry County Council

Site Location: Listowel

Project Number: P1766

Photo No.

Date:
23/10/19

1

Description:

BH02 within Garden of Europe



Photo No.

Date:

2

23/10/19

Description:

SW01 (upstream)



PHOTOGRAPHIC LOG



Client Name: Kerry County Council

Site Location: Listowel

Project Number: P1766

Photo No.

Date:

3

23/10/19

Description:

SW02 (downstream), close to bridge



Photo No.

Date:

4

23/10/19

Description:

BH01 within council work yard, south of site boundary



PHOTOGRAPHIC LOG



Client Name: Kerry County Council

Site Location: Listowel

Project Number: P1766

Photo No.

Date:

5

14/02/19

Description:

Leachate see page on council work yard



For inspection purposes only.
Consent of copyright owner required for any other use.

Photo No.

Date:

6

14/02/2019

Description:

Leachate seepage



PHOTOGRAPHIC LOG



Client Name: Kerry County Council

Site Location: Listowel

Project Number: P1766

Photo No.

Date:

7

14/02/2019

Description:

Surface waste



For inspection purposes only.
Consent of copyright owner required for any other use.

Photo No.

Date:

8

14/02/2019

Description:

Surface waste



Walkover Survey Checklist

Historic Kerry Landfills - Listowel

Walkover Survey Checklist		
Information	Checked	Comment (include distances from Site Boundary)
1. What is the current land use?	✓	Garden of Europe – area of cultural heritage
2. What are the neighbouring land uses?	✓	Agricultural land (east), pitches (west), forestry and residential areas (north) and River Feale (south)
3. What is the size of the site?	✓	Circa 1.01 ha
4. What is the topography?	✓	Relatively flat, slight incline from south to north
5. Are there potential receptors (if yes, give details)?	✓	Nearby residences, groundwater, River Feale
Houses		
Surface water features (if yes, distance and direction of flow)?	✓	Yes, River Feale 20m south of site boundary flowing in an east – west direction
Any wetland or protected areas?	✓	No
Public water supplies?	✓	Not identified
Private wells?	✓	Possible local usage
Services?	✓	None
Other buildings?	✓	None on-site
Other?	✓	Monuments scattered throughout site
6. Are there any potential sources of contamination (if yes, give details)?	✓	Buried waste
Surface waste (if yes, what type)?	✓	None noted
Surface ponding of leachate	✓	None present
Leachate seepage	✓	None noted
Landfill gas odours	✓	None noted
7. Are there any outfalls to surface water? (If yes, are there discharges and what is the nature of the discharge?)	✓	No evidence
8. Are there any signs of impact on the environment? (if yes, take photographic evidence)	✓	None noted.
Vegetation die off, bare ground	✓	None noted
Leachate seepages	✓	None noted
Odours	✓	None Noted
Litter	✓	None
Gas bubbling through water	✓	None noted
Signs of settlement	✓	No
Subsidence, water logged areas	✓	No evidence

Walkover Survey Checklist

Historic Kerry Landfills - Listowel

Walkover Survey Checklist		
Information	Checked	Comment (include distances from Site Boundary)
Drainage or hydraulic issues	✓	None noted
Downstream water quality appears poorer than upstream water quality	✓	No
9. Are there any indications of remedial measures? (Provide details)	✓	No
Capping	✓	No waste evident
Landfill gas collection	✓	No
Leachate collection	✓	No
10. Describe fences and security features (if any)	✓	Site surrounded by wooden fencing and ditches
Any other relevant information?		

For inspection purposes only.
Consent of copyright owner required for any other use.