

ATTACHMENT 4.3-1 LANDFILL EMISSIONS

Not applicable.

Ballynacarrick Landfill Site operated from c.1980 until closure in July 2012 due to the capacity of the facility being exhausted. The site has been progressively restored on a phased basis in accordance with the Waste Licence (Ref: W0024-04) since 2004 with the final restoration being completed in 2013. No further waste will be accepted at the facility for recovery or disposal. Groundwater, surface water, leachate and landfill gas is currently being monitored quarterly for parameters as listed in Waste Licence W0062-04.