## ATTACHMENT 4.3 CAPACITY FOR EACH RECOVERY AND DISPOSAL ACTIVITY

Not applicable.

Churchtown Landfill Site operated from c.1987 until closure in August 2000. No waste will be accepted at the facility for recovery or disposal. The site is unlined but has been restored with a cap and leachate treatment system (willow and Integrated Constructed Wetland) installed.

Section 29(2A) of the Waste Management Act 1996 as amended states that it shall be the duty of waste producers and holders to ensure that waste undergoes recovery operations in accordance with sections 21A (Waste Hierarchy) and 32(1) of the Waste Management Act. The leachate treatment system (willow and Integrated Constructed Wetland) was installed at the landfill facility as agreed with Office of Environmental Enforcement of the EPA to provide an effective, sustainable and self-sufficient leachate management and treatment system which eliminates the requirement to export leachate (19 07 03 landfill leachate other than those mentioned in 19 07 02) from the site to Letterkenny WwTW for final treatment. The effluent from the leachate treatment system is discharged to the adjacent waterbody. Further details are provided in Attachment 4.4 and Site Operational Report