



## EPA RIVER QUALITY SURVEYS: BIOLOGICAL

Biotic indices ("Q Values") reflect average water quality at any location as follows:

Q Value*	WFD Status	Pollution Status	Condition **
Q5, Q4-5	High	Unpolluted	Satisfactory
Q4	Good	Unpolluted	Satisfactory
Q3-4	Moderate	Slightly polluted	Unsatisfactory
Q3, Q2-3	Poor	Moderately polluted	Unsatisfactory
Q2, Q1-2,	Bad	Seriously polluted	Unsatisfactory

\* These Values are based primarily on the relative proportions of pollution sensitive to tolerant macroinvertebrates (the young stages of insects primarily but also snails, worms, shrimps etc.) resident at a river site. The intermediate values (Q1-2, 2-3, 3-4 etc.) denote transitional conditions. The scheme mainly reflects the effects of organic pollution (i.e. de-oxygenation and eutrophication) but where a toxic effect is apparent or suspected the suffix '0' is added to the biotic index (e.g. Q1/0, 2/0 or 3/0). An asterisk after the Q value (e.g. Q3\*) indicates something worthy of special attention, typically heavy siltation of the substratum.

\*\* "Condition" refers to the likelihood of interference with beneficial or potential beneficial uses.

Also presented is a description of the exact location surveyed with relevant OS Grid Reference, WFD river water body code and relevant Local Authority.

## Hydrometric Area 25

Name	Code
ANNACARRIGA	25A05
ANNAGH (TIPPERARY)	25A02
ARDCLOONY	25A03
ARDCRONY STREAM	25A06
ARDGREGANE STREAM	25A04
AYLE	25A07
BALLINLOUGH STREAM	25B15
BALLINTOTTY	25B01
BALLYFINBOY	25B02
BALLYNACARRIG	25B18
BALLYNAGRENIA STREAM	25B16
BALLYQUIVEEN STREAM	25B30
BALLYTEIGE (CLARE)	25B17
BARNACULLIA STREAM	25B14
BILBOA	25B03
BLACK (BALLYBOY)	25B04
BLACKWATER (CLARE)	25B06
BLACKWATER (SHANNONBRIDGE)	25B27
BLEACH	25B07
BOORA	25B08
BOW	25B10
BREAGHMORE	25B12

Name	Code
BRIDGETOWN (CLARE)	25B23
BROSNA	25B09
BUNOW	25B25
CAHERNAHALLIA	25C01
CAMCOR	25C02
CAPPAGH (GALWAY)	25C03
CAPPAWHITE STREAM	25C10
CARRIGAHORIG STREAM	25C16
CASTLE-ERKIN STREAM	25C17
CAUTEEN	25C04
CLAREEN (NENAGH)	25C11
CLAREEN STREAM/FUARAWN	25C13
CLODIAGH (TULLAMORE)	25C06
CLOGHAUN	25C07
COOS	25C08
CORRA	25C09
COUNTY (LAOIS/OFFALY)	25C21
DEAD	25D01
DERRAINY	25D10
Derreenboy Stream	25D18
DERRYCOOLY STREAM	25D13
DOLLA	25D08
DOON STREAM	25D03
DOONANE	25D04

Name	Code
DRUMANDOORA	25D06
DRUMKEARY STREAM	25D11
DUNIRY	25D07
DURROW ABBEY STREAM	25D12
DYSART STREAM (LOUGH ENNELL)	25D05
EYRECOURT STREAM	25E01
GAGEBOROUGH	25G01
GARRYARD STREAM	25G15
GLASHACLOONARAVEELA	25G02
GLENBONNIV	25G07
GLENFELLY STREAM	25G21
GLENOMRA WOOD STREAM	25G12
GOLDEN GROVE STREAM	25G06
GORRAGH	25G09
GORTNAGERAGH	25G03
GORTNAGOWNA	25G13
GRANEY (SHANNON)	25G04
GRANGE (TIPPERARY)	25G10
GROODY	25G05
INCH (BILBOA)	25I01
KEELOGE STREAM	25K14
KILCOMIN STREAM	25K15
KILCROW	25K01
KILFADDA CASTLE STREAM	25K07

Name	Code
KILLEENGARRIFF	25K02
KILMASTULLA	25K04
LISDUFF (KILCROW)	25L06
LISDUFF STREAM (SHANNON)	25L07
LITTLE (CLOGHAN)	25L01
LITTLE BROSNA	25L02
LORRHA STREAM	25L05
LOWER VILLAGE TRIB	25L08
MILL STREAM (TYNAGH)	25M06
MOATE STREAM	25M05
MONAGHANSTOWN	25M01
MOUNTRICE	25M03
MULKEAR (LIMERICK)	25M04
NENAGH	25N01
NEWPORT (TIPPERARY)	25N02
NEWTOWN	25N03
OLLATRIM	25O01
PALLAS	25P01
POLLAGH STREAM (BROSNA)	25P05
POPE'S	25P03
RAPEMILLS	25R01
ROCK (BIRR)	25R02
Roscomore Stream	25R05
ROSTOLLUS STREAM	25R03

Name	Code
SCARRIFF STREAM	25S08
SHANNON (LOWER)	25S01
Sheever Lough Stream	25S99
SHINRONE STREAM	25S11
SILVER (KILCORMAC)	25S02
SILVER (TULLAMORE)	25S03
SMALL (TIPPERARY)	25S05
SYONAN CASTLE STREAM	25S04
TOEM STREAM	25T05
TULLAMORE	25T03
WOODFORD (GALWAY)	25W01
YELLOW (KILMASTULLA)	25Y01
YOUGHAL (TIPPERARY)	25Y02

**ANNACARRIGA****25A05**

Date Surveyed (last survey year only): 31/12/88

**Biological Quality Rating (Q Values)**

Station Code	1982	1984	1988
RS25A050100	4-5	5	4-5

Most Recent Assessment:

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25A050100	ANNACARRIGA - First Bridge u/s Lough Derg	IE_SH_25A050100	167939	177528	Clare County Council

**ANNAGH (TIPPERARY)****25A02**

Date Surveyed (last survey year only): 08/08/21, 31/07/21

**Biological Quality Rating (Q Values)**

Station Code	1979	1983	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021
RS25A020040				5	5	4-5	4-5	4	4	4	4	4	4
RS25A020050			5										
RS25A020100	5	5	5	4-5	4-5	4-5	4-5	4-5	4	4	4	4	4
RS25A020160			5										
RS25A020200	5	5	5	5	4-5	4-5	4	4-5	4-5	4	4-5	4	4-5
RS25A020250			5										
RS25A020300	5	5	5	5	4-5	4-5	4	4-5	4	4-5	4	4-5	4-5
RS25A020400			5										
RS25A020500				4	4	4-5	4-5						

**Most Recent Assessment:**

The Annagh (Tipperary) was in satisfactory condition throughout in 2021. The upper two sites were in Good ecological condition. Charlotte's Bridge returned to High ecological condition and this condition was maintained at Ahacrossaun Bridge.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25A020040	Br u/s Inchinmathea Br	IE_SH_25A020100	184962	162061	Tipperary County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25A020050	ANNAGH (TIPPERARY) - Inchinamathea Br	IE_SH_25A020100	182796	162424	Tipperary County Council
RS25A020100	Tooreenbrien Br	IE_SH_25A020100	181440	160215	Tipperary County Council
RS25A020160	ANNAGH (TIPPERARY) - Ford NW of Vauchluce Cott	IE_SH_25A020200	181358	160132	Tipperary County Council
RS25A020200	Charlotte's Bridge	IE_SH_25A020200	175089	159186	Tipperary County Council
RS25A020250	ANNAGH (TIPPERARY) - Clare Br	IE_SH_25A020300	173077	159873	Limerick City & County Council
RS25A020300	Ahacrossaun Bridge	IE_SH_25A020300	171862	159339	Limerick City & County Council
RS25A020400	ANNAGH (TIPPERARY) - Ford d/s Ahacrossaun Br	IE_SH_25K020150	171607	159040	Limerick City & County Council
RS25A020500	ANNAGH (TIPPERARY) - 100m u/s Annagh Br	IE_SH_25K020150	168474	158040	Limerick City & County Council

**ARDCLOONY****25A03**

Date Surveyed (last survey year only): 17/08/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1988	1994	1996	1999	2002	2005	2009	2012	2014	2017	2018	2019	2021	2023
RS25A030100		5		5	5	5	5	5	5	4-5	5	4-5	5	4	4*
RS25A030200	5	5	4-5												

**Most Recent Assessment:**

While the species present in the invertebrate fauna at the single site assessed in 2023 are indicative of Good ecological quality, deposits of sand and gravel covering the substratum where there was previously cobble has changed the nature of the habitat.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25A030100	Ballycorney Br (at Mill View)	IE_SH_25A030100	166966	170668	Clare County Council
RS25A030200	ARDCLOONY - Ardclony Br (nr Ardclony Ho)	IE_SH_25A030100	167582	169148	Clare County Council

**ARDCRONY STREAM****25A06**

Date Surveyed (last survey year only): 01/08/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2018	2021	2025
RS25A060500	4	3-4	3-4	4-5	3-4	3	3-4	4	3-4	3-4	3-4	3

**Most Recent Assessment:**

The Ardcrony Stream declined from its previous Moderate condition (in 2014, 2018 and 2021) to Poor condition when surveyed in August 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25A060500	Br. u/s Ballyfinboy River	IE_SH_25A060500	190251	193337	Tipperary County Council

**ARDGREGANE STREAM****25A04**

Date Surveyed (last survey year only): 10/09/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25A040100			3	3-4	3*	3-4		3-4	3-4	3	3	3
RS25A040200	3											
RS25A040400	3	3	3-4	4	3-4*	3-4	3-4	3-4*	3-4	3-4	3-4	3-4

**Most Recent Assessment:**

No change was noted in the Ardgregane Stream with the upper site at Poor and the lower at Moderate ecological condition when surveyed in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25A040100	ARDGREGANE STREAM - Br S of Grallagh	IE_SH_25A040100	183293	178357	Tipperary County Council
RS25A040200	ARDGREGANE STREAM - Hogan's Pass Br	IE_SH_25A040400	182974	180345	Tipperary County Council
RS25A040400	Bridge W. of Ardgregane	IE_SH_25A040400	181152	181299	Tipperary County Council

**AYLE****25A07**

Date Surveyed (last survey year only): 10/07/23

**Biological Quality Rating (Q Values)**

Station Code	1988	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023
RS25A070300	5	5	4-5	5								
RS25A070400	5	5	4-5	4-5	4-5	4	4-5	4-5	4-5	4-5	4-5	4-5

**Most Recent Assessment:**

High ecological quality maintained at the single site assessed.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25A070300	AYLE - Ayle Br	IE_SH_25A070400	153896	184737	Clare County Council
RS25A070400	Br u/s Cloghaun R confl	IE_SH_25A070400	154357	183466	Clare County Council

**BALLINLOUGH STREAM**

**25B15**

Date Surveyed (last survey year only): 08/07/23, 09/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1989	1993	1996	1999	2003	2009	2012	2014	2017	2018	2019	2021	2023
RS25B150050		5	4-5	4-5	4	4-5	4-5	4-5	4	4	4		4	3-4
RS25B150100		4	4											
RS25B150200				4-5	4									
RS25B150300		5				4-5	4-5	4-5	4-5	4-5	4	4	4	3-4
RS25B150400			4-5											
RS25B150500	4	4-5	4	3	4-5	4-5	4-5	4-5	4-5	4-5			4	4-5

**Most Recent Assessment:**

While the Ballinlough Stream remained in satisfactory condition at the lower site (Station 0500), the other two sites were found to have declined to Moderate ecological quality in July 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B150050	Second Br u/s Ballin Lough	IE_SH_25B150300	167853	202291	Galway County Council
RS25B150100	BALLINLOUGH STREAM - First Br d/s Ballin Lough	IE_SH_25B150300	168948	202651	Galway County Council
RS25B150200	BALLINLOUGH STREAM - Br E of Silverstream House	IE_SH_25B150300	171922	202989	Galway County Council

---

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B150300	Br E. of Ballynagar House	IE_SH_25B150300	173194	204084	Galway County Council
RS25B150400	BALLINLOUGH STREAM - Br N of Brookville	IE_SH_25B150500	173800	204115	Galway County Council
RS25B150500	Bridge u/s Cappagh River	IE_SH_25B150500	176844	205031	Galway County Council

**BALLINTOTTY****25B01**

Date Surveyed (last survey year only): 09/09/25, 10/09/25

**Biological Quality Rating (Q Values)**

Station Code	1981	1984	1986	1987	1988	1993	2002	2005	2008	2012	2015	2018	2021	2025
RS25B010040						4								
RS25B010100	3-4		4	4		3	3	3-4	3-4	4	4	4	4	4
RS25B010110		1	3-4	2	3									
RS25B010200	3-4	3	3	3										
RS25B010240						3	3-4	3-4		4*				
RS25B010300	3-4	3	4-5	3-4		3	3-4	3-4	3-4	4	4	3-4	3-4	3

**Most Recent Assessment:**

The upper site (0100) on the Ballintotty River remained in Good condition but the lower site (0300) declined to Poor condition when surveyed in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B010040	BALLINTOTTY - Br NW of Moanmore	IE_SH_25B010100	198000	176709	Tipperary County Council
RS25B010100	Phillabreen Br	IE_SH_25B010100	197074	177647	Tipperary County Council
RS25B010110	BALLINTOTTY - Br 0.1km d/s Phillabreen Br	IE_SH_25B010300	196912	177397	Tipperary County Council
RS25B010200	BALLINTOTTY - Br NE of Coolderry	IE_SH_25B010300	194562	177607	Tipperary County Council

---

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B010240	BALLINTOTTY - Br SE of Norwood	IE_SH_25B010300	192776	177777	Tipperary County Council
RS25B010300	Br. U/s Ollatrim R. Confluence	IE_SH_25B010300	189494	179034	Tipperary County Council

**BALLYFINBOY****25B02**

Date Surveyed (last survey year only): 01/08/23

**Biological Quality Rating (Q Values)**

Station Code	1971	1974	1978	1982	1984	1987	1993	1996	1999	2002	2005	2008	2011	2014	2015	2017	2021	2023
RS25B020070						4-5	4	3-4	3-4	3-4	3-4	3-4	3-4	3-4		3-4	3-4	3-4
RS25B020100	5	4	4	4	3	3	3-4	3	3-4	3-4*	4		4		3-4	3	3-4	3*
RS25B020150						3												
RS25B020200				4-5	3	3-4												
RS25B020250										4	4-5	3-4						
RS25B020300			4-5	4-5	3-4	4-5	4	3	4			3-4	3-4	4		3-4	3-4	3-4
RS25B020400	5	4-5	4-5	4		4	4	Dry	4	3-4	3-4	3	3-4	3-4	3-4	3-4	3-4	3-4
RS25B020550						3-4	3-4	3	3-4	3	3		3-4		3-4		3-4	
RS25B020600	4	4	3-4	4	4	3-4	4	3	3-4	3-4	3-4	3-4	3-4	3-4		3-4	3-4	3-4
RS25B020700	5	3-4	4	4-5		4	3-4	3	3-4	4	4		4	3-4		3-4	3-4	3-4
RS25B020750					4	4	3										3-4	
RS25B020800	4	4	4	4-5		4	3-4	3	4	3-4	3-4	4	3-4	3-4		3-4	3-4	3-4

**Most Recent Assessment:**

The Ballyfinboy continues to be in an unsatisfactory ecological condition in August 2023. Moderate ecological quality was recorded at six of the seven stations surveyed while the remaining station (0100) declined from Moderate to Poor ecological quality and an \* was assigned due with heavy siltation of the substrate. Calcification and compaction were again noted at three sites 0400, 0600 and 0800.

### Station Details

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B020070	Br NW of Ballintemple Ho	IE_SH_25B020070	200141	184890	Offaly County Council
RS25B020100	BALLYFINBOY - Townfield Br	IE_SH_25B020100	198196	186877	Tipperary County Council
RS25B020150	BALLYFINBOY - Knockearl Br	IE_SH_25B020300	197197	187573	Offaly County Council
RS25B020200	BALLYFINBOY - Br W of Cloughjordan	IE_SH_25B020300	196668	187962	Tipperary County Council
RS25B020250	Br S of Modreeny	IE_SH_25B020300	195967	188860	Tipperary County Council
RS25B020300	Modreeny bridge (North)	IE_SH_25B020300	195903	189397	Tipperary County Council
RS25B020400	BALLYFINBOY - Ballynavin Br	IE_SH_25B020550	193823	191715	Tipperary County Council
RS25B020550	BALLYFINBOY - Br in Borrisokane	IE_SH_25B020550	191527	194101	Tipperary County Council
RS25B020600	Br. Near Ballyfinboy Castle	IE_SH_25B020600	189708	193700	Tipperary County Council
RS25B020700	BALLYFINBOY - Ballyhooney Br	IE_SH_25B020700	186245	196033	Tipperary County Council
RS25B020750	BALLYFINBOY - Ballinderry Br	IE_SH_25B020800	185115	196823	Tipperary County Council
RS25B020800	Br just u/s L Derg	IE_SH_25B020800	183808	198046	Tipperary County Council

**BALLYNACARRIG****25B18**

Date Surveyed (last survey year only): 29/09/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25B180100	4	4	3-4	4	3-4	3-4	3-4	3-4	3-4	3-4	4	3-4

**Most Recent Assessment:**

The improvement to Good ecological quality observed in 2021 was not maintained and the Ballynacarrig declined back to Moderate in September 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B180100	Br u/s Silver R confl	IE_SH_25B180100	227544	213661	Laois County Council

**BALLYNAGRENIA STREAM****25B16**

Date Surveyed (last survey year only): 13/06/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25B160400	3	3	2	3	3/0	3	3-4*	3*	3-4	3-4	3*	3*
RS25B160600	4	4	3	3-4	3	3-4	4	4	4	4	4	

**Most Recent Assessment:**

The macroinvertebrate fauna continues to indicate poor ecological conditions in the upper reaches (0400) of the Ballynagrenia Stream in June 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B160400	Br S of Rose Mount	IE_SH_25B160400	223309	242067	Westmeath County Council
RS25B160600	Br nr Newtown	IE_SH_25B160600	224687	238735	Offaly County Council

**BALLYQUIVEEN STREAM****25B30**

Date Surveyed (last survey year only): 12/09/24

**Biological Quality Rating (Q Values)**

Station Code	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2024
RS25B300300	3-4	3-4	3-4	4	4	4	4	4	4	3-4	4*

**Most Recent Assessment:**

A welcomed return to good ecological conditions in the Ballyquiveen stream in 2024 despite cattle poaching as a noted pressure at this site.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B300300	Br u/s Nenagh R confl	IE_SH_25N010500	191058	173499	Tipperary County Council

**BALLYTEIGE (CLARE)****25B17**

Date Surveyed (last survey year only): 31/12/88

**Biological Quality Rating (Q Values)**

Station Code	1984	1988
RS25B170200	5	5
RS25B170300		5

**Most Recent Assessment:****Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B170200	BALLYTEIGE (CLARE) - Ballyteige Bridge	IE_SH_25S012500	167055	175057	Clare County Council
RS25B170300	BALLYTEIGE (CLARE) - Bridge d/s Ballyteige Bridge	IE_SH_25S012500	167295	174467	Clare County Council

**BARNACULLIA STREAM****25B14**

Date Surveyed (last survey year only): 07/07/23

**Biological Quality Rating (Q Values)**

Station Code	1982	1983	1984	1986	1987	1988	1993	1996	2003	2009	2012	2014	2017	2021	2023
RS25B140100	1/0	1/0	2/0	3/0	2/0	2-3/0	3/0	3/0	2/0	3/0	3-4/0	3-4/0	3-4	3	3-4

**Most Recent Assessment:**

While still in unsatisfactory condition, the Barnacullia has improved slightly compared to 2021. It is now at Moderate ecological quality.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B140100	Bridge at Barnacullia	IE_SH_25L060400	175170	213464	Galway County Council

**BILBOA**

**25B03**

Date Surveyed (last survey year only): 02/09/25, 03/09/25, 13/08/25

**Biological Quality Rating (Q Values)**

Station Code	1979	1983	1987	1989	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2024	2025
RS25B030004				4	3-4	4	3									
RS25B030010			4		3-4	3-4	3-4	3-4	4	4-5*	4*	4	3-4	3-4		4
RS25B030020			4-5		3-4											
RS25B030028				4	4	3-4	4	4								
RS25B030050					4-5	4-5										
RS25B030080			5		5	4-5	5	4-5	4-5	4-5	4-5	4-5	4-5	4	4-5	
RS25B030100	5	5	5													
RS25B030200	5	5	5													
RS25B030300	5	5	5		5	4	4-5	3-4	4	4	4	4-5	4-5	4		4-5
RS25B030400	5	5	5													
RS25B030500			5		4-5	4		3-4*	3-4	3-4	4	4	4	4		4

**Most Recent Assessment:**

The upper site on the Bilboa (0010) improved to good ecological condition for the first time since 2015. Site 0300 returned to high condition while the lowermost site (0500) remained in Good condition when surveyed in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B030004	Br SE of Loughbrack	IE_SH_25B030080	191240	159714	Tipperary County Council
RS25B030010	Bridge in Kilcommon	IE_SH_25B030080	190144	160128	Tipperary County Council
RS25B030020	BILBOA - Anglesey Br	IE_SH_25B030080	188977	158697	Tipperary County Council
RS25B030028	Br u/s Main R confl	IE_SH_25B030080	188879	158580	Tipperary County Council
RS25B030050	BILBOA - SE of Cappaharoe	IE_SH_25B030080	185158	157486	Tipperary County Council
RS25B030080	Br u/s Blackboy Br - Bilboa b	IE_SH_25B030080	181568	151885	Limerick City & County Council
RS25B030100	BILBOA - Blackboy Br	IE_SH_25B030500	179937	151496	Limerick City & County Council
RS25B030200	BILBOA - Doon Rd Br Cappamore (K7)	IE_SH_25B030500	177576	151507	Limerick City & County Council
RS25B030300	Br 1.5 km d/s Cappamore	IE_SH_25B030500	177973	150469	Limerick City & County Council
RS25B030400	BILBOA - New Br u/s Dead R	IE_SH_25B030500	178701	148905	Limerick City & County Council
RS25B030500	Pullagh u/s Dead R	IE_SH_25B030500	177681	147881	Limerick City & County Council

**BLACK (BALLYBOY)****25B04**

Date Surveyed (last survey year only): 18/08/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2006	2011	2014	2018	2021	2025
RS25B040200	4-5	4	4-5	4-5	4	4	4	3-4	4	3-4

**Most Recent Assessment:**

The Black (Ballyboy) declined from good to moderate ecological condition in 2025. The snail *Potamopyrgus* dominated the fauna. The substratum had a significant amount of Phormidium-dominated mats and the dissolved oxygen saturation was low at 72%.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B040200	BLACK (BALLYBOY) - Br 0.5 km u/s Silver R	IE_SH_25S020200	224734	212734	Offaly County Council

**BLACKWATER (CLARE)****25B06**

Date Surveyed (last survey year only): 17/08/23, 18/08/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1986	1988	1994	1996	1999	2002	2006	2009	2012	2014	2017	2018	2019	2021	2023
RS25B060030			5	5		4	3-4*	4								
RS25B060060					4											
RS25B060080			5													
RS25B060100		4														
RS25B060120			4-5	5	4	4	4-5	4-5	4-5	4-5	4*	4-5	4	4	4	4
RS25B060180			3	3-4	4-5	4										
RS25B060250	4	4		4-5	4-5	4-5	4	4	4-5	4	4	4			3-4	4
RS25B060300		3	4													

**Most Recent Assessment:**

Satisfactory, Good ecological quality at both sites in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B060030	BLACKWATER (CLARE) - Br SE of Cappanagh	IE_SH_25B060120	156432	165468	Clare County Council
RS25B060060	BLACKWATER (CLARE) - 1st Br u/s Trough Br	IE_SH_25B060120	157783	165354	Clare County Council

---

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B060080	BLACKWATER (CLARE) - Trough Br	IE_SH_25B060120	158467	165584	Clare County Council
RS25B060100	BLACKWATER (CLARE) - Killaly's Br	IE_SH_25B060120	159060	165624	Clare County Council
RS25B060120	Br d/s Killaly's Br	IE_SH_25B060120	159373	165547	Clare County Council
RS25B060180	BLACKWATER (CLARE) - Br nr Blackwater Mills	IE_SH_25B060250	159415	162424	Clare County Council
RS25B060250	Br SW of Mt St Catherine	IE_SH_25B060250	161194	161531	Clare County Council
RS25B060300	BLACKWATER (CLARE) - Gilloge Bridge	IE_SH_25S012600	161347	159458	Clare County Council

**BLACKWATER (SHANNONBRIDGE)****25B27**

Date Surveyed (last survey year only): 17/08/23, 18/08/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1988	1993	1996	1999	2002	2005	2009	2011	2014	2017	2021	2023
RS25B270110		4-5	4	4	4	3-4	4	3-4	4	3-4	4	2-3	3*
RS25B270200	3	3	3-4	3-4	3	3-4*	4	4	4	4	4	3-4	3

**Most Recent Assessment:**

Both stations monitored on the Blackwater (Shannonbridge) were in unsatisfactory condition. Poor ecological quality continues at station 0110 with almost stagnant flow, very low dissolved oxygen (4.07mg/l) and an \* was assigned due to very heavily sedimented substrate. Conditions declined to poor further downstream at 0200 with very slow flows, low dissolved oxygen and heavy siltation were apparent.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B270110	Br ENE of Derryharry	IE_SH_25B270110	206453	228097	Offaly County Council
RS25B270200	Blackwater Br	IE_SH_25B270200	201589	223447	Offaly County Council

**BLEACH****25B07**

Date Surveyed (last survey year only): 09/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1989	1993	1996	1999	2003	2006	2009	2012	2014	2017	2018	2021	2022	2023
RS25B070100		5		4-5	4-5	4-5			4	3	4		4		3-4
RS25B070190							4-5	4-5	4-5	3-4	4	4	4	4	4
RS25B070200	5	5	5	4-5	4-5	4-5			4-5	4	4	4	4	4	4

**Most Recent Assessment:**

While Good ecological quality was maintained in 2023 at the lower two sites on the Bleach, There was a disappointing decline to Moderate quality at Corlea Bridge (Station 0100).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B070100	Corlea Bridge	IE_SH_25B070100	160378	196288	Clare County Council
RS25B070190	Br u/s Bleach Br	IE_SH_25B070200	157304	195900	Clare County Council
RS25B070200	BLEACH - Bleach Br	IE_SH_25B070200	157027	195708	Clare County Council

**BOORA**

**25B08**

Date Surveyed (last survey year only): 18/08/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1987	1988	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25B080100	3	3		3-4	4	3	3-4*	3-4		3-4*	3-4	3-4	3-4	3-4
RS25B080200		2/0	4	3-4	4	3-4	3-4*	4	3	4	4	4	3-4	3*

**Most Recent Assessment:**

Both stations monitored on the Boora were in unsatisfactory condition in August 2023. Moderate ecological condition continues at the upper station (0100) while the lower station (0200) declined further to Poor ecological condition. Flow here was very slow and low dissolved oxygen (5.51mg/l) was noted on the day of survey. In addition the substrate was dominated with deep sinking silts and an \* was assigned.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B080100	Gorteen Br	IE_SH_25B080100	216573	220284	Offaly County Council
RS25B080200	Aqueduct u/s Brosna R	IE_SH_25B080200	216758	223673	Offaly County Council

**BOW****25B10**

Date Surveyed (last survey year only): 16/08/23, 17/08/23

**Biological Quality Rating (Q Values)**

Station Code	1975	1980	1984	1988	1993	1996	1999	2002	2006	2009	2012	2014	2017	2021	2023
RS25B100100		5	5	5	5	5	5	4-5		4	4-5	4-5	4-5	4	4-5
RS25B100200	5	5	4-5	5	5	3-4	4-5	4-5	4-5	5	4-5	4-5	4-5	4	4-5

**Most Recent Assessment:**

There has been a welcome return to High ecological quality at both survey sites on the Bow River, as indicated by the composition of the invertebrate communities. However, the banks at the lower site (0200) are still overgrown with Japanese knotweed and Himalayan balsam.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B100100	Bow River Br	IE_SH_25B100200	166586	187050	Clare County Council
RS25B100200	Cloontymweenagh Br	IE_SH_25B100200	167438	185121	Clare County Council

**BREAGHMORE**

**25B12**

Date Surveyed (last survey year only): 12/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1989	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25B120020		5	5	5	4-5	4	4-5	4	4*	4*	4*	4-5	4
RS25B120080		5	4	4	3-4	4	4-5	4-5	4-5	4-5	4-5	4-5	4
RS25B120200	5												
RS25B120400	5		4-5	4-5	4	4	4	4-5	5	4-5	4-5	4-5	4-5

**Most Recent Assessment:**

Unfortunately the improvement to High ecological quality observed in the upper station (0020) in 2021 was not maintained with a decline to Good in July 2023. The next station (0080) also declined from High to Good ecological quality with heavy siltation noted. Only the lower station (0400) maintained its High ecological quality.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B120020	Br nr Roscmore Cott	IE_SH_25B120020	216525	197728	Offaly County Council
RS25B120080	Just u/s Main R confl	IE_SH_25B120400	214779	202223	Offaly County Council
RS25B120200	BREAGHMORE - Ford u/s Loftus Br	IE_SH_25B120400	214777	202269	Offaly County Council
RS25B120400	Breaghmore Br	IE_SH_25B120400	214553	203565	Offaly County Council

**BRIDGETOWN (CLARE)****25B23**

Date Surveyed (last survey year only): 10/07/23

**Biological Quality Rating (Q Values)**

Station Code	2009	2012	2014	2017	2021	2023
RS25B230100	3-4	3-4	4	4	4	3-4

**Most Recent Assessment:**

A disappointing decline to unsatisfactory condition was recorded in the Bridgetown in 2023, with only sufficient pollution sensitive invertebrates present for Moderate ecological quality to be assigned.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B230100	Fahy Br	IE_SH_25B230100	164093	167829	Clare County Council

**BROSNA**

**25B09**

Date Surveyed (last survey year only): 05/09/24

**Biological Quality Rating (Q Values)**

Station Code	1971	1974	1978	1982	1984	1987	1993	1996	1999	2002	2005	2007	2008	2009	2010	2011	2014	2017	2019	2021	2023	2024
RS25B090010					3-4	2-3	3															
RS25B090040					3-4	2-3	3	3	3	3	3		3			3	3	3		3		3
RS25B090100	1	1	1-2	1-2	2-3	2	2-3	3	2-3	2	1-2	2	2	2	3-4	3	3	3		3		3
RS25B090200	4-5	4	3-4	4	4	4	3-4	3-4	3	3-4	3-4					3	3-4	3-4		3-4	3-4	
RS25B090250					4	4-5	3-4	3-4	4	3-4	3		3-4			3-4	3-4	3-4	3-4	3-4	3-4	3-4
RS25B090400	4-5	4-5	4-5	4	4-5	4	3-4	3-4	4	3	3					4	4	4		4		
RS25B090420					4-5	4-5																
RS25B090450				4-5		4	4	3-4	4	3	3-4		3-4			4	4	4		4		
RS25B090500	4-5	4-5	4-5			4	4	3-4	3-4	3-4	3		3-4									
RS25B090600	3-4	4	4	4	4	4	4		3-4				3-4			3-4	3-4	4		3-4	3-4	
RS25B090700	4	4	4	4-5	4	4-5	3-4	3	3-4	3-4	4					4	4	4		4		
RS25B090760						4	3-4	4	4	4	3-4		3-4			4	4	4		4	3-4	
RS25B090800	4-5	4-5	4		4	5	3*	3-4	3	3-4*	4-5					4	4	4		3-4	4	
RS25B090950					4-5	4-5	4	4	4	4-5	4-5		4			4	4-5	4		3-4	4	
RS25B091000	4-5	5	4-5	4	3-4	4-5	3-4	3-4	3-4	3	3					3-4*		3-4		3-4	3-4	
RS25B091100			4-5													4		4		4	4	

**Most Recent Assessment:**

The Brosna was unsatisfactory poor ecological condition at the two sites 0040 (Mullingar: Indust Est Br) and 0100 (Butler's Br) surveyed in September 2024. Instream siltation was noted along the slow flowing stretch of site 0100. Both sites remained at Q3 and followed this trend since the 2011 assessments.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B090010	BROSNA - Mullingar- Canal Crossing	IE_SH_25B090006	244164	253380	Westmeath County Council
RS25B090040	Mullingar: Indust Est Br	IE_SH_25B090006	243787	252380	Westmeath County Council
RS25B090100	Butler's Br	IE_SH_25B090100	2241982	250177	Westmeath County Council
RS25B090200	BROSNA - Newell's Br	IE_SH_25B090200	238323	242320	Westmeath County Council
RS25B090250	Br at Ballynagore	IE_SH_25B090250	235671	239669	Westmeath County Council
RS25B090400	BROSNA - Just d/s Kilbeggan Br	IE_SH_25B090400	233182	235467	Westmeath County Council
RS25B090420	BROSNA - Glebe Ho d/s Kilbeggan	IE_SH_25B090450	232794	234784	Westmeath County Council
RS25B090450	Br near Lismoynty	IE_SH_25B090450	229559	233197	Offaly County Council
RS25B090500	Lehinch u/s Clara	IE_SH_25B090600	228302	232316	Offaly County Council
RS25B090600	Bolart Br	IE_SH_25B090600	223380	232468	Offaly County Council
RS25B090700	Ballycumber Br	IE_SH_25B090710	221109	230608	Offaly County Council
RS25B090760	0.5km NW of Pollagh	IE_SH_25B090761	219030	225714	Offaly County Council
RS25B090800	BROSNA - Br nr Kilcolgan	IE_SH_25B090800	214983	223751	Offaly County Council
RS25B090950	Ferbane Br	IE_SH_25B090950	211539	224405	Offaly County Council
RS25B091000	Bellmount d/s Ferbane	IE_SH_25B091000	207385	222255	Offaly County Council
RS25B091100	Clonony Br (NW of canal)	IE_SH_25B091200	204774	220887	Offaly County Council

**BUNOW****25B25**

Date Surveyed (last survey year only): 02/08/23, 14/08/23

**Biological Quality Rating (Q Values)**

Station Code	1971	1973	1975	1977	1979	1981	1984	1986	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25B250050										4-5	4-5	3-4	4	4	4					
RS25B250100								4-5	4-5											
RS25B250250								3	3	3	3	3-4	3	3-4		4	3-4	3-4	3-4	3-4
RS25B250400	2-3	2-3	2-3	2-3	3	3-4	3	3	3	3	3	3	3	3-4	3-4	4	3-4	3-4	3-4	3-4

**Most Recent Assessment:**

The Bunow continues to be in unsatisfactory condition with Moderate ecological quality assigned to both stations in August 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25B250050	Br S of Killavilla Ho	IE_SH_25B250100	217085	191131	Offaly County Council
RS25B250100	BUNOW - Br 2 km E of Roscrea (N of Verdanthill)	IE_SH_25B250100	215713	189785	Tipperary County Council
RS25B250250	BUNOW - Br d/s Roscrea Railway Sta	IE_SH_25B250400	213748	189553	Tipperary County Council
RS25B250400	Bunow Br	IE_SH_25B250400	210980	190189	Tipperary County Council

**CAHERNAHALLIA****25C01**

Date Surveyed (last survey year only): 12/08/25, 13/08/25

**Biological Quality Rating (Q Values)**

Station Code	1979	1983	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25C010010			4	3-4	4	3-4								
RS25C010025		4	5				3-4	4-5	4	4	4-5	4	4	4
RS25C010060		4-5	5	4	5	4-5								
RS25C010100	4	4	4-5	3-4	4	4	4	4	3-4*	4	4-5	4	4	4

**Most Recent Assessment:**

The macroinvertebrate fauna indicated continuing good ecological conditions on the Cahernahallia in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C010010	CAHERNAHALLIA - Br N of Foildarg	IE_SH_25C010025	188144	152363	Tipperary County Council
RS25C010025	Glengar Br WNW of Leugh	IE_SH_25C010025	186712	151044	Tipperary County Council
RS25C010060	CAHERNAHALLIA - Cahernahallia Br	IE_SH_25C010100	185340	149162	Limerick City & County Council
RS25C010100	Br u/s Dead R confl	IE_SH_25C010100	182791	148245	Limerick City & County Council

**CAMCOR****25C02**

Date Surveyed (last survey year only): 19/08/25

**Biological Quality Rating (Q Values)**

Station Code	1977	1981	1985	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2018	2019	2020	2021	2023	2025
RS25C020100		5	5	5	5	5	5	5	5	4-5	4-5	5	5	5	4-5	4-5	4-5	4-5	
RS25C020150			5	5													5		5
RS25C020200	5	5	5	5															
RS25C020300		5	5	5	4	3-4	4	3-4	3-4	3-4*	4	4-5	4-5				4-5	4-5	
RS25C020400		5	5	5															
RS25C020500	5	5	5	5	5	4	4	4	4	4*	4	4-5	4-5				4-5	4-5	
RS25C020600	5	5	5	4-5	4	4-5	3-4	4	4		4		4				4	4	
RS25C020650			5	5															
RS25C020700	5	5	5	5	4	3-4	4	4	3-4	3-4	4	4	4				4	4	

**Most Recent Assessment:**

One site (0150) was sampled on the Camcor in 2025. This site is marked with a 'Blue Dot' sign. While the invertebrates were of a very high quality the site has been damaged by severe bank works.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C020100	Ford u/s Coneyburrow Br	IE_SH_25C020100	221228	204313	Offaly County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C020150	0150 - Br SE Moneygunneen House	IE_SH_25C020300	220004	206248	Offaly County Council
RS25C020200	CAMCOR - Ford 1.5km N of Kinnitty	IE_SH_25C020300	219082	206580	Offaly County Council
RS25C020300	Drumcullen Br	IE_SH_25C020300	217751	206147	Offaly County Council
RS25C020400	CAMCOR - Carrig Br	IE_SH_25C020500	216034	205837	Offaly County Council
RS25C020500	Br S of Killyon	IE_SH_25C020500	213222	205402	Offaly County Council
RS25C020600	CAMCOR - Br S of Clonbrone	IE_SH_25C020600	209923	204255	Offaly County Council
RS25C020650	CAMCOR - Br near Syngfield	IE_SH_25C020700	208089	204626	Offaly County Council
RS25C020700	Br at Elm Grove Birr	IE_SH_25C020700	206673	204937	Offaly County Council

**CAPPAGH (GALWAY)**

**25C03**

Date Surveyed (last survey year only): 08/07/23, 09/07/23

**Biological Quality Rating (Q Values)**

Station Code	1975	1979	1983	1987	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023
RS25C030070							4-5								
RS25C030100				4-5	4	3-4	3-4	3-4	4	4-5	4	4-5	4-5	4	4
RS25C030200	4	4	4	3-4	4	3	4	4	4						
RS25C030300			4	4	4	4	4-5								
RS25C030400			4	4	4			4-5	3-4	3-4	4	3-4	3-4	3-4	3-4
RS25C030500	4-5	5	4	4	4	4	4								

**Most Recent Assessment:**

No change in the ecological quality of the Cappagh since 2021: Good at Metal Bridge and Moderate at Cappagh Bridge.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C030070	CAPPAGH (GALWAY) - Br u/s Metal Br	IE_SH_25C030100	167644	211189	Galway County Council
RS25C030100	Metal Bridge	IE_SH_25C030100	168212	211284	Galway County Council
RS25C030200	CAPPAGH (GALWAY) - Bridge W. of Duniry Village	IE_SH_25C030500	172359	209345	Galway County Council
RS25C030300	CAPPAGH (GALWAY) - 1.5 km N.E. of Abbey	IE_SH_25C030500	175323	207112	Galway County Council

---

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C030400	Cappagh Bridge	IE_SH_25C030500	177210	205620	Galway County Council
RS25C030500	Cloonmoylan Bridge	IE_SH_25C030500	178770	204690	Galway County Council

**CAPPAWHITE STREAM****25C10**

Date Surveyed (last survey year only): 12/08/25

**Biological Quality Rating (Q Values)**

Station Code	1979	1981	1983	1985	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25C100200	3-4	3-4	3	3	3	3	3	3	3	3	3	3-4	3	3	3	3
RS25C100300					3	3	3	3	3*	4		4				

**Most Recent Assessment:**

No change was recorded in the Cappawhite Stream with conditions continuing Poor in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C100200	Gortandrum Br	IE_SH_25C100200	187959	146163	Tipperary County Council
RS25C100300	CAPPAWHITE STREAM - Ayle Br NE of Clonbrick	IE_SH_25D010200	185778	144701	Tipperary County Council

**CARRIGAHORIG STREAM**

**25C16**

Date Surveyed (last survey year only): 10/08/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25C160300	4	3-4	3-4	4	3	4		3-4		3-4	3-4	3-4
RS25C160500	3-4	3-4	3-4	3-4	3	3-4	3-4	3-4	3	3	3	3

**Most Recent Assessment:**

The Carrigahorig continues to be in unsatisfactory condition in August 2023. Substrate at both stations monitored was calcareous and compacted. Moderate ecological quality was assigned at the upper station (0300) with low dissolved oxygen (6.43mg/l) and a fair bit of filamentous green algae (FGA) noted on the day. At station 0500 macroinvertebrate diversity was very low with moderate coverage of FGA and Poor ecological quality was assigned.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C160300	CARRIGAHORIG STREAM - Br S of Milford Ho	IE_SH_25C160500	191511	198809	Tipperary County Council
RS25C160500	Br at Carrigahorig	IE_SH_25C160500	190422	201490	Tipperary County Council

**CASTLE-ERKIN STREAM****25C17**

Date Surveyed (last survey year only): 30/07/87

**Biological Quality Rating (Q Values)**

Station Code	1987
RS25C170100	3-4
RS25C170200	3-4

**Most Recent Assessment:****Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C170100	Bridge S.W. of Dromkeen Ho	IE_SH_25M040200	170523	146451	Limerick City & County Council
RS25C170200	Bridge near Castle Erkin	IE_SH_25M040200	170521	148557	Limerick City & County Council

**CAUTEEN**

**25C04**

Date Surveyed (last survey year only): 12/08/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25C040200	3	3	3	3	3-4							
RS25C040300				3								
RS25C040400				2								
RS25C040500	3	3	3	3	3-4	3-4	3-4	3-4	3-4	3-4	3	3-4

**Most Recent Assessment:**

The Cauteen River improved from Poor to Moderate condition at the site sampled (0500) in August 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C040200	CAUTEEN - Br u/s Gortnacoolagh Br	IE_SH_25C040500	189603	144070	Tipperary County Council
RS25C040300	CAUTEEN - Gortnacoolagh Br	IE_SH_25C040500	189157	144375	Tipperary County Council
RS25C040400	CAUTEEN - 1st Br u/s Cauteen Br	IE_SH_25C040500	188653	144327	Tipperary County Council
RS25C040500	Cauteen Br (d/s side)	IE_SH_25C040500	187556	143565	Tipperary County Council

**CLAREEN (NENAGH)****25C11**

Date Surveyed (last survey year only): 11/09/25

**Biological Quality Rating (Q Values)**

Station Code	2023	2024	2025
RS25C110090	3		
RS25C110300	2	1*	1

**Most Recent Assessment:**

The Clareen was sampled upstream of its confluence with the River Nenagh (qv). The depauperate macroinvertebrate fauna continues to indicate bad ecological conditions again in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C110090	Upstream of WWTP	IE_SH_25N010700	186794	178332	Tipperary County Council
RS25C110300	CLAREEN (NENAGH) - u/s Nenagh River confluence	IE_SH_25N010700	187358	179286	Tipperary County Council

**CLAREEN STREAM/FUARAWN****25C13**

Date Surveyed (last survey year only): 02/08/23, 13/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25C130100								4	3-4	3-4	3-4	3-4
RS25C130200	3	4	3-4	4	4	3-4	3-4	3-4	3-4	3-4	4	3-4
RS25C130400	3	3-4										
RS25C130600	3-4	3-4	3-4	4	4	4	3	3-4	3-4	3	3-4	3-4

**Most Recent Assessment:**

With a decline from Good to Moderate at station 0200 all stations on the Clareen/Fuarawn are now in unsatisfactory condition. Substrate at stations 0200 and 0600 was very calcareous and heavy macrophyte growth (*Apium nodiflorum*) almost entirely dominated the channel at station 0200.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C130100	CLAREEN STREAM/FUARAWN - Br W of Aghancon	IE_SH_25C130200	213895	198216	Offaly County Council
RS25C130200	Br W of Grange Ho	IE_SH_25C130200	213998	200870	Offaly County Council
RS25C130400	CLAREEN STREAM/FUARAWN - Br N of Clareen	IE_SH_25C130600	213899	202625	Offaly County Council
RS25C130600	Br nr Kilmaine Ho	IE_SH_25C130600	212496	204163	Offaly County Council

**CLODIAGH (TULLAMORE)****25C06**

Date Surveyed (last survey year only): 03/08/23, 08/08/23, 09/08/23, 11/07/23

**Biological Quality Rating (Q Values)**

Station Code	1971	1973	1974	1975	1978	1982	1984	1987	1993	1996	1999	2002	2005	2007	2008	2011	2014	2017	2021	2023
RS25C060050								5			4-5		4-5			4-5	4-5	4-5	4-5	4
RS25C060090												4-5			4				4	
RS25C060100					5	5		5	5	4-5	2/0		3			4-5	4-5	4-5	4	4-5
RS25C060200					1/0	4	5	5												
RS25C060220								3	3-4	3	3*	3-4*	1	2	4	4*	4-5	4-5	4-5	4
RS25C060250							4-5	4	4-5	4	4-5	4-5	4-5		4	4-5	4-5	4-5		
RS25C060300					5	5	5	4-5	5	4-5	4-5	4-5	4-5			4	4-5	4-5	4-5	4-5
RS25C060330								4-5	4-5											
RS25C060340										4	4	4	4		4	4	4	4	4	3-4
RS25C060360							4-5	5	4-5											
RS25C060400	5		5	5	5	4-5	4-5	4-5	4-5	4	3-4	3-4	3-4		3-4	4	4	4	4	3-4
RS25C060500		4	4	4		4	3-4	3-4	4	3-4	3-4	3-4	4		3-4	4	4	4	3-4	3-4

**Most Recent Assessment:**

Satisfactory conditions continue at only four of the seven sites surveyed in the Clodiagh (Tullamore) in July 2023. The uppermost station (0050) unfortunately declined from high to good ecological quality while the next station (0100) improved from good to high. A decline was also noted at station 0220 from high to good ecological condition with bank works (vegetation clearance, sediment mounds) noted along the right bank. High ecological conditions continued at station 0300. An unwelcome decline in the pollution sensitive macroinvertebrates and increased dominance of pollution tolerant taxa indicated a decline from good to moderate ecological conditions at Annamoe Bridge (0340) and Bridge north of Clonagh (0400) with Moderate ecological conditions persisting at Rahan (0500).

### Station Details

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C060050	CLODIAGH (TULLAMORE) - Br NW of Scarroon	IE_SH_25C060220	229620	209513	Laois County Council
RS25C060090	u/s Clonaslee Waterworks	IE_SH_25C060220	231718	210672	Laois County Council
RS25C060100	CLODIAGH (TULLAMORE) - Just u/s Clonaslee Br	IE_SH_25C060220	231758	210872	Laois County Council
RS25C060200	CLODIAGH (TULLAMORE) - 0.8km d/s Clonaslee Br	IE_SH_25C060220	232019	211621	Laois County Council
RS25C060220	Just u/s Gorrageh R confl	IE_SH_25C060220	232268	212083	Laois County Council
RS25C060250	Br ENE of Brockagh ( E of Annaghmore L)	IE_SH_25C060300	233176	214606	Laois County Council
RS25C060300	CLODIAGH (TULLAMORE) - Gorteen Br	IE_SH_25C060300	234034	217145	Offaly County Council
RS25C060330	CLODIAGH (TULLAMORE) - Clonad Br	IE_SH_25C060340	231344	219330	Offaly County Council
RS25C060340	Br N of Clonagh	IE_SH_25C060340	230844	220936	Offaly County Council
RS25C060360	0360 - Mucklagh Br	IE_SH_25C060360	231038	222773	Offaly County Council
RS25C060400	Annamoe Br	IE_SH_25C060500	229098	224383	Offaly County Council
RS25C060500	Br at Rahan	IE_SH_25C060500	225665	225646	Offaly County Council

**CLOGHAUN****25C07**

Date Surveyed (last survey year only): 17/07/23, 24/08/23

**Biological Quality Rating (Q Values)**

Station Code	1986	1987	1989	1993	1996	1999	2003	2006	2009	2012	2014	2017	2019	2021	2023
RS25C070100			5												
RS25C070200			5	4	4-5	4-5	4-5	4	4	4-5	4-5	4	4	4	4
RS25C070300				4											
RS25C070400			4-5		4-5	4	4	4	4	4-5	4	4		4	4
RS25C070500			4		3-4	3-4	3-4								
RS25C070600	4	4-5	5	4-5	3-4	4	3-4	3-4	4	4	4	4		4	4

**Most Recent Assessment:**

Good ecological quality maintained throughout the Cloghaun in 2023

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C070100	CLOGHAUN - Br at Glendree	IE_SH_25C070200	151104	185895	Clare County Council
RS25C070200	Br N of Gortacummer	IE_SH_25C070200	152072	183951	Clare County Council
RS25C070300	CLOGHAUN - Garrauncam Br	IE_SH_25C070400	153188	183397	Clare County Council
RS25C070400	Annaghneal Br	IE_SH_25C070400	155740	182683	Clare County Council

---

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C070500	CLOGHAUN - Cloghaun Br	IE_SH_25C070600	157589	182781	Clare County Council
RS25C070600	Core Br	IE_SH_25C070600	159749	184399	Clare County Council

**COOS**

**25C08**

Date Surveyed (last survey year only): 09/07/23

**Biological Quality Rating (Q Values)**

Station Code	1975	1979	1984	1987	1988	1989	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023
RS25C080010								5	4-5	4	4	4	4	4	4	4	4
RS25C080020							4-5										
RS25C080040						5											
RS25C080100	5	5	4-5	4			4										
RS25C080180				4			4-5	3									
RS25C080200	3-4	5	4	1	2	3	2-3		1	3	4	4	4	3	3	3	3-4

**Most Recent Assessment:**

Good ecological quality was maintained at the upper site on the Coos (Station 0010) in 2023, while at the lower site (Station 0200) there was a slight improvement to Moderate ecological quality from the Poor quality recorded in 2014, 2017 and 2021.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C080010	Br N of Boleynabrone	IE_SH_25C080200	170713	194697	Galway County Council
RS25C080020	COOS - Ford NE of Boleynabrone	IE_SH_25C080200	171260	194571	Galway County Council
RS25C080040	COOS - Ford WNW of Tooreeny	IE_SH_25C080200	173569	194019	Galway County Council
RS25C080100	COOS - Br u/s L Derg	IE_SH_25C080200	174793	193936	Galway County Council

---

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C080180	COOS - Br N of Tooreeny	IE_SH_25C080200	174832	193952	Galway County Council
RS25C080200	Br NE of Tooreeny (Tooreeny Br)	IE_SH_25C080200	175164	193819	Galway County Council

**CORRA****25C09**

Date Surveyed (last survey year only): 16/08/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1989	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023
RS25C090100		5		5	5	4-5			3	4	4	4	4-5
RS25C090400	5	5	5	5	5	5	4-5	4-5	4-5	4-5	4-5	4	4-5

**Most Recent Assessment:**

A welcome return to High ecological quality is seen at both sites on the Corra in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C090100	CORRA - Br SE of Corrakyle	IE_SH_25C090100	161507	191274	Clare County Council
RS25C090400	Gortaderry Br	IE_SH_25C090400	159529	189318	Clare County Council

**COUNTY (LAOIS/OFFALY)****25C21**

Date Surveyed (last survey year only): 13/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2011	2014	2017	2021	2022	2023
RS25C210100						4-5	4-5	4-5	4-5	4-5	4
RS25C210200	4-5	4-5	4	4-5	4-5						

**Most Recent Assessment:**

While the County (Laois/Offaly) remains in satisfactory conditions a decline from High to Good ecological quality was observed. In 2022 it was noted that there were less sensitive taxa than previous years and this was noted again in 2023 with low diversity and very low density of pollution sensitive taxa.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25C210100	COUNTY (LAOIS/OFFALY) - Br u/s County Br	IE_SH_25S020200	224454	209445	Offaly County Council
RS25C210200	COUNTY (LAOIS/OFFALY) - County Br	IE_SH_25S020200	224091	209980	Laois County Council

**DEAD****25D01**

Date Surveyed (last survey year only): 12/08/25

**Biological Quality Rating (Q Values)**

Station Code	1979	1981	1985	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2024	2025
RS25D010100	3-4	4	3-4	3	3	3	3	3-4*	3	3-4	3-4	3-4	3-4	3	3-4	
RS25D010150			3-4	3-4												
RS25D010200	4-5	4-5	4	4	3-4	3	3	3-4*	3-4	3-4	3-4	4	3-4	3*		3-4
RS25D010300		4-5	4	4-5												

**Most Recent Assessment:**

One site was sampled on the Dead River (0200) in mid August 2025. An improvement from poor to moderate conditions was noted.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D010100	Pope's Bridge	IE_SH_25D010100	185598	143761	Tipperary County Council
RS25D010150	DEAD - Longford Br	IE_SH_25D010200	184202	145575	Tipperary County Council
RS25D010200	Derraun Br	IE_SH_25D010200	182477	146324	Limerick City & County Council
RS25D010300	DEAD - 0.2km d/s Br S of Pullagh u/s Bilboa R confl	IE_SH_25M040100	177752	147805	Limerick City & County Council

**DERRAINY****25D10**

Date Surveyed (last survey year only): 24/08/23

**Biological Quality Rating (Q Values)**

Station Code	1982	1984	1987	1988	1993	1996	1999	2002	2006	2009	2012	2014	2017	2019	2021	2023
RS25D100100		5		5	4											
RS25D100200	4-5	3-4	5		5	4	4	4-5	4-5	4-5	3-4*	4	4	4	4	4

**Most Recent Assessment:**

Good ecological conditions were maintained in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D100100	DERRAINY - Derroran Br	IE_SH_25D100200	171488	190376	Clare County Council
RS25D100200	Br at Derrainy	IE_SH_25D100200	174980	191550	Clare County Council

**Derreenboy Stream****25D18**

Date Surveyed (last survey year only): 02/10/03

**Biological Quality Rating (Q Values)**

Station Code	1989	1993	1996	1999	2003
RS25D180980	3-4	4	2-3	4	2-3

Most Recent Assessment:

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D180980	Was RS25K010009, Br u/s Main Channel (at 209' mark)	IE_SH_25K010060	180415	218614	Galway County Council

**DERRYCOOLY STREAM**

**25D13**

Date Surveyed (last survey year only): 22/08/02

**Biological Quality Rating (Q Values)**

Station Code	1989	1993	1996	1999	2002
RS25D130100		3-4	3-4	3	
RS25D130200	4	4	3-4	3-4	3*
RS25D130400	5				

**Most Recent Assessment:**

Deep deposits of peat silt and abundant duckweed (L. minor) and other emergent macrophytes indicate a considerable impact from peat extraction on this sluggish bog stream.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D130100	DERRYCOOLY STREAM - Br NE of Derrycooly	IE_SH_25D130400	222229	224461	Offaly County Council
RS25D130200	DERRYCOOLY STREAM - Aqueduct u/s Clodiagh R	IE_SH_25D130400	221240	226334	Offaly County Council
RS25D130400	DERRYCOOLY STREAM - Br at Grand Canal confl	IE_SH_25D130400	221181	226384	Offaly County Council

**DOLLA****25D08**

Date Surveyed (last survey year only): 12/09/24

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2024
RS25D080300	4	5										
RS25D080400	4-5	4-5	4	4	4	4	4	4-5	4-5	4	4	4

**Most Recent Assessment:**

The River Dolla continues to be in satisfactory condition (0400) with good ecological condition assigned in September 2024.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D080300	DOLLA - Br at Dolla	IE_SH_25D080400	187136	171742	Tipperary County Council
RS25D080400	Bridge u/s Nenagh River confl.	IE_SH_25D080400	187872	173545	Tipperary County Council

**DOON STREAM****25D03**

Date Surveyed (last survey year only): 12/08/25

**Biological Quality Rating (Q Values)**

Station Code	2008	2012	2015	2018	2021	2025
RS25D030600	3-4*	3-4*	3-4	4	3-4	4

**Most Recent Assessment:**

The Doon Stream improved from moderate to good ecological condition in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D030600	Bridge at Gortavalla, SW of Doon	IE_SH_25D030600	181422	148938	Limerick City & County Council

**DOONANE****25D04**

Date Surveyed (last survey year only): 04/09/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25D040010				4-5	4-5	4-5		4-5	4-5	4-5	4	4
RS25D040100	5											
RS25D040200	5	5	5	4-5	4-5	5	4-5	4-5	4-5	4-5	4	4

**Most Recent Assessment:**

Both sites sampled on the Doonane River in early September 2025 were in good ecological condition.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D040010	DOONANE - Ford ENE of Toor	IE_SH_25D040200	181266	164377	Tipperary County Council
RS25D040100	DOONANE - Br W of Toorataggart	IE_SH_25D040200	179894	164594	Tipperary County Council
RS25D040200	Bridge u/s Newport River confl.	IE_SH_25D040200	177824	165064	Tipperary County Council

**DRUMANDOORA****25D06**

Date Surveyed (last survey year only): 17/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1989	1994	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023
RS25D060200		5	5	4	4-5	4-5			5	4-5	4	4	4
RS25D060500					4-5	4	4-5	4-5	4	4	4	4	4
RS25D060600	4	4	4-5	4									

**Most Recent Assessment:**

The Drumandoora continues to be in satisfactory condition with Good ecological quality assigned to both stations in July 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D060200	DRUMANDOORA - Br N of Drumandoora West	IE_SH_25D060500	150694	194283	Clare County Council
RS25D060500	2nd Br u/s Lough Graney	IE_SH_25D060500	153731	195648	Clare County Council
RS25D060600	DRUMANDOORA - Br u/s L Graney	IE_SH_25G040100	153743	195656	Clare County Council

**DRUMKEARY STREAM**

**25D11**

Date Surveyed (last survey year only): 09/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1989	1993	1996	1999	2003	2006	2009	2012	2014	2017	2018	2019	2021	2023
RS25D110300		4	4-5	4-5	4-5	4	4	4	4-5	3-4	4			4	3-4
RS25D110350	5		5		4-5	4-5	4	4-5	4-5	4	4-5	4	4	4	4
RS25D110500				4-5											

**Most Recent Assessment:**

A disappointing drop to Moderate ecological quality at the upper site (0300), while Good quality was maintained at the lower site (0350) in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D110300	Bridge N.W. of Drumkeary	IE_SH_25D110300	167836	206491	Galway County Council
RS25D110350	Second Br u/s Duniry River	IE_SH_25D110350	169619	207358	Galway County Council
RS25D110500	DRUMKEARY STREAM - Just u/s Duniry R confl.	IE_SH_25D070400	169641	208656	Galway County Council

**DUNIRY**

**25D07**

Date Surveyed (last survey year only): 31/07/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1989	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023	2025
RS25D070100	5	5	4-5	5	4-5	4-5	4	4	4	4	4	4	3-4	4
RS25D070200		5	4-5	5	4-5	4-5	4-5		4-5	4-5	4-5	4-5	4	4
RS25D070300	5													
RS25D070400	5	5	5	5	5	5	4-5	4-5	4-5	4-5	4-5	4	4	

**Most Recent Assessment:**

The Duniry River improved from Moderate to Good condition at the Cullenagh Bridge site (0100) when sampled in late July 2025. The second site sampled (0200) retained its Good condition.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D070100	Cullenagh Bridge	IE_SH_25D070100	164908	207720	Galway County Council
RS25D070200	DUNIRY - Bridge u/s Ballinasack Br	IE_SH_25D070400	169176	208706	Galway County Council
RS25D070300	DUNIRY - Ballinasack Bridge	IE_SH_25D070400	169779	208845	Galway County Council
RS25D070400	Just u/s Cappagh River confl,	IE_SH_25D070400	172123	208970	Galway County Council

**DURROW ABBEY STREAM****25D12**

Date Surveyed (last survey year only): 18/07/23

**Biological Quality Rating (Q Values)**

Station Code	1989	1993	1996	1999	2002	2005	2011	2014	2017	2021	2023
RS25D120200	3-4	3-4	3	2-3	3	3-4	3-4	3-4	3-4	3	3

**Most Recent Assessment:**

The paucity of pollution sensitive macroinvertebrate species indicate Poor ecological quality on the Durrow Abbey Stream in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D120200	DURROW ABBEY STREAM - Br u/s Silver (Tullamore) River	IE_SH_25D120200	230189	228890	Offaly County Council

**DYSART STREAM (LOUGH ENNELL)****25D05**

Date Surveyed (last survey year only): 08/06/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2022	2023
RS25D050100		4-5	3	4	3*	3-4	3*	4*	3-4	4	4	4	4
RS25D050300	4												
RS25D050400		4-5	3-4	4	4	3-4	3*	3-4	3-4	3-4	3-4	3-4	3-4

**Most Recent Assessment:**

The macroinvertebrate fauna continues to indicate Good ecological conditions at the upper station (0100) on the Dysart Stream in June 2023 while Moderate ecological condition persists at station 0400 (just upstream Lough Ennell).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25D050100	Br NW of Milltown	IE_SH_25D050400	233262	249230	Westmeath County Council
RS25D050300	DYSART STREAM (LOUGH ENNELL) - Br in Dysart	IE_SH_25D050400	236137	247063	Westmeath County Council
RS25D050400	Br u/s L Ennell	IE_SH_25D050400	237108	245616	Westmeath County Council

**EYRECOURT STREAM****25E01**

Date Surveyed (last survey year only): 10/08/23

**Biological Quality Rating (Q Values)**

Station Code	1980	1983	1986	1988	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023
RS25E010050		3-4	3-4	3-4	4		4	3							
RS25E010080														3	
RS25E010100	3	3	3	2-3	3	2	2-3	2-3	2-3	3	2-3	3	3	3	3
RS25E010200			3	3	3		3	3		3	2-3	3	3		3
RS25E010300			3	3	3										

**Most Recent Assessment:**

The Eyecourt Stream remains in unsatisfactory condition in August 2023. Poor ecological quality was once again recorded at both stations and conditions at station 0200 appear to have deteriorated further. Here very low macroinvertebrate diversity was recorded with pollution tolerant taxa dominating the sample. This was coupled with very low dissolved oxygen (3.31mg/l), anoxic silts and very slow flow observed.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25E010050	EYRECOURT STREAM - Bridge W.S.W. of Eyrecourt	IE_SH_25E010200	190605	216358	Galway County Council
RS25E010080	Farm Br. u/s Eyrecourt WWTP	IE_SH_25E010200	191783	216345	Galway County Council
RS25E010100	Bridge N.N.E. of Fearmore	IE_SH_25E010200	193403	215889	Galway County Council
RS25E010200	N Br u/s Shannon River confl	IE_SH_25E010200	194771	214966	Galway County Council
RS25E010300	EYRECOURT STREAM - Br u/s Shannon River confl	IE_SH_25S012060	195273	214978	Galway County Council

**GAGEBOROUGH**

**25G01**

Date Surveyed (last survey year only): 12/06/23, 13/06/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1989	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25G010045			4	3-4	3-4	4	3-4		3-4	3-4	3-4	3-4	4
RS25G010050		4											
RS25G010100	4-5	4	4	3-4	3-4	3-4	4	3-4	3-4	4	4	4	3-4
RS25G010190		4											
RS25G010200	4-5												
RS25G010300	4-5	4	4	3-4	3-4	3-4	4-5	4	3-4	3-4	4	4	3-4
RS25G010400	4-5												
RS25G010500	5	4-5	3-4	4	3-4	3-4	3-4	3-4	4	4	4	4	4

**Most Recent Assessment:**

The macroinvertebrate fauna indicated satisfactory ecological conditions at only two of the four stations surveyed on the Gageborough in June 2023. While the macroinvertebrate community indicated an improvement in the upper reaches (0045), an unwelcome decline was noted in the mid reaches (0100, 0300).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G010045	GAGEBOROUGH - E of Bunanagh (roadside)	IE_SH_25G010100	229918	243154	Westmeath County Council
RS25G010050	GAGEBOROUGH - Br W of Rockfield	IE_SH_25G010100	229695	242559	Westmeath County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G010100	Donore Br	IE_SH_25G010100	229386	240248	Westmeath County Council
RS25G010190	GAGEBOROUGH - Horseleap- Mullingar Rd Br	IE_SH_25G010300	227841	238307	Offaly County Council
RS25G010200	GAGEBOROUGH - Horseleap- N6 Rd Br	IE_SH_25G010300	227670	238272	Offaly County Council
RS25G010300	Gageborough Br 1.2km S of Dunard	IE_SH_25G010300	226085	237776	Offaly County Council
RS25G010400	GAGEBOROUGH - Gorteen Br	IE_SH_25G010500	224101	235287	Offaly County Council
RS25G010500	Ballyboughlin Br u/s Brosna R confl	IE_SH_25G010500	223701	233773	Offaly County Council

**GARRYARD STREAM****25G15**

Date Surveyed (last survey year only): 14/09/05

**Biological Quality Rating (Q Values)**

Station Code	1974	1976	1978	1981	1985	1987	2002	2005
RS25G150100	1	1/0	1/0	1/0	3/0	1/0	1/0	3/0

**Most Recent Assessment:**

Although considerably improved since 2002 a very restricted macroinvertebrate fauna which was devoid of sensitive species indicated some considerable ecological disruption in this small stream in September 2005. Chemical analysis in 2004 revealed high levels of Cadmium, Zinc and Manganese. Formerly reported as Yellow (Kilmastulla) 25Y010100 and Kilmastulla 25K040400.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G150100	GARRYARD STREAM - Just u/s Yellow (Kilmastulla) confl	IE_SH_25K040800	180183	171235	Tipperary County Council

**GLASHACLOONARAVEELA**

**25G02**

Date Surveyed (last survey year only): 03/09/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25G020100		5	5	5	4-5			4-5	4-5	4-5	4	4
RS25G020500	5	5	4	4-5	4-5	4-5	4	4*	4	4	4	4-5

**Most Recent Assessment:**

The Glashacloonaraveela River showed an improvement from Good to High condition at the lower site (0500), with the upper site (0200) remaining in Good condition in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G020100	GLASHACLOONARAVEELA - Br E of Crehaun	IE_SH_25G020500	182192	155449	Limerick City & County Council
RS25G020500	Glasha Br u/s Bilboa R confl	IE_SH_25G020500	180072	153497	Limerick City & County Council

**GLENBONNIV****25G07**

Date Surveyed (last survey year only): 28/07/88, 31/12/88

**Biological Quality Rating (Q Values)**

Station Code	1980	1986	1988
RS25G070100	4	4	4-5
RS25G070200	4	4	4
RS25G070300	5	4-5	4
RS25G070600			4

**Most Recent Assessment:****Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G070100	GLENBONNIV - Bridge N.W. of Garraun	IE_SH_25C070600	157267	187430	Clare County Council
RS25G070200	GLENBONNIV - Bridge S.W. of Feakle	IE_SH_25C070600	157549	186848	Clare County Council
RS25G070300	GLENBONNIV - Bridge E. of Derryeaghra L	IE_SH_25C070600	156320	185795	Clare County Council
RS25G070600	GLENBONNIV - Bridge u/s Cloghaun River	IE_SH_25C070600	157879	183514	Clare County Council

**GLENFELLY STREAM****25G21**

Date Surveyed (last survey year only): 02/08/23, 03/08/23

**Biological Quality Rating (Q Values)**

Station Code	1989	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25G210010		5	5	5	5		4	4	4-5	4-5	4-5	4-5
RS25G210080	5	5	5									
RS25G210090				4-5	4-5	5	4	4	4-5	4-5	4-5	4-5

**Most Recent Assessment:**

The dominance of pollution sensitive macroinvertebrate taxa continues to indicate high ecological quality at the two stations surveyed on the Glenfelly Stream in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G210010	Br 3km E of Longford	IE_SH_25G210090	220186	201375	Offaly County Council
RS25G210080	GLENFELLY STREAM - Br W of Kinnitty	IE_SH_25G210090	217393	205405	Offaly County Council
RS25G210090	Wooden Br d/s Clonfosse Br	IE_SH_25G210090	217058	206080	Offaly County Council

**GLENOMRA WOOD STREAM****25G12**

Date Surveyed (last survey year only): 10/07/23

**Biological Quality Rating (Q Values)**

Station Code	1988	1994	1996	1999	2002	2009	2012	2014	2017	2021	2023
RS25G120100	4	4-5	4-5	4-5	4	4	4	4	4-5	4-5	4

**Most Recent Assessment:**

The composition of the invertebrate community in the Glenomra Wood Stream indicates a significant decline since last assesses in 2021, when it was at high ecological condition. It now just qualifies as Good.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G120100	Br u/s Blackwater R confl	IE_SH_25G120100	160025	165844	Clare County Council

**GOLDEN GROVE STREAM**

**25G06**

Date Surveyed (last survey year only): 14/08/23

**Biological Quality Rating (Q Values)**

Station Code	1981	1983	1985	1987	1988	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25G060040				4-5		2-3	3-4	3-4								
RS25G060080				5		3-4	4	3-4	3	3-4	3-4	3-4	3-4	3-4	3-4	3-4
RS25G060100				4-5												
RS25G060200	2	1-2	2	2-3	2-3	2-3	2-3	3	3	3						

**Most Recent Assessment:**

The Golden Grove Stream remained in Poor condition. Agricultural pressures are the most likely cause of the problem.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G060040	GOLDEN GROVE STREAM - d/s Br nr Ballybrit Castle	IE_SH_25G060080	214470	195376	Offaly County Council
RS25G060080	Br W of Laurel Hill	IE_SH_25G060080	213376	192514	Offaly County Council
RS25G060100	GOLDEN GROVE STREAM - Old Br E of High Park	IE_SH_25G060200	211908	191057	Offaly County Council
RS25G060200	Br. just u/s Little Brosna R.	IE_SH_25G060200	210947	190435	Offaly County Council

**GORRAGH****25G09**

Date Surveyed (last survey year only): 03/08/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2018	2019	2021	2023
RS25G090100	5													
RS25G090200		4-5	4-5	4-5	5	4		4-5	4-5	5	4-5	5	5	5
RS25G090300	5						4-5	4	4-5	4-5			4-5	5

**Most Recent Assessment:**

Satisfactory high ecological conditions continue at the two stations surveyed on the Gorragh in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G090100	GORRAGH - Ford W of Srahcullen	IE_SH_25G090300	231531	209659	Laois County Council
RS25G090200	GORRAGH - Gorragh Br E of Clonaslee	IE_SH_25G090300	232296	210757	Laois County Council
RS25G090300	Killart House	IE_SH_25G090300	232437	212007	Laois County Council

**GORTNAGERAGH****25G03**

Date Surveyed (last survey year only): 02/09/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25G030200		4	4-5	4-5	4-5	4-5	4	4	4-5	4	4	4-5
RS25G030300	5	5	4-5	4-5	4-5	4	4	4	4-5	4	4	4-5

**Most Recent Assessment:**

The Gortnageragh River showed an improvement to High ecological conditions at both sites sampled in early September 2025 compared with 2021 and 2018.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G030200	Br SW of Foilycleary	IE_SH_25G030300	187080	154864	Tipperary County Council
RS25G030300	Br u/s Bilboa R confl	IE_SH_25G030300	182635	152693	Limerick City & County Council

**GORTNAGOWNA****25G13**

Date Surveyed (last survey year only): 11/09/24

**Biological Quality Rating (Q Values)**

Station Code	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2024
RS25G130300	4-5										
RS25G130400		4	4-5	4-5	4-5	4	4-5	4-5	4-5	4	4-5*
RS25G130500	4-5										

**Most Recent Assessment:**

The macroinvertebrate fauna indicated a welcome return to high ecological conditions on the Gortnagowna in September 2024 despite a heavy plume and substrate siltation. The sampling location was moved 200m upstream of the bridge while bridge works were underway at the time of sampling.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G130300	GORTNAGOWNA - Tooreagh Br	IE_SH_25N010100	193957	167462	Tipperary County Council
RS25G130400	Br u/s Cloghinch Old Br	IE_SH_25N010100	195210	168300	Tipperary County Council
RS25G130500	GORTNAGOWNA - Cloghinch Old Br	IE_SH_25N010100	195638	168978	Tipperary County Council

**GRANEY (SHANNON)****25G04**

Date Surveyed (last survey year only): 10/07/23, 16/08/23

**Biological Quality Rating (Q Values)**

Station Code	1971	1975	1979	1981	1984	1986	1987	1993	1994	1996	1999	2003	2006	2009	2012	2014	2017	2018	2019	2021	2023
RS25G040010					4		4-5	5		5	5	4-5	4-5		4-5	4-5	4	4	4	4	4
RS25G040025					4-5		5	5		5	5	5	4-5	5	5	5	5	4-5	4-5	4-5	4-5
RS25G040100			4		4		4	4		3	4	4-5	4	4-5	4	4	4			3-4	4
RS25G040150					4-5		4														
RS25G040200	5	5	4		5		5		5	4	4	5	4-5	4-5	4-5	4-5	4		4	4	4
RS25G040300	5	5	4	5	4	4-5	4			4		3*	3-4		3-4	3-4	3			3-4	4
RS25G040350						3	3		3												
RS25G040400										3	3	2	3	3-4	3	3	3-4			3	3-4

**Most Recent Assessment:**

Five of the six sites samples on the Graneey in 2023 were assessed as being in satisfactory condition. Only the lowermost site (Station 0400) was assigned Q 3-4, but this is actually an improvements over the 2021 results, when this site was at Q3.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G040010	GRANEY (SHANNON) - Br d/s Lough Ea	IE_SH_25G040025	152208	189165	Clare County Council
RS25G040025	Caher Br, S of L.Graneey	IE_SH_25G040025	155459	190062	Clare County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G040100	Aughadarreen Bridge	IE_SH_25G040100	158152	189578	Clare County Council
RS25G040150	GRANEY (SHANNON) - New Br	IE_SH_25G040200	160713	188373	Clare County Council
RS25G040200	Cooleen Br	IE_SH_25G040200	160316	186028	Clare County Council
RS25G040300	GRANEY (SHANNON) - 1 km u/s Scarriff Br	IE_SH_25G040300	163341	184310	Clare County Council
RS25G040350	GRANEY (SHANNON) - Scarriff Br	IE_SH_25G040400	164183	184274	Clare County Council
RS25G040400	400 m d/s Scarriff Br	IE_SH_25G040400	164501	184057	Clare County Council

**GRANGE (TIPPERARY)****25G10**

Date Surveyed (last survey year only): 31/07/87

**Biological Quality Rating (Q Values)**

Station Code	1986	1987
RS25G100100	5	5
RS25G100200		4-5

**Most Recent Assessment:****Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G100100	GRANGE (TIPPERARY) - Br NW of Ballycorrigan	IE_SH_25G100100	171569	173983	Tipperary County Council
RS25G100200	GRANGE (TIPPERARY) - Just u/s Shannon R confl	IE_SH_25G100100	171536	173828	Tipperary County Council

**GROODY**

**25G05**

Date Surveyed (last survey year only): 03/09/25

**Biological Quality Rating (Q Values)**

Station Code	1971	1975	1979	1983	1985	1987	1993	1996	1999	2002	2006	2008	2012	2015	2018	2021	2025
RS25G050100	4	4	4	4	3-4	3	3	3-4	3	3-4							
RS25G050150					3-4	3	3	3	3	3		3	4	3-4	3-4	3-4	4
RS25G050200	4	4	4	4	3	3-4	3	3	3	3*	3-4	3-4	4	3-4	3-4	3-4	3
RS25G050300	4	4	4	4		3-4	3										

**Most Recent Assessment:**

Both sites on the Groody on the outskirts of Limerick City showed changes compared with 2021. The upper site (0150) improved from Moderate to Good and the second site (0200) declined from Moderate to Poor condition.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25G050100	GROODY - Br 2km N of Caherconlish (G4)	IE_SH_25G050200	167771	151681	Limerick City & County Council
RS25G050150	Killonan Br	IE_SH_25G050200	163587	154301	Limerick City & County Council
RS25G050200	Br in Ballysimon (G2)	IE_SH_25G050200	161607	155106	Limerick City & County Council
RS25G050300	GROODY - Groody Br (G1)	IE_SH_25S012600	160665	157022	Limerick City & County Council

**INCH (BILBOA)****25I01**

Date Surveyed (last survey year only): 02/09/25

**Biological Quality Rating (Q Values)**

Station Code	1989	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25I010004	4	3-4	4	3	3-4*	3-4		3-4	3-4	3-4*	3	4
RS25I010008	4	4	3-4	4	4	4-5	4	4	4	4	4	4

**Most Recent Assessment:**

Both sites on the Inch (Bilboa) were satisfactory when sampled in 2025 – with an improvement at the upper site.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25I010004	INCH (BILBOA) - Br SE of Loughbrack	IE_SH_25I010008	191720	158498	Tipperary County Council
RS25I010008	Br u/s R confl	IE_SH_25I010008	188902	158313	Tipperary County Council

**KEELOGE STREAM****25K14**

Date Surveyed (last survey year only): 19/08/25

**Biological Quality Rating (Q Values)**

Station Code	1984	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2018	2021	2023	2025
RS25K140015		5	4	4											
RS25K140016					4-5	4	3-4	3-4*	4*			4	4		3
RS25K140020	5	3													
RS25K140025		3-4	3-4	3	4-5	3-4	3-4		3-4	3-4	3-4		3-4	3-4	
RS25K140027	4	4	3-4	3-4	4	4	3-4	3-4*	3-4	3-4	3-4		3-4	3-4	

**Most Recent Assessment:**

One site on the Keeloge Stream was sampled in 2025 (0016) and this declined from Good to Poor. This site was severely impacted by livestock access to the stream.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25K140015	KEELOGE STREAM - Br E of Loughan	IE_SH_25K140016	205403	183371	Offaly County Council
RS25K140016	Br SW of Dunkerrin (Main Rd)	IE_SH_25K140016	205605	183928	Offaly County Council
RS25K140020	KEELOGE STREAM - Br E of Ballyrihy Ho	IE_SH_25K140027	205095	185512	Offaly County Council
RS25K140025	KEELOGE STREAM - Br 3 km N of Ballyrihy Ho	IE_SH_25K140027	205347	188134	Offaly County Council
RS25K140027	Br at Keeloge Cottage	IE_SH_25K140027	204549	191290	Offaly County Council

**KILCOMIN STREAM**

**25K15**

Date Surveyed (last survey year only): 31/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25K150040	3-4	3-4	3	3	3	3		3*		3	3	3
RS25K150052	4	3-4	3	4	3-4	3-4	3-4			3-4	3-4	3*
RS25K150070	3-4											
RS25K150085	3-4	3-4	3	3-4	3	3-4		3-4	3-4	3	3	3-4

**Most Recent Assessment:**

The Kilcomin Stream continues to be in unsatisfactory condition. At the upper station (0040) Poor ecological quality was recorded with turbid water noted on the day of survey. Downstream at station 0052 conditions declined from Moderate to Poor ecological quality and the river here was slow flowing with deep silts. An improvement was observed at the lowermost station (0085) from Poor to Moderate ecological quality.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25K150040	Br SW of Barna	IE_SH_25K150040	202723	186108	Offaly County Council
RS25K150052	Coolroe Br (1.6km u/s Kilcomin Br)	IE_SH_25K150052	202559	189280	Offaly County Council
RS25K150070	Was RS25K150055, Kilcomin Br	IE_SH_25K150085	202628	190593	Offaly County Council
RS25K150085	Br ESE of Kennes X-Rds	IE_SH_25K150085	204369	191774	Offaly County Council

**KILCROW**

**25K01**

Date Surveyed (last survey year only): 31/07/25

**Biological Quality Rating (Q Values)**

Station Code	1975	1979	1980	1983	1986	1988	1989	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023	2024	2025	
RS25K010005							3-4														
RS25K010020						4			4	4	4	4	4	3-4	4	4	4	3	4*	3	
RS25K010040						4															
RS25K010060								4				3		3-4	4	4	4	3	3-4*	3	
RS25K010100			4	4	3-4	4		3	3	3	3-4	4		3-4	4	3-4	3-4	3-4			
RS25K010200	2	4	4	3-4	4	4		4	3	4											
RS25K010300			3	3	3	4		4	3	3-4	3-4	3	4	3-4	4	3-4	3-4	3-4			
RS25K010350			3-4	3	3-4																
RS25K010360					3-4	4		3-4	2-3	4	4	3-4	4	3-4	3-4	3	3	3*			
RS25K010400			3-4	3-4	3-4	3-4		4		3-4	3	3									
RS25K010500	4	4	4	4	4	4		3	2-3	3			3-4	3-4	3	3	3	3			
RS25K010600			4	4-5	4	4		3-4	3	4	3-4	3									
RS25K010700	4	4	4	3-4	4	4		3	3-4	4	4	3-4	4	4	4	4	3-4	3			

Most Recent Assessment:

Two sites on the upper Kilcrow River were surveyed in late July 2025. Both sites were in poor condition. Excessive siltation was noted at both sites.

### Station Details

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25K010005	KILCROW - 3rd Br u/s Main Channel	IE_SH_25K010020	173270	224712	Galway County Council
RS25K010020	Bridge N. of Killoran	IE_SH_25K010020	176312	221924	Galway County Council
RS25K010040	KILCROW - Bridge S.E. of Cloonlahan	IE_SH_25K010060	180569	219490	Galway County Council
RS25K010060	KILCROW - 1st Br u/s Ahanageelery Br	IE_SH_25K010060	181901	217835	Galway County Council
RS25K010100	KILCROW - Ahanageleery Bridge	IE_SH_25K010100	180626	217238	Galway County Council
RS25K010200	KILCROW - Oxgrove Bridge	IE_SH_25K010300	180114	214998	Galway County Council
RS25K010300	Hearnesbrook Bridge	IE_SH_25K010300	179797	213032	Galway County Council
RS25K010350	KILCROW - East Br 2 km d/s Samp St 0300	IE_SH_25K010360	179996	211961	Galway County Council
RS25K010360	West Br 2 km d/s Samp St 0300	IE_SH_25K010360	179794	211766	Galway County Council
RS25K010400	KILCROW - Killeen Bridge	IE_SH_25K010500	179794	210952	Galway County Council
RS25K010500	Moat Bridge	IE_SH_25K010500	179980	210129	Galway County Council
RS25K010600	KILCROW - Newbridge	IE_SH_25K010700	179393	207294	Galway County Council
RS25K010700	Ballyshrule Bridge	IE_SH_25K010700	179808	205666	Galway County Council

**KILFADDA CASTLE STREAM****25K07**

Date Surveyed (last survey year only): 10/08/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25K070600	4-5	3-4	3-4	3-4	3-4	3-4	3-4	3-4*	4	3-4	3-4	3

**Most Recent Assessment:**

The macroinvertebrate fauna indicated poor ecological conditions at the Kilmadda Castle Stream with a high percentage of filamentous green algae and moderate siltation observed on the day of survey.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25K070600	Br SE of Carrigahorig	IE_SH_25K070600	191730	200817	Tipperary County Council

**KILLEENGARRIFF****25K02**

Date Surveyed (last survey year only): 13/08/25

**Biological Quality Rating (Q Values)**

Station Code	1971	1975	1979	1983	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25K020100	5	5	5	5	5											
RS25K020150					5	4-5	4-5	4-5	4	4-5	4	4	4	4	4	4-5
RS25K020200	5	5	5	4	4-5											

**Most Recent Assessment:**

The Killeengarriff River was assessed as returning to high conditions (last seen in 2005).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25K020100	KILLEENGARRIFF - Annagh Br (K3)	IE_SH_25K020150	168395	157764	Limerick City & County Council
RS25K020150	Br d/s Annagh Br	IE_SH_25K020150	168244	156327	Limerick City & County Council
RS25K020200	KILLEENGARRIFF - Barrington's Br (K4)	IE_SH_25M040590	167899	154882	Limerick City & County Council

**KILMASTULLA****25K04**

Date Surveyed (last survey year only): 10/07/25, 14/08/25

**Biological Quality Rating (Q Values)**

Station Code	1971	1974	1976	1978	1981	1983	1985	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25K040050											4	4	4-5		4-5	3-4	3-4	3-4	4
RS25K040100		4	4	3-4		3-4	3-4	4	4			3	3	3-4	3-4	3-4	3-4	4	3-4
RS25K040120										3	3-4	3-4	3-4	3-4	3-4	3-4	3-4	3	3-4
RS25K040150								4-5	3-4										
RS25K040300		3	2/0	1/0	3/0	3		3				3							
RS25K040700		2	1/0	1/0	2/0	3		3-4											
RS25K040800		2	2-3	1/0	3/0	3-4	3/0	3-4	3/0	3/0	3*	3	3-4	3-4	3-4	3-4	4	3-4	3-4
RS25K040900	3-4	3-4	3/0	3/0	3/0	3-4	4	4	3/0	3-4									
RS25K040910											3-4	3-4	3-4	3-4	3-4	3-4	3-4	3-4	4
RS25K040950					3/0	3-4	4	4-5											
RS25K041000	5	4-5	4	3-4	4	4	4-5	4-5	3/0	3-4	4	3-4	4	3-4	4	4	4	3-4	4

**Most Recent Assessment:**

The Kilmastulla River was surveyed over its length in July 2025. The macroinvertebrate fauna indicated improvements at four of the six sites surveyed with stations 0050, 0910 and 1000 improving from moderate to good and station 0120 improving from poor to moderate ecological condition. Station 0100 (Br d/s Silvermines Br) declined from good to moderate while station 0800 (Crana Br.) remained at moderate condition.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25K040050	Br in Silvermines village	IE_SH_25K040120	184257	171416	Tipperary County Council
RS25K040100	Br d/s Silvermines Br	IE_SH_25K040120	183987	172431	Tipperary County Council
RS25K040120	Carrow Br (W of Srah Cottage)	IE_SH_25K040120	182814	173402	Tipperary County Council
RS25K040150	KILMASTULLA - Erinagh Br (W of Gortnacleha)	IE_SH_25K040300	181589	172642	Tipperary County Council
RS25K040300	U/s Yellow R confl	IE_SH_25K040300	180191	172348	Tipperary County Council
RS25K040700	KILMASTULLA - d/s Yellow R confl	IE_SH_25K040800	179612	172122	Tipperary County Council
RS25K040800	Cranna Bridge	IE_SH_25K040800	178486	171868	Tipperary County Council
RS25K040900	KILMASTULLA - Br NE of Cappadine	IE_SH_25K040910	175462	171001	Tipperary County Council
RS25K040910	Br W of Cappadine	IE_SH_25K040910	174603	170636	Tipperary County Council
RS25K040950	KILMASTULLA - Br u/s Kilmastulla Br	IE_SH_25K041000	172832	169737	Tipperary County Council
RS25K041000	Cool Bridge	IE_SH_25K041000	170951	169510	Tipperary County Council

**LISDUFF (KILCROW)**

**25L06**

Date Surveyed (last survey year only): 07/07/23

**Biological Quality Rating (Q Values)**

Station Code	1980	1983	1984	1987	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023
RS25L060060				3		2-3	3-4								
RS25L060100				3	3-4	3		4	3-4	3-4	3-4	4	4	3-4	3
RS25L060200		3-4	4	4	3		4	3							
RS25L060300	3	3-4/0	3	3/0	3								4		
RS25L060400		4-5	3	3/0	3	3	4	3	3/0	3-4	3-4	3-4	3-4	3-4	3-4
RS25L060500		3-4	3	3/0											

**Most Recent Assessment:**

Both sites on the Lisduff (Kilcrow) continue to be in unsatisfactory condition in 2023. Station 0100 (Castletown Br.) has declined to Poor ecological quality.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25L060060	LISDUFF (KILCROW) - Br S.W. of Carrowshanbally	IE_SH_25L060100	171318	216003	Galway County Council
RS25L060100	Castletown Bridge	IE_SH_25L060100	174015	215374	Galway County Council
RS25L060200	LISDUFF (KILCROW) - Bridge at Coolagh	IE_SH_25L060400	175817	214527	Galway County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25L060300	LISDUFF (KILCROW) - Br u/s Kilcrow R confl (at Old Corn Mill)	IE_SH_25L060400	177297	213344	Galway County Council
RS25L060400	300 m d/s Samp station 0300	IE_SH_25L060400	177443	213120	Galway County Council
RS25L060500	LISDUFF (KILCROW) - Just u/s Kilcrow River confl	IE_SH_25K010360	179117	212430	Galway County Council

**LISDUFF STREAM (SHANNON)****25L07**

Date Surveyed (last survey year only): 07/07/23

**Biological Quality Rating (Q Values)**

Station Code	1982	1983	1984	1986	1987	1988	1993	1996	2003	2009	2012	2014	2021
RS25L070050				3	2/0	1/0	3/0	3/0	3/0		3/0	3/0	3
RS25L070100	1/0		1-2	1-2	2-3/0	2-3							
RS25L070200	1/0	1/0	3/0	3	2-3/0		2-3	2	2-3	3-4	3	3	3

**Most Recent Assessment:**

There was no discernible flow at either site on 22/08/2021. The condition was assessed as being unsatisfactory, but no evidence of a toxic impact was detected. This is unchanged since 2014 when last assessed. (Note the 2017 survey at station 0200 was assigned incorrectly and was actually taken on Lisduff (Kilcrow) 25L06 at Station 0300, which runs parallel to this river).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25L070050	LISDUFF STREAM (SHANNON) - 1.5 km S.W. Lisduff House	IE_SH_25L060400	175561	212706	Galway County Council
RS25L070100	LISDUFF STREAM (SHANNON) - Bridge at Lisduff House	IE_SH_25L060400	176660	213143	Galway County Council
RS25L070200	Just u/s Mill Stream confl	IE_SH_25L060400	177208	213398	Galway County Council

**LITTLE (CLOGHAN)****25L01**

Date Surveyed (last survey year only): 11/08/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1986	1987	1988	1989	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25L010100	1	2	2	2	2-3	2-3		2-3								
RS25L010200	1	3	3			3-4	4	3-4	3-4	3-4	4	4	4-5	4-5	4-5	4
RS25L010400	2	3	3			4	4	4	3-4*	4	3-4	4	4-5	4-5	4	4

**Most Recent Assessment:**

While conditions remained satisfactory within the Little (Cloghan) station 0200 declined from High to Good ecological quality. Here the density & diversity of sensitive taxa was lower than previous years. The upper site was very shaded and the substrate was very calcareous and compacted in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25L010100	LITTLE (CLOGHAN) - Crancreagh Br	IE_SH_25L010200	207930	216220	Offaly County Council
RS25L010200	Br 2km SW of Cloghan	IE_SH_25L010200	206296	217769	Offaly County Council
RS25L010400	Br u/s Brosna R confl	IE_SH_25L010400	204195	219805	Offaly County Council

**LITTLE BROSNA****25L02**

Date Surveyed (last survey year only): 19/08/25

**Biological Quality Rating (Q Values)**

Station Code	1971	1973	1975	1977	1981	1984	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023	2025
RS25L020100	5	5	5	5	4	4-5	3-4	3-4	4	4	3-4	3-4	3-4	4	4	4	4	4	
RS25L020200					4	4	3-4												
RS25L020300	4	3-4	3-4		3-4	3-4	3-4	3	3	3	3-4		3-4	3-4	3-4	3-4	3-4	3-4	3
RS25L020301											1								
RS25L020400				4	4	4	4	3-4	3	3	3/0	3-4	3-4	3-4	3-4	3	3	3	
RS25L020500	4-5	3-4	4	4	4	4-5	4												
RS25L020600	4				4-5	5	4-5	3-4	4	4	4	3-4	3-4	4	4	4	4	4	
RS25L020700	5	4-5		4-5	4-5	4	4	3-4	3	4	3-4	3	3-4	4	3-4	3-4	3-4	3	
RS25L020800	5	5		5	4	4	4-5	4											
RS25L020810									3-4	3-4	3-4	3-4		4	4		3-4		
RS25L020900	5			5	4	5	5												
RS25L021000					4	4-5	5	3-4	3-4	3-4	3-4	3-4	4	4	4	4	4	3-4	

**Most Recent Assessment:**

The absence of the most pollution sensitive macroinvertebrate taxa coupled with the increased dominance of pollution tolerant taxa indicated a decline from moderate to poor ecological conditions at station 0300 in 2025.

### Station Details

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25L020100	Milltown Br (nr Mt Lucas)	IE_SH_25L020100	206946	190912	Offaly County Council
RS25L020200	LITTLE BROSNA - Just u/s Bunow R confl (at water intake)	IE_SH_25L020400	210729	190393	Offaly County Council
RS25L020300	LITTLE BROSNA - 1st Br d/s Bunow R confl	IE_SH_25L020400	210877	190489	Offaly County Council
RS25L020301	LITTLE BROSNA - First Br d/s Bunow R confl (d/s RHS)	IE_SH_25L020400	210877	190504	Offaly County Council
RS25L020400	Br nr Brosna House (Drumakeenan)	IE_SH_25L020400	210070	191857	Offaly County Council
RS25L020500	LITTLE BROSNA - Brosna Br (nr Brosna Station)	IE_SH_25L020600	208020	193850	Offaly County Council
RS25L020600	Sharavoge Br (SW of S. Ho) ( d/s on RHS)	IE_SH_25L020600	205661	196471	Offaly County Council
RS25L020700	Riverstown Br	IE_SH_25L020700	205281	203542	Tipperary County Council
RS25L020800	0800 - Croghan Br	IE_SH_25L020800	205362	205624	Offaly County Council
RS25L020810	LITTLE BROSNA - 100m d/s Croghan Br	IE_SH_25L020800	205367	205670	Offaly County Council
RS25L020900	0900 - Derrinsallow Br	IE_SH_25L021000	203285	207919	Tipperary County Council
RS25L021000	New Br	IE_SH_25L021000	201700	209008	Offaly County Council

**LORRHA STREAM****25L05**

Date Surveyed (last survey year only): 01/08/25

**Biological Quality Rating (Q Values)**

Station Code	1989	1993	1996	1999	2002	2005	2008	2011	2014	2017	2018	2021	2023	2025
RS25L050200	3	3	3-4	3-4	3	3-4		4	3-4	3-4		3-4	3	
RS25L050300	4	3	3	3	3	3-4	3-4	3-4	3-4		3*	3		3

**Most Recent Assessment:**

The Lorrha Stream remained in Poor condition in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25L050200	Br SW of Lorrha	IE_SH_25L050200	191696	204475	Tipperary County Council
RS25L050300	Bridge d/s Friar's Lough	IE_SH_25L050300	190789	203724	Tipperary County Council

**LOWER VILLAGE TRIB****25L08**

Date Surveyed (last survey year only): 31/12/93

**Biological Quality Rating (Q Values)**

Station Code	1993
RS25L080081	4-5

Most Recent Assessment:

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25L080081	Tributary from Lower Village (To N. Limb)	IE_SH_25L080081	175621	194768	Galway County Council

**MILL STREAM (TYNAGH)****25M06**

Date Surveyed (last survey year only): 25/09/87

**Biological Quality Rating (Q Values)**

Station Code	1987
RS25M060200	3

Most Recent Assessment:

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25M060200	Just d/s Lisduff Stream	IE_SH_25L060400	173062	213583	Galway County Council

**MOATE STREAM**

**25M05**

Date Surveyed (last survey year only): 18/07/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1986	1987	1988	1989	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25M050150			1	1	2-3	3	1	3	2-3	3	3	3-4	3-4	3	3	3
RS25M050300	2	3	3			3	2	3	3	3						
RS25M050400	3-4	4	3			3	3-4	3	4	3-4	3*	3-4	3-4	3-4	3-4	3-4

**Most Recent Assessment:**

With a lack of sensitive taxa and low diversity Poor ecological quality continues at station 0150. Heavy siltation of the substrate was noted as well as a foul odour and very low dissolved oxygen levels on the day of survey (5.70mg/l). Moderate ecological quality was recorded at station 0400. Very low dissolved oxygen levels were again noted (5.62mg/l) and the pH indicated slightly acidic conditions compared to the upper station.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25M050150	Br NW of Culleenagower	IE_SH_25M050400	218687	237796	Westmeath County Council
RS25M050300	MOATE STREAM - Br S of Lurgan X-Rds	IE_SH_25M050400	219269	235452	Westmeath County Council
RS25M050400	Br nr Sheean Ho	IE_SH_25M050400	222092	233762	Offaly County Council

**MONAGHANSTOWN**

**25M01**

Date Surveyed (last survey year only): 08/06/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25M010100		3-4										
RS25M010300	4	4	3-4	4	4	3-4		3-4	3-4	3-4	3-4	
RS25M010500	4	4	3-4	4	3-4	3-4	3	3-4	3-4	3-4	3-4	3-4

**Most Recent Assessment:**

The macroinvertebrate fauna continues to indicate unsatisfactory ecological conditions at Nure Bridge (0500) on the Monaghanstown river in June 2023. The upstream station is no longer accessible due to health and safety concerns.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25M010100	MONAGHANSTOWN - Glomerstown- North Br	IE_SH_25M010500	233877	246851	Westmeath County Council
RS25M010300	MONAGHANSTOWN - Br NNW of Monaghanstown	IE_SH_25M010500	234991	245568	Westmeath County Council
RS25M010500	Nure Br	IE_SH_25M010500	237044	242917	Westmeath County Council

**MOUNTRICE****25M03**

Date Surveyed (last survey year only): 01/09/25

**Biological Quality Rating (Q Values)**

Station Code	1988	1994	1996	1999	2002	2006	2009	2012	2014	2017	2021	2023	2025
RS25M030300	4-5	5	4-5	4-5	4-5	3-4	4-5	4-5	4-5	4-5	4-5	4	4

**Most Recent Assessment:**

The Mountrice River remained at good ecological condition when sampled in early September 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25M030300	Br u/s Blackwater R confl	IE_SH_25M030300	158200	166123	Clare County Council

**MULKEAR (LIMERICK)****25M04**

Date Surveyed (last survey year only): 04/09/25, 13/08/25

**Biological Quality Rating (Q Values)**

Station Code	1971	1975	1979	1983	1986	1987	1993	1996	1999	2002	2006	2008	2009	2012	2015	2018	2021	2025
RS25M040100	5	5	5	4	4-5	5	4	4	4	4	4-5				4	4	3-4	3-4
RS25M040200			4-5	4	4-5	4-5	3-4*	3-4	3	4	4-5		4	4	3-4	4	3-4	4
RS25M040300		5				4-5	3											
RS25M040400			5	5		5		4	4	4	4		4-5	4	4	4	3-4	
RS25M040500	5	5	4-5	5		5	4	3-4	4	4-5								
RS25M040590						5	4	3-4	4	4	4-5	4		4-5	4-5	4-5	4	4
RS25M040600	5	5	4-5	4-5		4-5												

**Most Recent Assessment:**

Three sites were sampled on the Mulkear (Limerick) in 2025 with the upper site (0100) remaining Moderate as in 2021 and an improvement from moderate to good ecological condition was noted at Brittas Br (0200) while good ecological conditions continues at Annacotty Br (0590).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25M040100	Dromkeen Bridge	IE_SH_25M040100	174058	148025	Limerick City & County Council
RS25M040200	Brittas Br	IE_SH_25M040200	172237	150763	Limerick City & County Council
RS25M040300	Br nr Abingdon Ho (K5)	IE_SH_25M040300	171559	153421	Limerick City & County Council

---

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25M040400	2km d/s St 0300 (N of Boher at be	IE_SH_25M040400	169562	153084	Limerick City & County Council
RS25M040500	MULKEAR (LIMERICK) - Ford d/s Killeengarriff R	IE_SH_25M040590	165251	155487	Limerick City & County Council
RS25M040590	Annacotty Br d/s weir	IE_SH_25M040590	164286	157626	Limerick City & County Council
RS25M040600	MULKEAR (LIMERICK) - 1km d/s Annacotty Br (LHS)	IE_SH_25S012600	163920	158220	Limerick City & County Council

**NENAGH**

**25N01**

Date Surveyed (last survey year only): 09/09/25, 11/09/25

**Biological Quality Rating (Q Values)**

Station Code	1971	1974	1978	1981	1984	1986	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2019	2020	2021	2023	2024	2025	
RS25N010010							4	3-4															
RS25N010050							4-5	4	4-5	3-4	4-5	4-5		4-5	4-5	4-5			4		4		
RS25N010100			5	5	5		4-5	5	4-5	4-5	4	4-5	4	4	4	4			4				4-5
RS25N010170									4														
RS25N010200			5	5	4-5		4-5	5	4-5	4-5	4	4	4	4-5	4	3-4			4		4		
RS25N010300			4	5	5		5	4-5	4	4-5	4-5	4	4	4-5	4-5	4			4-5		4-5		
RS25N010400				5	4-5	5	4		4	4-5	4	3-4											
RS25N010500	5	5	4-5	5	4	4-5	5	4-5	4	4-5	4	3-4	3-4	4	4	3-4	4		4		3	3-4	
RS25N010540																					4		
RS25N010543																					3-4		
RS25N010550						4-5	4-5	3-4	3	4	3-4						4	3-4	3-4				
RS25N010600			3-4	3-4	3	4-5	4-5	3-4									4	3-4	3-4				
RS25N010650						4	3-4	3-4									3-4	3-4	3-4				
RS25N010700			3-4	3-4	3-4	4	4-5	3-4	3-4	3-4	3-4	3-4	3-4	3-4	3-4	3-4			3-4		3-4		
RS25N010730																					3-4		
RS25N010740																					3-4		

Station Code	1971	1974	1978	1981	1984	1986	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2019	2020	2021	2023	2024	2025	
RS25N010750							3-4																
RS25N010800			4	4	4		3-4	3	3-4	3-4	3-4	3-4	3-4	3-4	3-4	3-4			3-4				3-4

**Most Recent Assessment:**

Macroinvertebrate surveys were carried out at three sites on the River Nenagh in 2025. The upper site (0100) improved to high and is its best rating since 2005. The macroinvertebrate community indicated a welcome improvement from poor to moderate ecological conditions at station 0500 while moderate conditions continue at Annaghbeg Br (0800).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25N010010	NENAGH - Br NE of Curreeny Cross	IE_SH_25N010050	190905	165251	Tipperary County Council
RS25N010050	NENAGH - Br NE of Ballyhane Cross	IE_SH_25N010050	194004	168824	Tipperary County Council
RS25N010100	Cloghinch Br	IE_SH_25N010100	196182	169409	Tipperary County Council
RS25N010170	NENAGH - Br E of Latteragh Cross	IE_SH_25N010200	196426	172114	Tipperary County Council
RS25N010200	Lacken Bridge	IE_SH_25N010200	196025	172992	Tipperary County Council
RS25N010300	Ballysoilshaun bridge	IE_SH_25N010300	191556	173951	Tipperary County Council
RS25N010400	NENAGH - Ballynaclogh Br	IE_SH_25N010500	189215	174775	Tipperary County Council
RS25N010500	Bridge near Tyrone Abbey	IE_SH_25N010500	187583	178082	Tipperary County Council
RS25N010540	Just u/s Clareen rv Conflu.	IE_SH_25N010700	187432	179194	Tipperary County Council
RS25N010543	Br. just d/s Clareen Conflu	IE_SH_25N010700	187438	179312	Tipperary County Council
RS25N010550	NENAGH - Bennett's Br	IE_SH_25N010700	187743	179473	Tipperary County Council
RS25N010600	NENAGH - Kyleeragh Br	IE_SH_25N010700	187409	179906	Tipperary County Council
RS25N010650	NENAGH - Nenagh Old Br	IE_SH_25N010700	186806	181170	Tipperary County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25N010700	Bridge d/s Nenagh Bridge	IE_SH_25N010700	186111	182220	Tipperary County Council
RS25N010730	~0.95km d/s Moyroe Tributary (u/s Ballycommon)	IE_SH_25N010800	184819	182321	Tipperary County Council
RS25N010740	~1km u/s Ballyartella Br (d/s Ballycommon)	IE_SH_25N010800	184527	182613	Tipperary County Council
RS25N010750	NENAGH - Ballyartella Br	IE_SH_25N010800	183984	183351	Tipperary County Council
RS25N010800	Annaghbeg Bridge	IE_SH_25N010800	183078	184895	Tipperary County Council

**NEWPORT (TIPPERARY)****25N02**

Date Surveyed (last survey year only): 04/09/25, 05/09/25

**Biological Quality Rating (Q Values)**

Station Code	1971	1975	1979	1981	1984	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2024	2025
RS25N020020						3-4	3-4	3-4	3-4	3-4*								
RS25N020060						5	5	5	5	4-5	4-5	4-5	4-5	4-5	4-5	4		
RS25N020080						5	5	5	5	4-5			4-5	4-5	4-5	4		4
RS25N020100			5	5	5	5	5	3-4	4-5	4-5	4-5	4	4-5	4-5	4-5	4		4-5
RS25N020200	5	5	5	5	5	5	5	3	3-4	3-4*	4	4	4-5	4-5	4-5	4	4-5	4
RS25N020300	5	5	5	4-5	5	5	5											
RS25N020330							5	4	4-5	4	4-5	4	4-5	4-5	4-5	4		4
RS25N020400			5	5	5	5												
RS25N020500							5	4	4-5	4								

**Most Recent Assessment:**

Three of the four sites surveyed in 2025 were at good ecological condition while the macroinvertebrate community indicated high ecological condition at the Ford u/s Doonane river confluence (0100).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25N020020	NEWPORT (TIPPERARY) - Br S of Curreeny Commons	IE_SH_25N020060	186806	165357	Tipperary County Council
RS25N020060	Br nr Glanculoo old school	IE_SH_25N020060	183709	168346	Tipperary County Council
RS25N020080	NEWPORT (TIPPERARY) - Br N of Coolruntha	IE_SH_25N020080	180534	168641	Tipperary County Council
RS25N020100	Ford u/s Doonane R confl.	IE_SH_25N020200	177561	166828	Tipperary County Council
RS25N020200	Rockvale Br nr Mackney	IE_SH_25N020200	173864	163337	Tipperary County Council
RS25N020300	NEWPORT (TIPPERARY) - Portryan Br (1st Br d/s Newport)	IE_SH_25N020330	171653	161602	Tipperary County Council
RS25N020330	Br S of Shower	IE_SH_25N020330	170268	161832	Tipperary County Council
RS25N020400	NEWPORT (TIPPERARY) - Br nr Bunkey Br (K2)	IE_SH_25K020150	168615	160466	Limerick City & County Council
RS25N020500	NEWPORT (TIPPERARY) - Just u/s Annagh R confl	IE_SH_25K020150	168390	157941	Limerick City & County Council

**NEWTOWN****25N03**

Date Surveyed (last survey year only): 09/09/25

**Biological Quality Rating (Q Values)**

Station Code	1982	1985	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25N030100		5	5	5	4-5	4-5	4-5	4-5		4	4	4	4	
RS25N030200	4-5	5	5	5	3-4	4-5	4	4	4	4	4	4	4	4

**Most Recent Assessment:**

The Newtown River retained its Good condition at the site sampled (0200) in September 2025

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25N030100	NEWTOWN - Carrigmadden Br	IE_SH_25N030200	179776	177959	Tipperary County Council
RS25N030200	Newtown Br	IE_SH_25N030200	180430	180794	Tipperary County Council

**OLLATRIM****25001**

Date Surveyed (last survey year only): 10/09/25, 11/09/25, 19/08/25, 20/08/25

**Biological Quality Rating (Q Values)**

Station Code	1981	1984	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2019	2021	2025
RS25O010040			3-4	3-4	3	3	3*	3	3-4*	3-4	3	3		3*	3
RS25O010080			4-5	3-4	3-4	3-4	3-4	3-4		3-4*	4	3-4		3-4	3-4
RS25O010100	5	4	4	4											
RS25O010150			4-5		4	4	4	4	4-5	4-5	4-5	4	4	3-4	3-4
RS25O010200	5	3-4	3-4	4											
RS25O010250					4	4	4	4	4	4-5	4-5	4		3-4	3-4
RS25O010300	4	3-4	4	4-5											
RS25O010400	4	4	4	3-4	3-4	3-4	3-4		3-4	4	4-5	4		4	4
RS25O010450			4												
RS25O010500	5	3-4	4												
RS25O010600			4-5	3-4	3-4	3-4	3-4	3-4	3-4	3-4	4	3-4		3-4	3

**Most Recent Assessment:**

Five of the six sites surveyed on the Ollatrim river were in an unsatisfactory ecological condition when surveyed in 2025. There was no change compared with the last sampling in 2021 – apart from the lowermost site (0600) which declined to Poor ecological condition.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25O010040	Br SE of Ballybeg	IE_SH_25O010040	202299	176078	Tipperary County Council
RS25O010080	OLLATRIM - Aghnameadle Br	IE_SH_25O010080	201771	177450	Offaly County Council
RS25O010100	OLLATRIM - Ollatrim Br	IE_SH_25O010150	200065	179499	Tipperary County Council
RS25O010150	Bridge d/s Ollatrim Br	IE_SH_25O010150	198849	180965	Tipperary County Council
RS25O010200	OLLATRIM - Br SW of Millgrove Ho (W of Millgrove on Discovery)	IE_SH_25O010250	197702	181247	Tipperary County Council
RS25O010250	Bridge Nr Riverlawn House	IE_SH_25O010250	194208	181932	Tipperary County Council
RS25O010300	OLLATRIM - Ford at Castle Willington	IE_SH_25O010400	193588	181681	Tipperary County Council
RS25O010400	Rathurles bridge	IE_SH_25O010400	190619	179778	Tipperary County Council
RS25O010450	OLLATRIM - Br SW of Islandbaun Ho	IE_SH_25O010400	189696	179191	Tipperary County Council
RS25O010500	OLLATRIM - Gourdeen Br	IE_SH_25O010400	188730	179648	Tipperary County Council
RS25O010600	Br u/s Nenagh R Confl	IE_SH_25O010400	187623	180232	Tipperary County Council

**PALLAS****25P01**

Date Surveyed (last survey year only): 17/08/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25P010300	4-5	3-4	3	3	2-3	3-4		4				
RS25P010500	5	4	3-4	3	3	4	3-4	4	3-4	3-4	3-4	3-4

**Most Recent Assessment:**

The macroinvertebrate fauna indicated continued unsatisfactory ecological conditions on the Pallas Stream in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25P010300	PALLAS - Br SE of New Grove nr Holy Well	IE_SH_25P010500	196912	206397	Tipperary County Council
RS25P010500	Nr Church d/s Pallas Bridge	IE_SH_25P010500	199911	207170	Tipperary County Council

**POLLAGH STREAM (BROSNA)****25P05**

Date Surveyed (last survey year only): 09/08/23

**Biological Quality Rating (Q Values)**

Station Code	1989	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25P050200	5	4	4	3-4								
RS25P050300	4	3-4	4	3-4	4	4	3-4	4	4	4	3-4	3-4

**Most Recent Assessment:**

The macroinvertebrate fauna indicated continued unsatisfactory ecological conditions on the Pollagh Stream in 2023. Dissolved oxygen levels were very low on the day of survey (4.63mg/l) and macrophyte growth was a lot denser compared to previous years with 70% of the channel covered with Sparganium erectum.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25P050200	POLLAGH STREAM (BROSNA) - Br d/s Barony Br	IE_SH_25P050300	220682	222045	Offaly County Council
RS25P050300	Br u/s Brosna R confl	IE_SH_25P050300	219214	225008	Offaly County Council

**POPE'S****25P03**

Date Surveyed (last survey year only): 04/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	2021	2023
RS25P030200	2	2-3	3

**Most Recent Assessment:**

Poor ecological quality again recorded at Station 0200, just upstream of the Dead River confluence.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25P030200	Just u/s Dead R confl	IE_SH_25D010100	186037	143524	Limerick City & County Council

**RAPEMILLS****25R01**

Date Surveyed (last survey year only): 11/08/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1987	2008	2011	2014	2017	2021	2023
RS25R010100	4	4						
RS25R010200	4	4						
RS25R010300	4-5	4-5	3-4	4	4	3-4	3-4	3-4
RS25R010400	4	4-5						
RS25R010500	4-5	3-4						

**Most Recent Assessment:**

The macroinvertebrate fauna indicated moderate ecological quality on the Rapemills stream (0300). As in the 2021 survey, enhanced filamentous algal growth was again observed.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25R010100	RAPEMILLS - Br nr Eglis Castle	IE_SH_25R010300	210068	209618	Offaly County Council
RS25R010200	RAPEMILLS - Boolinarig Br	IE_SH_25R010300	207614	209296	Offaly County Council
RS25R010300	Br at Rapemills	IE_SH_25R010300	204817	210193	Offaly County Council
RS25R010400	RAPEMILLS - Br SW of Taylors X Rds	IE_SH_25R010500	202696	211284	Offaly County Council
RS25R010500	RAPEMILLS - Lusmagh Br	IE_SH_25R010500	200175	214603	Offaly County Council

**ROCK (BIRR)****25R02**

Date Surveyed (last survey year only): 02/08/23, 14/08/23

**Biological Quality Rating (Q Values)**

Station Code	1984	1987	1993	1996	1999	2002	2005	2011	2014	2017	2021	2023
RS25R020050	3-4	4-5	4	4-5	3-4	3-4	4	4	3-4	3	3	3*
RS25R020100	3	4	3-4									
RS25R020200	3	3-4								3-4	3-4	3-4
RS25R020300	3	4	4	2	3	3	3-4	4				

**Most Recent Assessment:**

The lack of pollution sensitive macroinvertebrate species continues to indicate unsatisfactory conditions at both stations. The lower station (0200) was indicative of moderate ecological quality while the upper station (0050) was indicative of poor ecological quality. Here the substrate was heavily silted with little coarse substrate and an \* was assigned.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25R020050	ROCK (BIRR) - Br WNW of Killeenbreaghan Ho	IE_SH_25R020050	208383	200000	Offaly County Council
RS25R020100	ROCK (BIRR) - Whiteford Br	IE_SH_25R020200	207258	203448	Offaly County Council
RS25R020200	ROCK (BIRR) - Br u/s Aughnagann Ford	IE_SH_25R020200	205979	203529	Offaly County Council
RS25R020300	ROCK (BIRR) - Aughnagann Ford	IE_SH_25L020700	205444	202719	Offaly County Council

**Roscomore Stream****25R05**

Date Surveyed (last survey year only): 12/07/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2018	2019	2020	2021	2023
RS25R050100	5	5	5	4-5	5	5	4	5	5	5	5	4-5	4-5	4-5	4-5
RS25R050990															4-5

**Most Recent Assessment:**

High ecological quality continues at the Roscomore Stream in July 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25R050100	Aghagurty Br	IE_SH_25R050100	217045	200884	Offaly County Council
RS25R050990	Just (~20m) u/s Breaghmore confluence	IE_SH_25B120400	214813	202252	Offaly County Council

**ROSTOLLUS STREAM****25R03**

Date Surveyed (last survey year only): 31/12/93

**Biological Quality Rating (Q Values)**

Station Code	1993
RS25R030400	3

**Most Recent Assessment:**

This Woodford River tributary was moderately polluted in October i 1993.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25R030400	ROSTOLLUS STREAM - 1st Br. u/s Woodford River confl.	IE_SH_25W010300	176386	197199	Galway County Council

**SCARRIFF STREAM****25S08**

Date Surveyed (last survey year only): 16/08/23

**Biological Quality Rating (Q Values)**

Station Code	1994	1996	1999	2003	2005	2009	2012	2014	2017	2021	2023
RS25S080400	4	3-4	4	3	3	3-4	3-4	3-4	3	3	3

**Most Recent Assessment:**

Unsatisfactory conditions persist in the Scarriff Stream in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S080400	West Br Scarriff	IE_SH_25S080400	164061	184581	Clare County Council

**SHANNON (LOWER)****25S01**

Date Surveyed (last survey year only): 01/09/25

**Biological Quality Rating (Q Values)**

Station Code	1972	1976	1984	1987	1990	1993	1996	1999	2002	2008	2011	2012	2014	2015	2017	2018	2021	2023	2025
RS25S011960			4-5																
RS25S012010			4-5																
RS25S012030		4-5	4																
RS25S012050			4																
RS25S012060										3-4	4		4		3-4		3-4	3-4	
RS25S012110			4																
RS25S012300			4																
RS25S012500	4-5		4	4	4	3-4	3-4	3-4	4	3-4		3-4		3-4		3-4	3		3-4
RS25S012600			4	4	4	3-4	3-4	3-4	3-4										

**Most Recent Assessment:**

The macroinvertebrate community indicated only a slight improvement to moderate ecological condition at Castleconnell: World's End (2500) in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S011960	SHANNON (LOWER) - D/s Blackwater R confl	IE_SH_25S012000	200016	221633	Galway County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S012010	SHANNON (LOWER) - 0.8km d/s Banagher Br(LHS)	IE_SH_25S012060	199853	215797	Offaly County Council
RS25S012030	SHANNON (LOWER) - 2.5km d/s Banagher Br (RHS)	IE_SH_25S012060	198254	216377	Galway County Council
RS25S012050	SHANNON (LOWER) - 4km d/s Banagher Br	IE_SH_25S012060	197010	215895	Galway County Council
RS25S012060	Incherky Quay (d/s Banagher)	IE_SH_25S012060	195270	214307	Galway County Council
RS25S012110	SHANNON (LOWER) - Meelick- d/s L Brosna R confl	IE_SH_25S012350	193367	212289	Galway County Council
RS25S012300	SHANNON (LOWER) - Killaloe Br (RHS)	IE_SH_25S012350	187343	204881	Galway County Council
RS25S012500	Castleconnell: World's End	IE_SH_25S012500	165869	163500	Clare County Council
RS25S012600	Athlunkard Br (d/s LHS)	IE_SH_25S012600	158792	159050	Clare County Council

## Sheever Lough Stream

25S99

Date Surveyed (last survey year only): 05/09/24

### Biological Quality Rating (Q Values)

Station Code	1984	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2024
RS25S990720	3-4	3	3	3	3	3	3-4	3	3	3	3	3	3

#### Most Recent Assessment:

The macroinvertebrate community continues to indicate poor ecological conditions at Sheever Lough Stream (formally coded as part of the Brosna 25B09) at the Bridge downstream of Lough Sheever (0720) in 2024. The invasive Zebra mussel continues to persist at this location.

### Station Details

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S990720	Br. d/s Lough Sheever	IE_SH_25B090006	245579	254933	Westmeath County Council

**SHINRONE STREAM****25S11**

Date Surveyed (last survey year only): 31/07/23

**Biological Quality Rating (Q Values)**

Station Code	2008	2009	2011	2014	2017	2021	2023
RS25S110100	2*	2-3*	2-3	3	3	3	3*

**Most Recent Assessment:**

Poor ecological quality continues in the Shinrone Stream with an unbalanced macroinvertebrate fauna and lack of pollution sensitive taxa. Low dissolved oxygen was observed on the day of survey (5.91mg/l) along with dense macrophyte growth. An \* was assigned due to very heavy siltation of the substrate.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S110100	Fortified House Bridge on R491	IE_SH_25S110100	204743	192419	Offaly County Council

**SILVER (KILCORMAC)**

**25S02**

Date Surveyed (last survey year only): 11/07/23, 11/08/23, 18/08/23

**Biological Quality Rating (Q Values)**

Station Code	1971	1974	1981	1984	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25S020100			5	5	5	4	4	4-5	4-5	4-5	4	4-5	4-5	4-5	4-5	4-5
RS25S020200			5	5	4-5	3-4	4-5	4	4	4-5	3-4	4	3-4	3-4	4	4
RS25S020300		5	5	5	4-5											
RS25S020320						3-4	3-4	3	3	3-4		3-4	3-4	3-4	3-4	3-4
RS25S020400	4	4-5	4	3-4	3-4	3-4	3-4	4		3-4	3-4	4	3-4	3-4	3-4	3-4
RS25S020500			4	3-4	4	4	4	4	4-5	4	3-4	4	4	4	4	3-4
RS25S020600	4	4	4	5	4											
RS25S020700	4-5	4	4	4-5	4	4	4	4	4	4	4	4	4	4	3-4	3-4

**Most Recent Assessment:**

Of the six stations monitored on the Silver (Kilcormac) in 2023, only the upper two stations were in satisfactory condition (0100 & 0200) with High and Good ecological quality assigned respectively. Moderate ecological quality was assigned to the remaining stations. At Lumcloon Bridge (0700) the excessive instream macrophytes observed in 2021 was again apparent in 2023 but no filamentous green algae was noted here this year.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S020100	Br at Cadamstown	IE_SH_25S020100	222754	208482	Offaly County Council
RS25S020200	Ballynacarrig Br	IE_SH_25S020200	222558	213619	Offaly County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S020300	SILVER (KILCORMAC) - Br at Ballyboy	IE_SH_25S020400	220401	213997	Offaly County Council
RS25S020320	East Br Kilcormac	IE_SH_25S020400	218609	214064	Offaly County Council
RS25S020400	Br 1km d/s Kilcormac	IE_SH_25S020400	217743	214671	Offaly County Council
RS25S020500	Wooden Br N of Aghagoogy	IE_SH_25S020500	212727	214347	Offaly County Council
RS25S020600	SILVER (KILCORMAC) - Millbrook Br	IE_SH_25S020700	213540	218777	Offaly County Council
RS25S020700	Lumcloon Br	IE_SH_25S020700	213917	219771	Offaly County Council

**SILVER (TULLAMORE)**

**25S03**

Date Surveyed (last survey year only): 08/08/25

**Biological Quality Rating (Q Values)**

Station Code	1984	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023	2025
RS25S030050		4												
RS25S030055		4	4	4	3-4									
RS25S030100	4-5	3-4	4	3	3	3*	3-4	3-4	4	4	4	4	4	4
RS25S030200			3-4											
RS25S030300	4-5	4	4	4	4	3*	3-4	3-4	4	4	4	4	3-4	3
RS25S030400	4	4												
RS25S030500			3-4	3	3-4	3-4	3-4	3-4	3-4	4	3-4	3-4	3-4	4

**Most Recent Assessment:**

The Silver (Tullamore) was sampled at three sites. No change in condition was noted at the upstream station (0100) which remained in Good ecological condition. The middle site (0300) was in Poor condition while the lowermost site (0500) improved to Good condition compared with 2023 when it was Moderate.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S030050	SILVER (TULLAMORE) - Derrygolan Br (LH Chan)	IE_SH_25S030100	236288	229814	Offaly County Council
RS25S030055	SILVER (TULLAMORE) - Derrygolan Br (RH Chan)	IE_SH_25S030100	236276	229784	Offaly County Council
RS25S030100	Gormagh Br	IE_SH_25S030100	233826	228490	Offaly County Council

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S030200	SILVER (TULLAMORE) - Ballyduff Br	IE_SH_25S030300	231601	227846	Offaly County Council
RS25S030300	Br N of Aharney	IE_SH_25S030300	228938	228601	Offaly County Council
RS25S030400	SILVER (TULLAMORE) - Br E of Derries	IE_SH_25S030500	226686	228700	Offaly County Council
RS25S030500	New Br u/s Clodiagh R confl	IE_SH_25S030500	225119	227355	Offaly County Council

**SMALL (TIPPERARY)****25S05**

Date Surveyed (last survey year only): 14/08/25

**Biological Quality Rating (Q Values)**

Station Code	1979	1983	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25S050100	5	5	5											
RS25S050200	5	5	5	4	4-5	4-5	3-4*	4-5	4	4	4	4	3-4	3-4

**Most Recent Assessment:**

The macroinvertebrate fauna continues to indicate moderate ecological conditions on the Small (Tipperary) in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S050100	SMALL (TIPPERARY) - Br 1.9km u/s Newport	IE_SH_25S050200	174329	162433	Tipperary County Council
RS25S050200	U/s Newport River Confl	IE_SH_25S050200	174264	162542	Tipperary County Council

**SYONAN CASTLE STREAM****25S04**

Date Surveyed (last survey year only): 13/06/23

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2011	2014	2017	2021	2023
RS25S040300		4	4-5	3-4	3	4	3-4*	3-4	4	3-4	3-4	3-4
RS25S040400	4											
RS25S040500	4	4	4	3-4	3-4	4	3-4	3-4	3-4	3-4	3-4	

**Most Recent Assessment:**

The paucity of pollution sensitive macroinvertebrate fauna continues to indicate unsatisfactory moderate ecological conditions on the Syonan castle Stream in June 2023. The lower station was not surveyed due to health and safety concerns.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25S040300	Br N of Lisnagree (W of Streamstown Ho)	IE_SH_25S040500	226770	242680	Westmeath County Council
RS25S040400	SYONAN CASTLE STREAM - Br nr Syonan Castle	IE_SH_25S040500	228066	240133	Westmeath County Council
RS25S040500	Br u/s Gageborough R confl	IE_SH_25S040500	227946	238873	Westmeath County Council

**TOEM STREAM****25T05**

Date Surveyed (last survey year only): 12/08/25

**Biological Quality Rating (Q Values)**

Station Code	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25T050300	4	3-4	4	4	4	4		4*				
RS25T050600	4-5	4	4	4	4	4	4*	4	3	3	3*	3

**Most Recent Assessment:**

The Toem Stream remained in poor ecological condition with a low number of macroinvertebrate taxa (10). Excessive instream siltation of the river bed was observed.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25T050300	TOEM STREAM - South Br at Toem	IE_SH_25T050600	186710	147474	Tipperary County Council
RS25T050600	Br u/s Dead R confl	IE_SH_25T050600	184127	145649	Limerick City & County Council

**TULLAMORE****25T03**

Date Surveyed (last survey year only): 08/08/23, 09/08/23

**Biological Quality Rating (Q Values)**

Station Code	1971	1975	1977	1979	1981	1986	1987	1989	1990	1993	1996	1999	2002	2005	2007	2008	2011	2014	2017	2019	2021	2023
RS25T030030										3	3	3	3	3*		3-4	3-4	3-4	3-4		3-4	3
RS25T030100	4	3-4	3-4		4	4	3			4-5	3	3	3	3-4		3	3-4	3-4	3	3	3	3
RS25T030400	1-2	2	1-2	2-3	2	2	2	2-3	2-3	2-3	2-3	2	2	2	2-3	2-3	2-3	3	3-4	4	3-4	3-4

**Most Recent Assessment:**

The Tullamore river remains in unsatisfactory condition at all stations surveyed. The uppermost station (0030) declined from Moderate to Poor ecological quality with no sensitive taxa present. Poor ecological quality continued at the next station (0100) while the lowermost station (0400) continued to be of moderate ecological quality. Dissolved oxygen levels were quite low at stations 0100 and 0400 (6.52mg/l & 5.14mg/l respectively).

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25T030030	Br d/s Geashill Stream	IE_SH_25T030030	244456	222336	Offaly County Council
RS25T030100	Br S of Cappincur	IE_SH_25T030100	238782	224046	Offaly County Council
RS25T030400	Bridge SW of Ballycowen bridge	IE_SH_25T030400	229513	225049	Offaly County Council

**WOODFORD (GALWAY)**

**25W01**

Date Surveyed (last survey year only): 08/07/23, 09/07/23

**Biological Quality Rating (Q Values)**

Station Code	1975	1979	1984	1987	1993	1996	1999	2003	2006	2009	2012	2014	2017	2021	2023
RS25W010040							3*	4	4	3-4	3*	3-4	3-4	3-4	3-4
RS25W010050			4	4-5	4	5									
RS25W010060					4		3-4*								
RS25W010100		5	4-5	4	4										
RS25W010200		5	4	4-5	4	3-4	4	4	4	4	3-4	3-4	3-4	4	3-4
RS25W010300	4-5	5	4-5	5	4-5	3-4	4	4-5	4-5	4-5	4	4	4	3-4	3-4

**Most Recent Assessment:**

With a decline to Moderate ecological quality at Bolag Bridge (Station 0200), and no improvements at the other two sites, all 3 sites on the Woodford River are in unsatisfactory condition in 2023.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25W010040	Br NW of Featherstone Lodg	IE_SH_25W010040	168981	199162	Galway County Council
RS25W010050	WOODFORD (GALWAY) - Br N of Featherstone Lodge	IE_SH_25W010200	169281	199265	Galway County Council
RS25W010060	WOODFORD (GALWAY) - Br N of Lough Alee	IE_SH_25W010200	170756	199967	Galway County Council

---

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25W010100	WOODFORD (GALWAY) - Woodford Br	IE_SH_25W010200	173217	200022	Galway County Council
RS25W010200	Br d/s Woodford Br - Bolag Br	IE_SH_25W010200	174135	199787	Galway County Council
RS25W010300	Rossmore Br	IE_SH_25W010300	177203	198426	Galway County Council

**YELLOW (KILMASTULLA)****25Y01**

Date Surveyed (last survey year only): 11/08/25

**Biological Quality Rating (Q Values)**

Station Code	1974	1976	1978	1981	1983	1985	1987	2002	2005	2008	2012	2015	2018	2021	2025
RS25Y010200	3/0	2/0	1/0	1/0	3	3-4	3/0	3/0	4-5		4	3-4	3	3	3
RS25Y010300	1/0	1/0	1/0	1/0	3	3/0	3/0	3/0	4	3-4	3-4	3-4	3/0	3	3

**Most Recent Assessment:**

Both sites on the Yellow (Kilmastulla) were in poor ecological condition in 2025.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25Y010200	u/s Yellow Br & u/s Garryard Stream	IE_SH_25K040800	180808	171776	Tipperary County Council
RS25Y010300	d/s Yellow Br & d/s Garryard Stream	IE_SH_25K040800	180759	171783	Tipperary County Council

**YOUGHAL (TIPPERARY)**

**25Y02**

Date Surveyed (last survey year only): 09/09/25

**Biological Quality Rating (Q Values)**

Station Code	1982	1985	1987	1993	1996	1999	2002	2005	2008	2012	2015	2018	2021	2025
RS25Y020050		4-5	3	4	3	3-4	3-4*	3-4		3-4	3-4	3-4		
RS25Y020060													3-4	4
RS25Y020100		5	4-5											
RS25Y020200	5	5	5	4	4	4-5	4-5	4	4	4-5	4	4	4	4

**Most Recent Assessment:**

The Youghal (Tipperary) showed an improvement at the upper site (0060) while the second site retained its good condition. The 2021 survey result for station 0050 was recoded to station 0060 as per its sampled location.

**Station Details**

Station Code	Station Location	WFD Waterbody Code	Easting	Northing	Local Authority
RS25Y020050	YOUGHAL (TIPPERARY) - Br N of Curragh	IE_SH_25Y020200	176258	180111	Tipperary County Council
RS25Y020060	YOUGHAL (TIPPERARY) - 1st Br d/s St 0050	IE_SH_25Y020200	176383	180195	Tipperary County Council
RS25Y020100	YOUGHAL (TIPPERARY) - Ballycarridoge Br	IE_SH_25Y020200	178312	181487	Tipperary County Council
RS25Y020200	Br. At Youghal	IE_SH_25Y020200	179083	182006	Tipperary County Council